
Photograph Log for EPA's December 9, 2010 Owens-Brockway Glass Container RCRA Inspection

All photographs on this log were taken with a digital camera by Amy C. Miller, RCRA Enforcement Office, EPA Region IX. Please note that each photograph number begins with "PC0901" and that the photograph log stats with photograph number 01.

- 27. Error
- 28. Error
- 29. Outdoor Area: 500-gallon diesel tank
- 30. Outdoor Area: Hazardous waste label on the 3,950-gallon used oil tank. Note: Label is faded.
- 31. Outdoor Area: Overview of the 3,950-gallon used oil tank.
- 32. Outdoor Area: 3,950-gallon used oil tank marked as "used oil".
- 33. Outdoor Area: Hazardous waste label on roll-off bin of furnace/checker dust.

 Note: the label does not have an accumulation start date.
- 34. Outdoor Area: Overview of the roll-off bin of furnace/checker durst.
- 35. Outdoor Area: Hazardous waste label on roll-off bin of furnace/check dust is modified to have an accumulation start date.
- 36. Outdoor Area: Bin for EP dust re-used on-site.
- 37. Stairwell: Trash can with lint waste.
- 38. Stairwell: Trash can with lint waste.
- 39. Stairwell: Overview of the two trash cans
- 40. Basement Level: 2,025-gallon used oil tank. Photograph is blurred.
- 41. Basement Level: 2,025-gallon used oil tank with hazardous waste label and marked as "used oil".
- 42. Basement Level: Close up of hazardous waste label on 2,025-gallon used oil tank. Note: no accumulation start date.
- 43. Basement Level: 2,025-gallon used oil tank is open on top.


- 63. Selecting Maintenance Area: Hazardous waste label on one of the three containers in the photograph 60.
- 64. Selecting Maintenance Area: Inside the flammable cabinet are a 55-gallon drum of methyl ethyl ketone and several unlabeled containers of Methyl ethyl ketone.
- 65. Selecting Maintenance Area: Label of the 55-gallon drum of methyl ethyl ketone in previous photograph.
- 66. Selecting Maintenance Area: Inside the flammable cabinet are a 55-gallon drum of methyl ethyl ketone rags and rags stored on top of the container
- 67. Selecting Maintenance Area: Label of the 55-gallon drum of methyl ethyl ketone rags in previous photograph. Note: the accumulation start date states "12/5/2005".
- 68. Universal waste and CRT Storage Area: Overview of the area.
- 69. Universal waste and CRT Storage Area: Close-up of lamps stored without a container.
- 70. Universal waste and CRT Storage Area: Close-up of lamps stored without a container.
- 71. 90 Day Storage Area: Open used oil 55-gallon drum.
- 72. 90 Day Storage Area: Close-up of label in previous photograph. Note: there is no accumulation start date.
- 73. 90 Day Storage Area: All empty containers except for the blue bin in the back area.
- 74. 90 Day Storage Area: Hazardous waste label on one of the empty containers.
- 75. 90 Day Storage Area: Hazardous waste label on one of the empty containers.
- 76. 90 Day Storage Area: All empty containers beyond the blue bin in the foreground.







HAZARDOUS WASTE
















































PC090171.JPG


PC090172.JPG





PC090175.JPG

PC090176.JPG



Certified Mail Provides:

- A mailing receipt
- A unique identifier for your mailpiece
- A record of delivery kept by the Postal Service for two years

Important Reminders:

- Certified Mail may ONLY be combined with First-Class Mail® or Priority Mail®
- Certified Mail is not available for any class of international mail.
- NO INSURANCE COVERAGE IS PROVIDED with Certified Mail. For valuables, please consider Insured or Registered Mail.
- For an additional fee, a Return Receipt may be requested to provide proof of delivery. To obtain Return Receipt service, please complete and attach a Return Receipt (PS Form 3811) to the article and add applicable postage to cover the fee. Endorse mailpiece "Return Receipt Requested". To receive a fee waiver for a duplicate return receipt, a USPS_® postmark on your Certified Mail receipt is recuired.
- For an additional fee, delivery may be restricted to the addressee or addressee's authorized agent. Advise the clerk or mark the mailpiece with the endorsement "Restricted Delivery".
- If a postmark on the Certified Mail receipt is desired, please present the article at the post office for postmarking. If a postmark on the Certified Mail receipt is not needed, detach and affix label with postage and mail.

IMPORTANT: Save this receipt and present it when making an inquiry.

PS Form 3800, August 2006 (Reverse) PSN 7530-02-000-9047

SENDER: COMPLETE THIS SECTION	NC	COMPLETE THIS SECTION ON DELIVER	Y
 Complete items 1, 2, and 3. Also contem 4 if Restricted Delivery is desired. Print your name and address on the so that we can return the card to your address. Attach this card to the back of the or on the front if space permits. 	red. e reverse ou.	1200 ate 1	Agent Addresse
1. Article Addressed to: William Boscacci Environmental, Health &			☐ Yes / /
Owens-Broadway Galss Co 3600 Alameda Avenue	ntainer	inc.	
Oakland, CA 94601-3329		<u> </u>	
		3. Service Type Certified Mail Registered Insured Mail C.O.D.	or Merchandis
		4. Restricted Delivery? (Extra Fee)	☐ Yes
Article Number (Transfer from service label)	7007		

	UNITE	STATES	Postal	SERVICE
--	-------	--------	--------	---------



First-Class Mail Postage & Fees Paid USPS Permit No. G-10

• Sender: Please print your name, address, and ZIP+4 in this box •

Clint Seiter (WST-3) US EPA 75 Hawthorne Street San Francisco, CA 94105-3901

MahadadadMaaddaddaddaddaddaddaddadda

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX 75 Hawthorne Street

San Francisco, CA 94105-3901 JAN 2 0 2011

CERTIFIED MAIL NO. 7007-0710-0003-6240-4142 RETURN RECEIPT REQUESTED

WARNING LETTER

William Boscacci Environmental, Health & Safety Director Owens-Brockway Glass Container Inc. 3600 Alameda Ave. Oakland, CA 94601

EPA Identification Number: CAT000618918

Dear Mr. Boscacci:

On December 9, 2010, a hazardous waste compliance inspection was conducted by representatives of the United States Environmental Protection Agency ("EPA"), accompanied by a representative from the Oakland Fire Department at Owens-Brockway Glass Container Inc., located in Oakland, CA with EPA Identification Number CAT000618918. During the course of this investigation, information was gathered in accordance with Section 3007(a) of the Resource Conservation and Recovery Act ("RCRA"), as amended {42 U.S.C. §6927(a)}.

A copy of the inspection report is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with RCRA regulations and potential violations of the State of California authorized program under RCRA Subtitle C and potential non-RCRA state violations. Any omissions in the report shall not be construed as a determination of compliance with any other applicable regulation.

Pursuant to Section 3008 of RCRA {42 U.S.C. §6928}, you are required to correct the identified areas of noncompliance and to submit documentation of their correction to the EPA:

- Ensure that all hazardous waste containers identified in the accompanying report as improperly labeled, be labeled with the following information:
 - the words "Hazardous Waste";
 - the initial date of waste accumulation;
 - composition and physical state of the waste:

- the particular hazardous properties of the waste; and
- the name and address of the person producing the waste.

Ensure that all hazardous waste tanks identified in the accompanying report as improperly labeled, be labeled with the following information:

- the words "Hazardous Waste";
- the initial date of waste accumulation.

In addition, ensure that all tanks and containers of used oil are identified with the words "USED OIL".

Provide EPA with photos that this has been done. If the containers in question have already been transported offsite for disposal, provide EPA with a copy of the manifest;

- Ensure that all spent fluorescent lamps are secured in closed containers labeled with the words "Universal Waste-Lamps". In addition, ensure that the facility can document the length of storage time for all spent lamps;
- Ensure that all containers and tanks of hazardous waste identified in the attached report as open are closed.

Provide EPA with photos that this has been done. If the containers in question have already been transported offsite for disposal, provide EPA with a copy of the manifest;

- Perform a hazardous waste determination on oil/grease contaminated rags and personal protective equipment (PPE). Provide EPA with the results of this determination. If it is determined that these wastes are hazardous, establish a Standard Operating Procedure (SOP) for all facility personnel to discard future such wastes correctly;
- Provide documentation for all facility personnel charged with managing hazardous wastes per the requirements of the California Code of Regulations (CCR) Title 22 §66265.16(d)(1)-(4), specifically:
 - (1) the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
 - (2) a written job description for each position listed;
 - (3) a written description of the type and amount of both introductory and continuing training that will be given to each person listed above;
 - (4) records that document that the training or job experience required have been completed.
- Ensure that the facility's outdoor used oil tank has a leak detection system. Provide EPA with documentation that this has been done.

- Obtain certification from a certified, outside engineer regarding the structural integrity of the facility's three used oil tanks. Provide EPA with copies of this certification;
- Establish a system of daily inspection for all of the facility's used oil tanks, including the use of a daily inspection check sheet;
- Provide access to the 55-gallon drum of spent lubricant in the Selecting Maintenance Satellite Accumulation Area #1.
- Provide EPA with photographic documentation that this has been done. If the containers in question have already been transported offsite for disposal, provide EPA with a copy of the manifest.

Documentation of your return to compliance may consist of, among other things, photographs, manifests, and revised records. Where compliance cannot be achieved within 30 calendar days, you must provide to the EPA the reasons for the delay, a description of each corrective action planned, and a schedule on which each corrective action will be taken.

By copy of this letter, the EPA is providing the State of California with notice that the EPA may take appropriate enforcement action if the facility does not resolve the violations within the time specified above, and the State of California does not take appropriate enforcement action. The State of California may notify the EPA of its intent to assume or decline responsibility to take such action to resolve the referenced RCRA Subtitle C violations.

The EPA reserves the right to take further enforcement action as it deems appropriate. However, your response to this letter will be considered in determining the need for further enforcement action. RCRA Subtitle C violations such as those listed in the Enclosure may be punishable by civil and criminal actions, including penalties of up to \$37,500 per day for each violation, as provided by Section 3008 of RCRA.

The EPA routinely provides copies of inspection reports to state or tribal agencies, and upon request, to the public. Such releases are handled according to the Freedom of Information Act regulations, 40 C.F.R. Part 2, Subpart B. For any portion of the information included in this inspection report which is entitled to confidential treatment, please assert a confidentiality claim in accordance with 40 C.F.R. §2.203(b). If the EPA determines that the information so designated meets the criteria set forth in 40 C.F.R. §2.208, the information will be disclosed only to the extent, and by means of the procedures specified in 40 C.F.R. Part 2, Subpart B. As described in 40 C.F.R §2.203(a)(2), the EPA will construe the failure to furnish a confidentiality claim within 14 calendar days from the date of your receipt of this letter as a waiver of that claim, and information may be made available to the public by the EPA without further notice.

Your certification of correction of the areas of noncompliance identified in this warning letter must be included in a response letter signed by a duly authorized official of your facility. Your response, due 30 calendar days from the date of your receipt of this letter, shall be addressed to:

Clint Seiter

Mailcode: WST-3

RCRA Enforcement Office

U.S. Environmental Protection Agency

75 Hawthorne Street

San Francisco, CA 94105

If you have questions related to the inspection report or this letter, please contact Clint Seiter of my staff at (415) 972-3298 or seiter.clint@epa.gov.

Sincerely,

Amy C. Miller, Manager RCRA Enforcement Office

Enclosure

cc (w/o enclosure): Charles McLaughlin, DTSC

Leroy Griffin, Oakland Fire Department

				F 1 - 6 3
				,



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, CA 94105

WASTE MANAGEMENT DIVISION

RCRA ENFORCEMENT OFFICE

Purpose:

RCRA Compliance Evaluation Inspection

Facility:

Owens-Brockway Glass Container Inc.

3600 Alameda Ave. Oakland, CA 94601

EPA ID Number:

CAT000618918

Date of Inspection:

December 9, 2010

EPA Representatives:

Clint Seiter

(415) 972-3298

seiter.clint@epa.gov

Amy Miller

(415) 947-4198

miller.amy@epa.gov

Oakland Fire Department

CUPA representative:

Leroy Griffin

(510) 238-7759

lgriffin@oaklandnet.com

Facility Representative:

William Boscacci

Environmental, Health & Safety Director

(510) 436-2166

Report Prepared By:

Clint Seiter

Report Date:

January 11, 2011

the state of the s		

BACKGROUND

Facility Description

Owens-Brockway Glass Containers ("Owens-Brockway" or "the facility"), a unit of Owens-Illinois, is a glass manufacturing facility located at 3600 Alameda Avenue, Oakland, CA 94601. It has been in operation since 1937 and currently has a work force of 180 employees. The facility has three furnaces, but at the present only one is in operation (approximately 700,000 bottles are manufactured daily). Most of the bottles manufactured come from recycled glass (cullet), which is ground down and remelted, with the remainder glass made on site from silica sand mixed with salt cake, soda ash, limestone, and colorizers or de-colorizers.

A review of the California Department of Toxic Substance Control's (DTSC) Hazardous Waste Tracking System database indicates that Owens-Brockway is a large quantity generator of lead D008 (lead) and D010 (selenium) RCRA hazardous waste.

Owens-Brockway was last inspected by the City of Oakland Fire Department on October 19, 2004. Generator related violations were noted during that inspection, and the facility was documented as having returned to compliance on February 24, 2005.

Per the facility's 2009 Biennial Report, Owens-Brockway generates the following hazardous waste streams:

Hazardous Waste Name	Hazardous Waste Code
Electrostatic precipitator dust	D006/D007/D008/D010/ CA135
Electrostatic precipitator rinsate	D007/D008/CA135
Ignitable spent solvent and ink, methyl ethyl ketone	D001/D035/F005/ CA214
(MEK)	

MANUFACTURING PROCESS

The glass is manufactured from a combination of raw materials (sand, limestone, soda ash, sodium carbonate and sodium sulfate) and cullet (reusing cullet is desirable because this reduces the melting point of the batch, resulting in lower energy consumption). Both the cullet (segregated by color) and the raw materials are stored in individual silos above a weighing container. Different glass products require different combinations of ingredients and the required proportions of each batch are adjusted accordingly. The batches are transported via closed conveyor belts to the facility furnaces, where the batch material is melted down to molten glass (the conveyor belts are vacuumed daily and the vacuumed dust is re-entered into the manufacturing process). The molten glass is drawn from the bottom of the furnace, via the throat to feeders. Dust contaminated with chromium and lead (from crushed cullet) accumulates on the

bottom of the exhaust chambers that flank the furnaces (approximately once every three years this dust is vacuumed out and shipped off to be disposed of as D007 and D008 hazardous waste). Orifices in the feeders control the amount of molten glass let through, and shears cut off the bottoms of the gobs (discreet units of molten glass) to the desired length. The gobs are funneled to forming machines (the facility currently has three active forming machines, with two other machines being idle), and formed into blanks, called "parisons". The parisons are then transferred into molds (two at a time) in machines called shops. The hot glass is quenched by water as it is ejected out of the shop. This water picks up lubricating oil from the shop machinery, and before the water is recycled, it is directed to a skim pond. Used oil is skimmed off the pond and diverted to an above-ground tank. The molds in each shop can be configured to whatever specifications are required for the particular bottle, and the molds are periodically cleaned via bead blasting. Bottles are formed when compressed air is blown into the molds containing the gobs. The bottles then go through an annealing process where they are reheated in lehrs (specialized, temperature-controlled kilns) to temperatures up to 1030 degrees and then gradually cooled down. After the bottles are sufficiently cooled, they are sprayed with a polycoat mixture that increases the bottles' lubricity (scratch resistance). Each bottle is then imprinted with an ink code from an ink jet. The ink jets are periodically cleaned with methyl ethyl ketone (MEK) solvent, and the spent solvent eventually is discarded as a RCRA hazardous waste. The bottles are then checked by means of optical equipment for various potential defects (irregular wall thickness, blisters, cracks, specks, etc.) and defective bottles are removed from the assembly line (to be recycled as cullet). The bottles that pass inspections are eventually packaged and transported off to the customers.

INVESTIGATION

The purpose of the investigation was to determine Owens-Brockway's compliance with applicable federal environmental statutes and regulations, and, in particular, RCRA, as amended, the regulations provided in the Code of Federal Regulations (CFR), Chapter 40, Parts 261-265, 268, 273 and 279, and the California Code of Regulations (CCR), Title 22, Division 4.5 and the California Health and Safety Code, Division 20. On December 9, 2010, Clint Seiter and Amy Miller, representing the U.S. EPA, accompanied by a representative from the City of Oakland Fire Department, conducted an unannounced site investigation at the Owens-Brockway facility in Oakland, CA (EPA # CAT000618918). Upon providing introductions and credentials, the inspectors contacted Mr. William Boscacci, the environmental, health and safety director. The inspectors explained that this was a routine inspection to determine whether or not the facility was in compliance with federal and state regulations concerning the proper management of RCRA and non-RCRA hazardous wastes. The inspection would consist of a walkthrough of the facility, focusing on those areas where hazardous wastes were handled or stored, with photos taken, followed by a record review and a post-inspection outbriefing. In the course of the prewalkthrough briefing, the inspectors provided Mr. Boscacci with a copy of the EPA Small **Business Resources Information Sheet.**

WALK-THROUGH INSPECTION

Outside used oil tank

The inspectors noted a 3950-gallon used oil tank located outside of the facility's main building (used oil is a non-RCRA, California only hazardous waste). Although the tank had a hazardous waste label, the label had faded to the point that it was essentially unreadable (Photo 1). The tank was clearly marked with the words "Used Oil", per regulatory requirements (Photo 2).



Photo 1: used oil tank's unreadable label



Photo 2: "USED OIL" label on used oil tank

The tank had adequate secondary containment but lacked a leak detection system. The facility representative informed the inspectors that the tank was inspected daily per the regulatory tank

requirements, but that no daily inspection log was kept for the tank. In addition, he was not able to produce an engineer's certification of the tank's structural integrity.

Furnace checker dust bin

The inspectors noted a 15-cubic-yard furnace checker dust bin near the used oil tank (Photo 3). The bin was closed, in good condition and labeled, but the hazardous waste label's accumulation start date (ASD) was so faded that it was nearly illegible (Photo 4) (this was corrected during the inspection).



FROM CONTAINS HE C

Photo 3: furnace checker dust bin

Photo 4: bin's label with unreadable ASD

EP Building

Dust from the furnace exhaust is collected on electrostatic plates (EP) in the exhaust ducts. The collected dust is recycled into the glass manufacturing process as a substitute for sodium sulfate. The inspectors noted a bin of the dust awaiting recycling (Photo 5). No violations were noted.



Photo 5: bin of EP dust awaiting recycling

Batch House: C Furnace Area

The raw materials and cullet are combined here per the specified proportions for a given batch of glass. The inspectors noted the following:

Two open, unlabeled trash containers in the stairwell. Inside each container were what appeared to be oily rags (Photos 6 and 7), which, if sufficiently saturated could be considered a non-RCRA, California only hazardous waste. The inspector requested that the facility representative have a hazardous waste determination made for this waste stream to ensure that non-RCRA hazardous wastes were not being improperly discarded.



Photo 6: trash containers with discarded rags



Photo 7: close up shot of discarded rags

- Basement Area: glass constituents in the given specified proportions are gravity fed from the silos onto a conveyor belt here. Oily water from the quench water bins is processed through an oil/water separator, and the generated used oil is pumped to two interior

2025-gallon above-ground used oil tanks. The two tanks are located on a concrete floor which appeared to be in good condition (i.e., showed no signs of cracks). The tanks are elevated approximately three inches above the concrete floor on one end and had adequate containment. Both tanks were properly marked with the words "USED OIL" and had hazardous waste labels (Photo 8). However, in both cases, the printing on the label had faded to the point where it was barely legible (Photo 9). As with the previously described used oil tank, no written logs were kept of daily inspections. In addition, the facility representative was not able to produce an engineer's certification of the tanks' structural integrity.





Photo 8: used oil tank

Photo 9: label close-up

Near the facility furnace was a bin for spent blast grit, a non-RCRA, California only hazardous waste (Photos 10 and 11). The bin was closed and properly labeled. No violations were noted.








Photo 11: label close-up

- Adjacent to the spent blasting grit bin was a satellite accumulation area with a 55-gallon drum of used oil. The drum was labeled but the label was unreadable (Photo 12).




Photo 12: satellite accumulation container of used oil with unreadable label

- The inspectors noted a bin for contaminated rags and personal protective equipment (PPE). The rags and PPE are sent to an industrial laundry for cleaning and then returned to the facility. Per the California Health and Safety Code, dirty rags are exempt from regulation if they are managed correctly and picked up for laundering by an industrial laundry service. No violations were noted.
- Near the rag bin were two 55-gallon satellite accumulation drums (Photo 13). One contained used oil, the other, oil-contaminated swab heads. The used oil container had an unreadable label while the swab head container had no label. Both containers had open bungs (Photo 14).



Photo 13: two open 55-gallon satellite accumulation containers



Photo 14: close up of open bung

Batch House: D and E Furnace Area

The inspectors noted the following:

- An unlabeled, open 55-gallon container of discarded PPE (gloves, coveralls, etc.) that appeared to be contaminated with grease or oil (Photo 15). Adjacent to this container was an unlabeled, open drum containing a mixture of trash and contaminated PPE (Photo 16). The facility representative was not able to verify at the time whether or not the contaminated PPE in both containers was a non-RCRA, California only hazardous waste.



Photo 15: two open unlabeled drums Photo 16: interior shot of the second drum containing discarded PPE

One trash can for non-hazardous waste, containing what appeared to be oil-contaminated PPE (Photo 17). The inspectors requested that the facility representative make a hazardous waste determination for PPE and rags that are contaminated with oil to ensure that a non-RCRA California only waste is not improperly discarded with non-hazardous trash.



Photo 17: trash can with soiled PPE

Selecting Maintenance Satellite Accumulation Area #1 (Photo 18)



Photo 18: Selecting Maintenance Satellite Accumulation Area

The inspectors noted the following:

- One 55-gallon drum of used oil whose label did not include an accumulation start date and was not identified with the words "USED OIL" (Photo 19);



Photo 19: used oil container label without accumulation start date

- One 55-gallon drum of spent aerosol cans, closed and labeled correctly;
- One 55-gallon drum of contaminated rags, closed and labeled correctly;
- One 55-gallon drum of spent lubricant. The drum was closed and labeled correctly, but there was no access to it since the other drums were in front of it.

Selecting Maintenance Satellite Accumulation Area #2

The inspectors noted the following:

- One 55-gallon drum of spent MEK. Although the drum was closed and labeled correctly, there was an unlabeled quart container of spent MEK on top of the drum (Photo 20).



Photo 20: Drum of spent MEK with unlabeled quart bottle of MEK on top

One 55-gallon drum of rags with MEK ink. The drum was closed and labeled, but its accumulation start date was entered as 12/5/2005 (Photo 21) (the facility representative said that this was an incorrect date). In addition there was a pile of dirty rags and a spent aerosol can on top of the drum (Photo 22).

000000000000000000000000000000000000000
HAZARDOUS
WASTE 05-144
STATE AND FEDERAL LAW PROHIBIT IMPROPER DISPOSAL. IF FOUND, CONTACT THE NEAREST POLICE OR PUBLIC SAFETY AUTHORITY, THE U.S. ENVIRONMENTAL PROTECTION AGENCY OR THE CAUFONNIA DEPARTMENT OF TOXIC SUBSTANCES CONTROL.
TOTAL INTO INFORMATION:
NAME DWENTS RECORDARY GLASS CONTAINERS, INC.
OTY OFFICE COLORES
DNO DOCUMENT NO. CATODOSISSIS
WASTINGTO DECISION TO CA
CONTENTS, COMPOSITION: WASTE NO. 352 ACCUMULATION STAFT DATE 1275/2005 EAGS WITH MEK INK AND SOLVENT
PAGEORAL OFFICE MADRIENCANCE ROTTLE PROPERTY AND SOLVENS
PHYSICAL STATE: HAZAPOOUS PROPERTIES: FLAMMABLE TOXIC SATEL FUEL CORROSIVE TREACTIVITY TO OTHER
SATELL THE ACCOUNTY OTHER
SATELLITE ACCUMULATION
D.G.T. PROPER INSPERSAGE
HANDLE WITH CARE!
CONTROLE WITH CARE!
LABORERATES (HELD EZS-SADE) WAS REVENUENCE CO.

Photo 21: spent MEK drum label with incorrect satellite accumulation date.



Photo 22: 55-gallon drum of used MEK with a pile of dirty rags and a spent aerosol on top.

Universal Waste Storage Area

The inspectors noted spent fluorescent lamps in the area that were not being stored in containers. There were also spent lamps in unlabeled boxes, but the boxes were open, with the lamps sticking out (Photos 23 and 24).





Photos 23 and 24: uncontainerized or partially containerized spent fluorescent lamps

Hazardous Waste Storage Area

At the time of the inspection, there were only empty 55-gallon drums in the designated hazardous waste storage area. No violations were noted.

Record Review

RCRA

Manifests and LDR Notification forms: Manifests and LDR notification forms dating from 2008 to 2010 were reviewed. No violations were noted.

Contingency Plan: No violations were noted

Training: The facility representative was able to provide documentation of annual refresher training. However, the facility did not have the training records required under CCR Title 22 §66265.16(a) through (d), specifically:

- 1) the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
- 2) a written job description for each position listed;
- 3) a written description of the type and amount of both introductory and continuing training that will be given to each person listed above;

4) records that document that the training or job experience required have been completed.

Weekly Inspections: The inspectors reviewed the facility's weekly inspection logs. No violations were noted.

-Area of Concern: although the logs indicated that the facility's waste storage areas were being inspected weekly, the inspectors noted numerous instances during the course of the inspection where hazardous waste labels had faded to the point of being unreadable. When performing these weekly inspections, facility personnel should pay particular attention to the legibility of the hazardous waste containers' labels.

Daily Tank Inspections: The facility had not set up a formal system for inspecting its hazardous waste tanks on a daily basis.

Tank Engineering Certification: The facility representative was not able to provide to the inspectors certifications by a qualified, outside engineer regarding the structural integrity of its hazardous waste tanks.

Biennial Report: No violations

POTENTIAL RCRA VIOLATIONS

Hazardous Waste Storage Area Labeling Requirements	
Title 22 §66262.34(a)(3) and (f) (40 CFR §262.34(a)(2) and (3))	Each container used for onsite accumulation of hazardous waste shall be labeled with the following information: - the words "Hazardous Waste"; - the initial date of waste accumulation; - composition and physical state of the waste; - the particular hazardous properties of the waste; - the name and address of the person producing the waste.
	The accumulation start date on the hazardous waste label for the outdoor checker dust bin had faded to illegibility (corrected during the inspection).
Satellite Accumulation Area Labeling Requirements	
Title 22 §66262.34(e)(1)(E) and (f)(3) (40 CFR §262.34(c)(1))	Generators who accumulate hazardous waste on site without a permit or grant of interim status shall comply with the following requirements: (1) the date upon which each period of accumulation begins shall be clearly marked and visible for inspection on each container; (2) the date the applicable accumulation period begins, and (3) each container and tank used for onsite accumulation of hazardous waste shall be labeled or marked clearly with the words, "Hazardous Waste." Additionally, all containers shall be labeled with the following information: (A) composition and physical state of the wastes; (B) statement or statements which call attention to the particular hazardous properties of the waste (e.g.,

	flammable, reactive, etc.); (C) name and address of the person producing
	the waste.
	 A 1-quart container of spent MEK in the Selecting Maintenance Satellite Accumulation Area #1 was unlabeled; One 55-gallon container of discarded MEK contaminated rags had an incorrect satellite accumulation date.
Used Oil Labeling	
Title 22 §66279.21(b) (40 CFR §279.22(c))	Containers and aboveground tanks used to store used oil and fill pipes used to transfer used oil into underground storage tanks shall be marked or clearly labeled with the words "USED OIL."
	The following used oil containers/tanks were not marked with the words "USED OIL":
	 One 55-gallon drum of used oil in the C Furnace Area; One 55-gallon drum of used oil in the Selecting Maintenance Satellite Accumulation Area #1.
Universal Waste - Containers	
Title 22 §66273.33(b)(1) (40 CFR §273.33(d)(1))	A universal waste handler shall contain any lamp in a container or package that is structurally sound, adequate to prevent breakage, and compatible with the contents of the lamp. Such a container or package shall remain closed and shall lack evidence of leakage, spillage or damage that could cause leakage under reasonably foreseeable
	conditions.
	Spent fluorescent lamps stored in the facility's universal waste storage area were in open containers or not containerized at all.

Universal Waste – Labeling	
Title 22 §66273.34(c) (40 CFR §273.34(e))	Lamps (i.e., each lamp), or a container or package in which the lamps are contained, shall be labeled or marked clearly with the following phrase: "Universal Waste-Lamp(s)".
	The discarded spent fluorescent lamps in the facility's universal waste storage area were not labeled.
Universal Waste – Accumulation Start Date	
Title 22 §66273.35(b) (40 CFR §273.35(b))	A universal waste handler shall be able to demonstrate the length of time that the universal waste has been accumulated from the date it became a waste or was received.
	The discarded fluorescent lamps in the facility's universal waste storage area did not have accumulation start dates.
Training: Job Title and Description	
Title 22 §66265.16(d)(1)-(4) (40 CFR §265.16(d)(1-4))	Title 22 §66265.16(d)(1-4) requires that a generator maintain the following training records: (1) the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job; (2) a written job description for each position listed; (3) a written description of the type and amount of both introductory and continuing training that will be given to each person listed above; (4) records that document that the training or job experience required have been completed.
·	The facility did not have these records.

POTENTIAL NON-RCRA, CALIFORNIA ONLY VIOLATIONS

Hazardous Waste Storage Area Labeling Requirements	
Title 22 §66262.34(a)(3) and (f)	Each tank used for onsite accumulation of hazardous waste shall be labeled with the following information: - the words "Hazardous Waste"; - the initial date of waste accumulation:
	 The hazardous waste label of the exterior 3950-gallon tank of used oil was faded to illegibility; The hazardous waste labels of the 2025-gallon tanks of used oil in the C Furnace area were faded to illegibility.
Satellite Accumulation Area Labeling Requirements	
Title 22 §66262.34(e)(1)(C); Title 22 §66262.34(e)(1)(E), (f)(3)	A generator may accumulate as much as 55 gallons of hazardous waste at or near any point of generation if each container used for onsite accumulation is labeled with the words "Hazardous Waste" and with the following information: - the initial date of waste accumulation is clearly marked and visible for inspection on each container used for accumulation of hazardous waste; - composition and physical state of the waste; - the particular hazardous properties of the waste; - the name and address of the person producing the waste. - The two satellite accumulation 55-gallon drums (used oil and oil-contaminated swab
	drums (used oil and oil-contaminated swab heads) in the C Furnace Area were unlabeled; - The 55-gallon satellite accumulation

container of used oil adjacent to the spent blast grit bin had an unreadable label;
blast grit bin had an unreadable label;
- The label of the 55-gallon satellite
accumulation container of used oil in the
Selecting Maintenance Area lacked an
accumulation start date.
Title 22 §66262.34(a)(1)(A) states that a
generator may accumulate hazardous waste
on-site without a permit provided that the
generator complies with the applicable
requirements of article 9 of chapter 15.
Title 22 §66265.173(a) (Article 9) states that a container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste.
Two 55 callon satallite accumulation containers
Two 55-gallon satellite accumulation containers in the C Furnace Area had open bungs.
In the C Furnace Area had open bungs.
Title 22 §66262.34(a)(4) states that a generator may accumulate hazardous waste on-site without a permit provided that the generator complies with the applicable requirements of article 3 of chapter 15.
Title 22 §66265.35 (Article 3) states that the owner or operator (of a facility that generates hazardous waste) shall maintain aisle space to allow the unobstructed movement of personnel and equipment.
One 55-gallon drum of spent lubricant in the Selecting Maintenance Satellite Accumulation Area #1 lacked access.
A person who generates a waste shall
determine if that waste is a hazardous
waste.

Title 22 §66262.11(a) and (b)	Throughout the facility there were instances of
	dirty rags and PPE being discarded with non- hazardous trash, although no determination had
	been made as to whether or not they were non-
	RCRA hazardous wastes.
Tanks: Certification	
Title 22 §66265.191(a)	Title 22 §66262.34(a) states that a generator may accumulate hazardous waste on-site without a permit provided that the generator complies with the applicable requirements of article 10 of chapter 15.
	Title 22 §66265.191(a) (Article 10) states that the facility owner must keep on file at the facility a written assessment reviewed and certified by an independent, qualified, professional engineer, that attests to the tank system's integrity.
	The facility was not able to provide engineering certification of the structural integrity of the facility's three used oil tanks.
Tanks: Leak Detection System	
Title 22 §66265.193(c)(3)	Title 22 §66265.193(c)(3) (Article 10) states that hazardous waste tanks must be provided with a leak detection system.
	The facility's outdoor 3950-gallon used oil tank
	did not have a leak detection system.
Tanks: Daily Inspection	
Title 22 §66265.195(a)	The owner or operator must inspect at least once each operating day data gathered from monitoring and leak detection equipment.
	The facility did not have a formal daily tank inspection system implemented.

			š

Photograph Log for EPA's December 9, 2010 Owens-Brockway Glass Container RCRA Inspection


All photographs on this log were taken with a digital camera by Amy C. Miller, RCRA Enforcement Office, EPA Region IX. Please note that each photograph number begins with "PC0901" and that the photograph log starts with photograph number 090.


- 27. Error
- 28. Error
- 29. Outdoor Area: 500-gallon diesel tank
- 29a. Lower resolution version
- 30. Outdoor Area: Hazardous waste label on the 3,950-gallon used oil tank. Note: Label is faded.
- 30a. Cropped version
- 31. Outdoor Area: Overview of the 3,950-gallon used oil tank.
- 32. Outdoor Area: 3,950-gallon used oil tank marked as "used oil".
- 32a. Cropped version
- 33. Outdoor Area: Hazardous waste label on roll-off bin of furnace/checker dust. Note: the label does not have an accumulation start date.
- 33a. Cropped version
- 34. Outdoor Area: Overview of the roll-off bin of furnace/checker dust.
- 34a. Cropped version
- 35. Outdoor Area: Hazardous waste label on roll-off bin of furnace/check dust is modified to have an accumulation start date.
- 36. Outdoor Area: Bin for EP dust re-used on-site.
- 36a. Lower resolution version
- 37. Stairwell: Trash can with lint waste.
- 37a. Cropped version


- 38. Stairwell: Trash can with lint waste.
- 38a. Lower resolution version
- 39. Stairwell: Overview of the two trash cans
- 39a. Cropped version
- 40. Basement Level: 2,025-gallon used oil tank. Photograph is blurred.
- 41. Basement Level: 2,025-gallon used oil tank with hazardous waste label and marked as "used oil".
- 41a. Lower resolution version
- 42. Basement Level: Close up of hazardous waste label on 2,025-gallon used oil tank. Note: no accumulation start date.
- 42a. Cropped version
- 43. Basement Level: 2,025-gallon used oil tank is open on top.
- 44. Near Furnace Area: spent blast grit bin.
- 44a. Lower resolution version
- 45. Near Furnace Area: Hazardous waste label on spent blast grit.
- 45a. Cropped version
- 46. Near Furnace Area: Used oil container. Facility representative stated it was not waste, but rather used on site. Image is blurred.
- 47. Near Furnace Area: Same as previous photograph.
- 48. Near Furnace Area: Close-up of the top of the container in the previous photograph.
- 49. Near Furnace Area: Close-up of the label on the container in photograph 47.
- 50. C-Tank Satellite Accumulation Area: Hazardous waste label on 55-gallon drum of used oil. Note: label was faded.
- 50a. Cropped version
- 51. C-Tank Satellite Accumulation Area: Open bin of contaminated gloves.


- 52. C-Tank Satellite Accumulation Area: Hazardous waste label on the container in the previous photograph.
- 53. C-Tank Satellite Accumulation Area: Two open top 55-gallon drums of used oil adjacent to the bin of contaminated gloves.
- 53a. Lower resolution version
- 54. C-Tank Satellite Accumulation Area: Same as previous photograph.
- 55. C-Tank Satellite Accumulation Area: Close up of the open top of the container in the previous photograph.
- 55a. Lower resolution version
- 56. D and E Area: Open top can of contaminated gloves.
- 57. D and E Area: Contents of the can in the previous photograph.
- 57a. Lower resolution version
- 58. D and E Area: Trash can.
- 59. D and E Area: Contaminated gloves inside trash can in previous photograph.
- 59a. Lower resolution version
- 60. Selecting Maintenance Area: Overview of satellite accumulation area.
- 60a. Lower resolution version
- 61. Selecting Maintenance Area: Hazardous waste label for used oil on one of the three containers in the previous photograph. Note: the label does not have an accumulation start date.
- 61a. Cropped version
- 62. Selecting Maintenance Area: Hazardous waste label on one of the three containers in the photograph 60.
- 63. Selecting Maintenance Area: Hazardous waste label on one of the three containers in the photograph 60.
- 64. Selecting Maintenance Area: Inside the flammable cabinet are a 55-gallon drum of methyl ethyl ketone and several unlabeled containers of Methyl ethyl ketone.

- 64a. Lower resolution version.
- 65. Selecting Maintenance Area: Label of the 55-gallon drum of methyl ethyl ketone in previous photograph.
- 66. Selecting Maintenance Area: Inside the flammable cabinet are a 55-gallon drum of methyl ethyl ketone rags and rags stored on top of the container
- 67. Selecting Maintenance Area: Label of the 55-gallon drum of methyl ethyl ketone rags in previous photograph. Note: the accumulation start date states "12/5/2005".
- 67a. Cropped version
- 68. Universal waste and CRT Storage Area: Overview of the area.
- 69. Universal waste and CRT Storage Area: Close-up of lamps stored without a container.
- 69a. Cropped version
- 70. Universal waste and CRT Storage Area: Close-up of lamps stored without a container.
- 70a. Cropped version
- 71. 90 Day Storage Area: Open used oil 55-gallon drum.
- 72. 90 Day Storage Area: Close-up of label in previous photograph. Note: there is no accumulation start date.
- 73. 90 Day Storage Area: All empty containers except for the blue bin in the back area.
- 74. 90 Day Storage Area: Hazardous waste label on one of the empty containers.
- 75. 90 Day Storage Area: Hazardous waste label on one of the empty containers.
- 76. 90 Day Storage Area: All empty containers beyond the blue bin in the foreground.













PC090176.JPG 12/9/2010

Photograph Log for EPA's December 9, 2010 Owens-Brockway Glass Container RCRA Inspection


All photographs on this log were taken with a digital camera by Amy C. Miller, RCRA Enforcement Office, EPA Region IX. Please note that each photograph number begins with "PC0901" and that the photograph log starts with photograph number 090.

- 27. Error
- 28. Error
- 29. Outdoor Area: 500-gallon diesel tank
- 30. Outdoor Area: Hazardous waste label on the 3,950-gallon used oil tank. Note: Label is faded.
- 31. Outdoor Area: Overview of the 3,950-gallon used oil tank.
- 32. Outdoor Area: 3,950-gallon used oil tank marked as "used oil".
- 33. Outdoor Area: Hazardous waste label on roll-off bin of furnace/checker dust. Note: the label does not have an accumulation start date.
- 34. Outdoor Area: Overview of the roll-off bin of furnace/checker dust.
- 35. Outdoor Area: Hazardous waste label on roll-off bin of furnace/check dust is modified to have an accumulation start date.
- 36. Outdoor Area: Bin for EP dust re-used on-site.
- 37. Stairwell: Trash can with lint waste.
- 38. Stairwell: Trash can with lint waste.
- 39. Stairwell: Overview of the two trash cans
- 40. Basement Level: 2,025-gallon used oil tank. Photograph is blurred.
- 41. Basement Level: 2,025-gallon used oil tank with hazardous waste label and marked as "used oil".
- 42. Basement Level: Close up of hazardous waste label on 2,025-gallon used oil tank. Note: no accumulation start date.
- 43. Basement Level: 2,025-gallon used oil tank is open on top.

- 44. Near Furnace Area: spent blast grit bin.
- 45. Near Furnace Area: Hazardous waste label on spent blast grit.
- 46. Near Furnace Area: Used oil container. Facility representative stated it was not waste, but rather used on site. Image is blurred.
- 47. Near Furnace Area: Same as previous photograph.
- 48. Near Furnace Area: Close-up of the top of the container in the previous photograph.
- 49. Near Furnace Area: Close-up of the label on the container in photograph 47.
- 50. C-Tank Satellite Accumulation Area: Hazardous waste label on 55-gallon drum of used oil. Note: label was faded.
- 51. C-Tank Satellite Accumulation Area: Open bin of contaminated gloves.
- 52. C-Tank Satellite Accumulation Area: Hazardous waste label on the container in the previous photograph.
- 53. C-Tank Satellite Accumulation Area: Two open top 55-gallon drums of used oil adjacent to the bin of contaminated gloves.
- 54. C-Tank Satellite Accumulation Area: Same as previous photograph.
- 55. C-Tank Satellite Accumulation Area: Close up of the open top of the container in the previous photograph.
- 56. D and E Area: Open top can of contaminated gloves.
- 57. D and E Area: Contents of the can in the previous photograph.
- 58. D and E Area: Trash can.
- 59. D and E Area: Contaminated gloves inside trash can in previous photograph.
- 60. Selecting Maintenance Area: Overview of satellite accumulation area.
- 61. Selecting Maintenance Area: Hazardous waste label for used oil on one of the three containers in the previous photograph. Note: the label does not have an accumulation start date.
- 62. Selecting Maintenance Area: Hazardous waste label on one of the three containers in the photograph 60.

- 63. Selecting Maintenance Area: Hazardous waste label on one of the three containers in the photograph 60.
- 64. Selecting Maintenance Area: Inside the flammable cabinet are a 55-gallon drum of methyl ethyl ketone and several unlabeled containers of Methyl ethyl ketone.
- 65. Selecting Maintenance Area: Label of the 55-gallon drum of methyl ethyl ketone in previous photograph.
- 66. Selecting Maintenance Area: Inside the flammable cabinet are a 55-gallon drum of methyl ethyl ketone rags and rags stored on top of the container
- 67. Selecting Maintenance Area: Label of the 55-gallon drum of methyl ethyl ketone rags in previous photograph. Note: the accumulation start date states "12/5/2005".
- 68. Universal waste and CRT Storage Area: Overview of the area.
- 69. Universal waste and CRT Storage Area: Close-up of lamps stored without a container.
- 70. Universal waste and CRT Storage Area: Close-up of lamps stored without a container.
- 71. 90 Day Storage Area: Open used oil 55-gallon drum.
- 72. 90 Day Storage Area: Close-up of label in previous photograph. Note: there is no accumulation start date.
- 73. 90 Day Storage Area: All empty containers except for the blue bin in the back area.
- 74. 90 Day Storage Area: Hazardous waste label on one of the empty containers.
- 75. 90 Day Storage Area: Hazardous waste label on one of the empty containers.
- 76. 90 Day Storage Area: All empty containers beyond the blue bin in the foreground.











PC090176.JPG 12/9/2010

				•
	·			
		•		
		·		

CAT 6006 2



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street San Francisco, CA 94105-3901

MAR 1 4 2011

CERTIFICATION OF VIOLATION CORRECTION

William Boscacci
Environmental, Health & Safety Director
Owens-Brockway Glass Container Inc.
3600 Alameda Ave.
Oakland, CA 94601
EPA Identification Number: CAT000618918

Dear Mr. Boscacci:

On December 9, 2010, a hazardous waste compliance inspection was conducted by a representative of the United States Environmental Protection Agency ("EPA") at Owens-Brockway Glass Container Inc., located in Oakland, CA, with EPA Identification Number CAT000618918. During the course of this investigation, information was gathered in accordance with Section 3007(a) of the Resource Conservation and Recovery Act ("RCRA"), as amended {42 U.S.C. §6927}.

Pursuant to Section 3008 of RCRA {42 U.S.C. § 6928}, the EPA required you to correct the identified areas of noncompliance and to submit documentation of their correction to the EPA within 30 days from the date of your receipt of the Warning Letter sent by the EPA on January 25, 2011.

Your submittal, dated February 23, 2011, adequately addresses the violations which were noted during the inspection, and documents Owens-Brockway Glass Container Inc.'s return to compliance with the regulations cited in the inspection report. This letter should not be construed as a determination by the EPA of your compliance with any other applicable regulation.

Owens-Brockway Glass Container Inc. should continue to take the necessary steps to maintain and ensure compliance with all applicable Federal, State and local environmental requirements. If you have questions related to the inspection report or this letter, please contact Clint Seiter of my staff at (415) 972-3298 or seiter.clint@epa.gov.

Sincerely,

Amy C.: Miller, Manager RCRA Enforcement Office

cc: Charles McLaughlin, DTSC

Leroy Griffin, Oakland Fire Department


•

ROUTING SLIP FOR RCRA INSPECTION REPORTS

From: CL	INT SEITH	
Facility Name:	OWENS-BROCKWA-1 GLASS	

	Initials	Date
1. Lead Inspector (Report Writer):	as	1/2/11
् RCRA Info Evaluation & Violation Entry (CEI Date)	c75	1/12/11
- ICIS Entry (Add Compliance Monitoring)	CTE	1/12/11
- RCRA Info Enforcement Entry (102, 105)	c15	1/12/11
– EJ Maps 🤰		
2. 2nd Inspector (Reviewer): Helloway	Re	1/14/11
3. QA/QC Team Reviewer (Formal Actions Only):		-
4. Supervisor:	ACM	118/1
5. Lou Tully: ?		
6. Lead Inspector (File):		

Notes:
- FACTURE Change.
- Photolog should only have original photos
Not cropped lets talk.




ROUTING SLIP FOR RCRA INSPECTION REPORTS

From:		
Facility Name:		
	Initials	Date
1. Lead Inspector (Report Writer):		
- RCRA Info Evaluation & Violation Entry (CEI Date)		
- ICIS Entry (Add Compliance Monitoring)		
- RCRA Info Enforcement Entry (102, 105)		
– EJ Maps		
2. 2nd Inspector (Reviewer):		
3. QA/QC Team Reviewer (Formal Actions Only):		·
4. Supervisor:		
5. Lou Tully:	·	
6. Lead Inspector (File):		

Notes:

			٠ .	
,				
	,			



ACM 12/9/10

	I	

Report run on: January 3, 2011 - 5:03 PM

User Selection Criteria

BR Cycle: 2009

Number of GM Forms: 25

Handler ID: CAT000618918

Number of WR Forms: 25

Included in National Report: Yes

GM and WR Form Sort Order: Descending Order by Waste Amount

Results:

Data meeting the criteria you selected follows.

Total Pages: 3

Report Description

This report is designed to provide all information from the Biennial Report forms in a concise manner. This report should be used after identifying facilities with potential problems using the Preliminary State Detail Analysis volume, the Preliminary TSD & LQG List volumes or the Top Generator/Manager/Shipper/Receiver List reports below. If the user is not interested in seeing GM or WR forms, 0 (zero) may be specified to omit this portion of the report. The user may restrict data to records that were actually included in the National Biennial RCRA Hazardous Waste Report.

Report Information

Name:

b comprehensive.rdf

Deployed: Last Revised: April 2003

Contact:

rcrainfo.help@epa.gov

June 2010

2009 Comprehensive Biennial Report

UNITED STATES

Report run on: January 3, 2011 - 5:03 PM

EPA ID: CAT000618918 Handler Included in National Report: Yes Submittal Source: Annual/Biennial Report updated with Notification Sequence Number: 1 Site Name: OWENS BROCKWAY GLASS CONTAINERS Activity Location: CALIFORNIA Land Type: Private

Location Address:

3600 ALAMEDA AVENUE Mailing Address: 3600 ALAMEDA AVENUE OAKLAND, CA 94601 OAKLAND, CA 94601 ALAMEDA UNITED STATES

Contact Person: BILL BOSCACCI Certifying Person: PLANT MANAGER LOREN JOHNSON

3600 ALAMEDA AVENUE Signed: 02/18/2010 OAKLAND, CA 94601

Ph: (510) 436-2166, Fax:(510) 436-2032 BILL.BOSCACCI@O-I.COM

Owner (current) ONE O-I PLAZA Type: Private

OWENS ILLINOIS ONE MICHAEL OWENS WAY Phone: (567) 336-8682 From: 01/01/1937 PERRYSBURG, OH 43551

PERRYSBURG Notes: F

Operator (current) Private

Type: **OWENS ILLINOIS**

From: 01/01/1937

Notes: Regulated Waste Activities

County:

Notes:

Hazardous Waste Generator Status Federal: LARGE QUANTITY GENERATOR **Used Oil Activities**

State: LARGE QUANTITY GENERATOR Used Oil Transporter Activity Off-Specification Used Oil Burner: Exempt Boiler and/or Industrial Furnace

Transfer Facility: Used Oil Fuel Marketer Activity Importer Activity:

Mixed Waste Generator: Transporter: Marketer who first claims the used oil Transporter Activity: meets the specifications: Used Oil Processor and/or Tsd Activity:

Re-refiner Activity Recycler Activity: Marketer who directs shipment off-specification used oil to off-specification Processor:

Other Hazardous Waste Generator Activities used oil burner: Refiner: Small Quantity Onsite Burner Exemption: Destination Facility for Universal Waste: Underground Injection Control:

Smelting, Melting, Refining Furnace Exemption: **EPA Waste Codes:** D001 D006 D007 D008 D010 D035 F005

State Waste Codes: 135 181 214

Universal Waste

No Universal Waste Information

NAICS Codes: 327213 - GLASS CONTAINER MANUFACTURING

State Activity: No State Activity Information

2009 Comprehensive Biennial Report

Report run on: January 3, 2011 - 5:03 PM

CAT000618918 - OWENS BROCKWAY GLASS CONTAINERS (continued)

Form GM - Page: 1

ELECTROSTATIC PRECIPITATOR DUST EPA Waste Codes: D006 D007 D008 D010

State Waste Codes: CA-181

Notes:

Source: HQ-G15-EQUIPMENT CHANGE

Form: HQ-W319-OTH INORGANIC SOLIDS

RCRA-radioactive Mixed: NO

On-Site Process:

Qty Generated (tons):

94.52

Qtv Generated: 189,030.00

UOM: HQ-POUNDS

Density: 0.00/

Generation included in NBR: Yes

Off-Site Shipments:

EPA ID

Sequence Number

Quantity (tons) Quantity **Management Method**

NVT330010000

27.15

54,290.00 H132 - LANDFILL OR SURFACE IMPOUNDMENT

Shipment Included in NBR Yes

CAT000646117

1 2

67.37

134,740.00 H132 - LANDFILL OR SURFACE IMPOUNDMENT

Yes

Form GM - Page: 2

ELECTROSTATIC PRECIPITATOR RINSATE

EPA Waste Codes: D007 D008

State Waste Codes: CA-135

Notes: CLEANING OF AIR POLLUTION CONTROL EQUIPMENT

Source: HQ-G13-CLEANING EQUIPMENT

Form: HQ-W504-OTHER SLUDGES

RCRA-radioactive Mixed: NO

On-Site Process:

Waste Minimization: No waste minimization efforts were implemented

Waste Minimization: Recycling on-site was implemented

Qty Generated (tons):

27.90

Qty Generated: 55,800.00

UOM: HQ-POUNDS

Density: 0.00/

Generation Included in NBR: Yes

Off-Site Shipments:

EPA ID

Sequence Number

Quantity (tons)

Quantity

Management Method

Shipment Included in NBR

27.90 55,800.00 H121 - NEUTRALIZATION ONLY CAD008488025

Form GM - Page: 3

IGNITABLE SPENT SOLVENT AND INK, MEK EPA Waste Codes: D001 D035 F005

State Waste Codes: CA-214

Notes: CLEANING OF SPRAY HEADS

Source: HQ-G01-RINSING

Form: HQ-W209-PAINT, INK, ETC.

RCRA-radioactive Mixed: NO

On-Site Process:

Qty Generated: 55.00

UOM: HQ-GALLONS

Density: 6.70/ HQ-lbs/gal

Generation Included in NBR: Yes

Off-Site Shipments:

Qty Generated (tons):

Sequence Number

Quantity (tons)

Quantity

Management Method

EPA ID

Shipment included in NBR

ARD981057870

0.18

55.00 H061 - FUEL BLENDING

Waste Minimization: No waste minimization efforts were implemented

Yes

Yes

No Form WR Pages Submitted

^{*} End of Report *

g 1 - 42			



CAT 000 618918 Part A = 3A-2

Oakland, CA 94601 +1 510 436 2166 tel +1 510 436 2032 fax bill.boscacci@ us.o-i.com

February 23, 2011

Clint Seiter Mailcode: WST-3 RCRA Enforcement Office U. S. Environmental Protection Agency 75 Hawthorne Street San Francisco, CA 94105

Re: RCRA Compliance Evaluation Inspection of December 9, 2010

Dear : Mr. Seiter,

This letter will provide written and photographic documentation of compliance to the potential violations detailed in the warning letter received by Owens Brockway on January 25, 2011. The order which this documentation is layout here will follow that which you presented in your report starting on page 14, Potential RCRA Violations.

Hazardous Waste Storage Area Labeling Requirements

First issue, the faded hazardous waste label on the outdoor checker dust bin; this photo shows

the label with the writing legible.




Satellite Accumulation Area Labeling Requirements

Next issue, the one quart container of spent MEK in Selecting Maintenance, the photo shows the container labeled. It is a container used to transfer the spent ink and solvent to the satellite accumulation drum.





Also, a 55 gallon drum of discarded MEK contaminated rags had an incorrect date. This next photo shows the correction.



Used Oil Labeling

This next photo will serve as photographic evidence of the resolution of this issue. The specific drum mentioned has been shipped off-site and a copy of the manifest is attached to this letter. However, as you can see in the "Hazardous Description "field of the label the words "Used Oil" are printed. We have had all new labels for oil printed and the old labels removed and destroyed. All of the hazardous waste labels for oil now state this.

IF FOUND, CONTACT THE NEAREST POLICE OR PUBLIC SAFETY AUTHORITY, OR THE U.S. ENVIRONMENTAL PROTECTION AGENCY OR THE CALIFORNIA DEPARTMENT OF TOXIC SUBSTANCES CONTROL NON RCRA HAZARDOUS WASTE, LIQUID (OIL) ROPER D.O.T. MIPPING NAME SOLID | LIQUID | FLAMMABLE | TOXIC | CORROSIVE | REACTIVITY | OTHER (510) 436-2166 **NERATOR INFORMATION:** TELEPHONE . OWENS ILLINOIS INC PLANT 20 - OAKLAND 3000 ALAMEDA AVENUE DAKLAND 94801 STATE STATE E.P.A. WASTE CAT000618918 NON MANIFEST

Universal Waste - Containers

This next photo shows the spent fluorescent bulbs properly containerized.



Universal Waste - Labeling

This next photo shows the spent fluorescent bulbs properly labeled.



Universal Waste - Accumulation Start Date

This next photo shows the spent fluorescent bulbs properly labeled with a start date of accumulation.



Training: Job Title and Description

The appendix of this letter contains the list of names of the hazardous waste handlers, job description of the hazardous waste manager and the documentation of the required training for the handling and disposing of oily debris/rags/gloves.

Hazardous Waste Storage Area Labeling Requirements

This next photo shows label on the exterior used oil tank as being legible.


THO HOXE	prioto criotic labor on are exterior acou on tariit ac boning
	STATE & FEDERAL LAW PROHIBITS IMPROPER DISPOS STATE & FEDERAL LAW PROHIBITS IMPROPER DISPOS IF FOUND, CONTACT THE NEAREST POLICE OR PUBLIC SAFETY AUTHORITY, OR THE U.S. ENVIRONMENTAL PROTECTION AGENCY OR THE CALIFORNIA DEPARTMENT OF TOXIC SUBSTANCES CONTROL. PROPER B.O.T. NON RCRA HAZARDOUS WASTE, LIQUID (OIL)
	SHIPPING NAME
	SOLID DLIQUID DE FLAMMABLE TOXIC DE CORROSIVE DE REACTIVITY DOTHER
	HAZZER DELIGION DE CONTROLI DI CONTROLI CANTE PROPERTIES:
	HAZARDOUS DESCRIPTION PHYSICAL STATE PROPERTIES
	(510) 438-2166
	EGENERATOR INFORMATION: TELEPHONE
	DIMENS ILLINOUS INC SUSANT 20 - CARLAND
	MAME SWENS THE POWER 25 CONTENTS
	Address - Address
	STATESTATE
	STATE
	BIA CATGOOBISHIS E.P.A. NON WASTE
	CATBOOS1991B E.P.A. NON WASTE
	Thores.
	ACCUMULATION 1 / 10 / 10 MANIFEST
	ESTABLE DATE TRACKING NO

This photo shows the label of the used oil tank in the basement of C furnace area being legible.



Satellite Accumulation Area Labeling Requirements

This photo is of a C Furnace Area drum labeled.



This photo shows the Selecting Maintenance Area drums labeled.



Open Containers

These photos show the waste drums in the C furnace area with the lid and bung closed





Lack of Aisle Space

This photo shows proper access to the drums is maintained.



Failure to make a hazardous waste determination

A hazardous waste determination of the oil/grease contaminated rags and personal protective equipment (PPE) has been made and it has been determined to be "NON-RCRA Hazardous Waste, Solid (Oil, Debris)". The laboratory analysis is attached in the appendix. The established Standard Operating Procedure for disposing this waste is attached in the appendix

Tanks: Certification

The appendix of this letter contains a copy of the certification of the structural integrity of the facility's three used oil tanks.

Tanks: Leak Detection System

The Leak Detection System of our 3950 gallon used oil tank is the daily inspection by our personnel.

Tanks: Daily Inspection

The appendix of this letter contains a copy of the daily inspection report that is completed during the monitoring of the facility's three used oil tanks.

If you have any questions about this response contact Bill Boscacci at 510-436-2166 or bill.boscacci@o-i.com.

Sincerely,

Tom Bost

O-I Oakland Plant Manager

	N			1200
-		ę		
			•	
		,		
		·		
			-	
		-		

Form Approved. OMB No. 2050-0039 Please print or type. (Form designed for use on elite (12-pitch) typewriter.) 4. Manifest Tracking Number 2. Page 1 of 3. Emergency Response Phone 1. Generator ID Number 008051516 JJK UNIFORM HAZARDOUS (800) 368-4778 WASTE MANIFEST CAT000618918 Generator's Site Address (if different than mailing address 5. Generator's Name and Mailing Address 3500 ALAMEDA AVENUE OWENS ILLINOIS INC PLANT 20 - DAKLAND 3500 ALAMEDA AVENUE DAKLAND CA 34601 94801 CA CAKLAND 510 436-2166 Generator's Phone: U.S. EPA ID Number 6. Transporter 1 Company Name CAR000188201 ENVIRONMENTAL RECOVERY SERVICES, INC U.S. EPA ID Number 7. Transporter 2 Company Name 8. Designated Facility Name and Site Address U.S. EPA ID Number DEMENNO KERDOON 2000 NORTH ALAMEDA STREET COMPTON CAT090013352 (\$10)537-7100 Facility's Phone: 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 10. Containers 12 Unit 11. Total 13. Waste Codes and Packing Group (if any)) Quantity Wt./Vol. НМ NON RORA HAZARDOUS WASTE, LIQUID (OIL) 221 GENERATOR G DM14. Special Handling Instructions and Additional Information ERG#: 981. 171*** ER5W.O#70499 - KA ** 981) 928189DM-OIL AK SING BILL TO ENVIROSERY ** WEAR PROPER PPE 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Month Day Year Generator's/Offeror's Printed/Typed Name 16. International Shipments Export from U.S. Port of entry/exit: Import to U.S. Transporter signature (for exports only): Date leaving U.S.: 17. Transporter Acknowledgment of Receipt of Materials Day Year Transporter | Printed/Typed Name Signature Month 1011616 1 1 Transporter 2 Printed/Typed Name Signatur Month Discrepancy 18a. Discrepancy Indication Space Partial Rejection Residue Quantity Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone DESIGNATED 18c. Signature of Itemate Facility (or Generator) Month Day Year 19. Hazardous Waste 19port Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Printed/Typed Name Signature Day

•		

CAT OLD 52917 40-4 31-2

Job Description

Job Title: Environmental, Health, & Safety Director

Job Summary:

Responsible for implementation, maintenance, and oversight of the plant's Environmental Management System (EMS) to ensure plant compliance with Federal, State, and Local laws. Serves as plant liaison and official representative in maintaining a positive working relationship with EH&S agencies. Interacts with outside consultants, contractors, and regulatory agencies to ensure that the plant complies with applicable regulations.

Job Duties:

- > Interacts with Environmental Health & Safety Regulatory agencies (EH&S) and serves as plant's spokesperson with inspectors, explaining and providing information regarding plant's efforts to comply with required regulations.
- > Interacts with EH&S consultants in the performance of EH&S consulting activities at the facility to ensure there is adequate exchange of information in maintaining plant's environmental standards to minimize business risk.
- > Prepares internal and external EH&S documents and reports as required. Maintains required records and documentation.
- > Serves as plant's official representative at Hearings and Board meetings conducted by the regulatory agencies.
- > Conducts internal inspections and audits to maintain EH&S compliance on an ongoing basis.
- > Collects EH&S samples and submits them to an authorized testing laboratory for analysis. Reviews and interprets results of analysis and advises appropriate action to take if risk areas exist.
- > Maintains required EH&S reference materials. Keeps abreast of changing regulations. (Federal, State, and Local)
- > Develops outlines and conducts internal training of employees in appropriate EH&S areas.
- > Verifies and prepares EH&S shipping documents and manifests in accordance with regulatory requirements.

Education/Experience:

Education: Bachelor's degree in Engineering or in Environmental Studies

Experience: Plant experience working with environmental issues and/or technical knowledge of environmental regulations.

Maintenance

Pay Date

01/27/2011

Union Dues Taken

Location 020

	Description	Local	Name	Amount	Ssn	Clock#
N1	N1-LOCAL UN DUESR	1142	Battu,Michael D			•
	N1-LOCAL UN DUESR		Burns,Michael S			
	N1-LOCAL UN DUESR		Carero,Edward			
	N1-LOCAL UN DUESR		Carino,Enrique R			
	N1-LOCAL UN DUESR		Chew,Henry F			
	N1-LOCAL UN DUESR		Clark,Donald A			
	N1-LOCAL UN DUESR		Cobb,Philip R	[
	N1-LOCAL UN DUESR		Flentroy,Michael J	Ī		
	N1-LOCAL UN DUESR		Fong,Roland Y			
	N1-LOCAL UN DUESR		Gonzalez,Manuel V	Ī		
	N1-LOCAL UN DUESR		Gutierrez,Jesus A	Ī		
	N1-LOCAL UN DUESR		Hord,Philip K			
	N1-LOCAL UN DUESR		Lheureux, Michel			
	N1-LOCAL UN DUESR	7-7	Loomer, Joseph M	Ī		
	N1-LOCAL UN DUESR		Nietogomez, Michael A			
	N1-LOCAL UN DUESR		Nunez,Adolfo R	Ī		
	N1-LOCAL UN DUESR		Powell,Douglas J	Ī		
_	N1-LOCAL UN DUESR		Rull,Henry V	Ī		
	N1-LOCAL UN DUESR		Sanford,Degail Y	Ī		
	N1-LOCAL UN DUESR		Smith,Clyde S	1		
	N1-LOCAL UN DUESR		Strayer,David N	1		
	N1-LOCAL UN DUESR		Torres,Raymond R	1		
-	N1-LOCAL UN DUESR		Washington,Kirk D	1		
	N1-LOCAL UN DUESR		Zhou,Richard K			
		1142	Sum:			
N1			Sum:	175.34		
		Count All:	24		Count All:	24

Forming Operators

Pay Date

01/27/2011

Union Dues Taken

Location 020

	Description	Local	Name	Amount	Ssn	Clock#
N1	N1-LOCAL UN DUESR	2002	Adkins,Harold D			
	N1-LOCAL UN DUESR		Agbonavbare,Stephen G	Ī		
	N1-LOCAL UN DUESR		Alvarado,Rogelio	Ţ		
	N1-LOCAL UN DUESR		Arroyo,Salvador M	Ī		
	N1-LOCAL UN DUESR		Baldosano,Jose P	Ī		
	N1-LOCAL UN DUESR		Bettencourt,Lawrence J	Ţ		
	N1-LOCAL UN DUESR		Betts,Cole R	Ţ		
	N1-LOCAL UN DUESR		Burciaga,Julio A	I		
	N1-LOCAL UN DUESR		Burciaga,Servando	Ι		
	N1-LOCAL UN DUESR		Busier,Gilman R	Ι		
	N1-LOCAL UN DUESR		Cambra,Ricky A			
	N1-LOCAL UN DUESR		Carretero, Sergio			
	N1-LOCAL UN DUESR		Castro,Joel R			
	N1-LOCAL UN DUESR		Clement, Gregory			
	N1-LOCAL UN DUESR		Daliva,Roquelito V]		
	N1-LOCAL UN DUESR		Davis,Charles E			
	N1-LOCAL UN DUESR		Duckett,Andre C	<u> </u>		
	N1-LOCAL UN DUESR		Garrison, Kenneth J			
	N1-LOCAL UN DUESR		Hernandez Sr,Steve P			
	N1-LOCAL UN DUESR		Hill,Gregory O			
	N1-LOCAL UN DUESR	<u> </u>	Hunwick,Brian A			
	N1-LOCAL UN DUESR		Johnson,Lawrence M			
ļ	N1-LOCAL UN DUESR		Jones,Geronimo E			
	N1-LOCAL UN DUESR		Jones,Robert			
	N1-LOCAL UN DUESR		Lascano,Anthony	_		
	N1-LOCAL UN DUESR		Liles,Samuel L			
	N1-LOCAL UN DUESR		Miller,Gary T			
	N1-LOCAL UN DUESR		Moa Jr, Vaiolini			
	N1-LOCAL UN DUESR		Moa,Sosiua			
ļ	N1-LOCAL UN DUESR		Mojica,Renato A	<u> </u>		
	N1-LOCAL UN DUESR		Monarrez,Francisco	_		
	N1-LOCAL UN DUESR		Nevels, Walter L	-		
ļ	N1-LOCAL UN DUESR	_	Nunu,David	_		
	N1-LOCAL UN DUESR		Osborne, Nathel	_		
	N1-LOCAL UN DUESR		Quintero,Carlos H	_		
	N1-LOCAL UN DUESR		Reid,Daniel J	_		
	N1-LOCAL UN DUESR		Roberts, Joseph	•		
	N1-LOCAL UN DUESR		Roe,Thomas M	-		
<u> </u>	N1-LOCAL UN DUESR	ļ	Rojas,Mauro			
	N1-LOCAL UN DUESR	1	Ruth,James A			

		Count All:		51
N1				Sum:
·				
		2002		Sum:
	N1-LOCAL UN DUESR		Young, Nicholas A	
	N1-LOCAL UN DUESR		Williams,David K	
	N1-LOCAL UN DUESR		Waldron,Jim D	
	N1-LOCAL UN DUESR		Viveiros,Jose A	
	N1-LOCAL UN DUESR		Valencia, Carlos	
	N1-LOCAL UN DUESR		Valencia,Alejandro	
	N1-LOCAL UN DUESR		Torres,Refugio G	
	N1-LOCAL UN DUESR		Stewart, Jackie L	
	N1-LOCAL UN DUESR		Snow,Ronald	
	N1-LOCAL UN DUESR		Smith,Stephen	
	N1-LOCAL UN DUESR		Smith,Burl G	

î. •

CAT0006898 Port A 24-2

Proper handling and disposal of Oily Gloves and Rags

We must not throw away oily debris, rags and gloves in the trash.



This is wrong. It is against the law.

Oily debris, rags and gloves must be disposed of in the drums labeled with a Hazardous Waste label.



These hazardous waste drums must be kept closed when not in use.

We can recycle and reuse the oily gloves. They will be washed by a laundry service and returned to us.



The dirty gloves will be put into the containers labeled "Dirty Gloves".

From there they will be picked up by a laundry service, washed and returned to us for reuse.

Once the gloves are worn out they will be disposed of in the drums labeled with a Hazardous Waste label.



Place the worn out oily gloves in the drum and close lid.

Oily swabs will be disposed of in the drums labeled with a Hazardous Waste label.





We will cut the metal handle off the swabs and place the metal in the scrap metal container for recycling.

The hazardous waste drum for oily swab heads is to be closed by sliding the gate





Maml Clock # 2053 NewMan G Werethy Turner Joyce Cage 4496 C'HARles Davis 0349 ance Loomer Hargarila Philad Caba 4253 Tessie Pingol 4249 MINH TRUONG 3259 ROMULO CANCINO 4248 RAMÓN QRtegA 4272 SOCORED ARMENTA 3104 Emilia Mier 0350 Meleane Puly 4290 Virginia Conconles 2490 Coloria Amaya 2796 COURADO Amigiete 3024 2339 ALEXANDER BUTH John M. Thompson JONAR DAVID 2857 435/ 4344 REY Y/RAY SAMUEL CRANE 3366 RAYMOND TORRES 2236 MARIA NAVARRO 0345 Am Wavis 4008 Jarbara Love 3698 2719 estine Mc Jaco

4880

Clock # Name HUNG THU Ines Cartameda 0386 4384 WARLITO MINA 4261 ROMED RIVERA 0213 DianieSmith 0211 CONNIE BAUGHER 0262 Richard 2hou 2795 my 16/1 0632 3097 5143 Adela Mejia Linda Aniceta Esteln Felipe 515 232 2402 Nanul Albita 5046 Kamon Hernandez-700 Manual M. Alvarez H. 012712 5131 Lolita Cachola - 4270 PEARO ALVANEZ - 7010 Edilh lingson 3645 Maria Whin, 193 MARIA, A. Horaton 3365

Meeting Syn-in

Conne Nellower

Roland Fong

De Carino

HEARY V. RULL

Condo Dound

em ar Williams

De Gril San Ford

Name
ELOY ORTEGIA
AIBERTO ESPARZA
MICHAEL ZOBB
RICK STORY
OZEL Juhitworth
Victor Hammoyan

Clock #-7008 5156 5036 4554

7000

CEONARDO CAWIT REMATO A. MOSICA 388 PAUL KRY8120 411 Mauro Rojas 451 SAM HOLMES 2010 ROCKS MAUPIN 0796 MARIO LAMBARICH 0162 Slephen Agboonavbare Koul dage S Ma Ru 4238 1678 312

Allehall Flention 2756
Word Clark 507
Muchael S. Burns 673
Michael Leter Domes 3790
A. Javier-Chaucz 4398
Joe Loomer 1253
MIKE 32+TU 3736

202
1857

Wane Dollato V. Lucia Donnes Comin

CLOLK# 3/49 2-262 Name
RONALD SNOW

Jim Ruth

St. A. Bette

B. A. CHE/E

MISH SAMBAN

Samuel J. Lelas

Clock # 367 533 4/8 3355 17

•				
		ī		
			•	
	ı			
			.	

C47 200 62 62 Pro- 4 31-

ATMOSPHERIC STORAGE TANK INTERNAL / EXTERNAL & ULTRASONIC OUT-OF-SERVICE INSPECTION REPORT

OWENS-BROCKWAY

A-SUMP (USED OIL BIN)

OAKLAND FACILITY

OAKLAND, CA

DECEMBER 7, 2004



Prepared by:

HMT Inspection A Division of HMT Inc. 250 W. Channel Rd., Suite D Benicia, CA 94510 707.747.0444

INTRODUCTION

Owens-Brockway contracted with HMT Inspection, a division of HMT Inc. to provide inspection services for the A-Sump (Used Oil Bin). The tank is located at the Oakland facility in Oakland, CA.

This report documents the findings of the examinations performed on December 7, 2004 and provides an evaluation of the inspection results per the applicable criteria of API Standard 653.

Matthew K. Orr API 653 Aboveground Storage Tank Inspector Certification Number: 6158 Level II Technician

Mike Domralski Technician


SUITABILITY FOR SERVICE

A-Sump (Used Oil Bin) is suitable for service according to the applicable criteria of API Standard 653 if the following conditions are met:

1. The repair recommendations in Section 2.0 Summary and Repair Recommendations of this report have been implemented.

TABLE OF CONTENTS

1.0 DESCRIPTION.	5
2.0 SUMMARY AND REPAIR RECOMMENDATIONS	6
3.0 DRAWINGS	8 8
4.0 INSPECTION REPORT 4.1 FOUNDATION 4.1.1 FOUNDATION INSPECTION CHECKLIST 4.2 SHELL 4.2.1 SHELL INSPECTION CHECKLIST 4.3 NOZZLES AND APPURTENANCES 4.3.1 NOZZLE AND APPURTENANCE INSPECTION CHECKLIST 4.3.2 NOZZLE AND APPURTENANCE TABLE	9 10 10 11
5.0 NDE INSPECTION 5.1 NDE INSPECTION SCOPE 5.2 BOTTOM EXAMINATION 5.3 SHELL READINGS 5.4 NOZZLE READINGS	13 13
6.0 EQUIPMENT	14
7.0 TABLESTABLE A SHELL READINGS	
8.0 WARRANTY	16
9.0 PHOTOGRAPHS	17



1.0 DESCRIPTION

G	F	N	F	R	Δ	ı	•
•	_	14	_		_	_	٠

TANK NUMBER:	A-Sump (Used Oil Bins)
OWNER:	Owens-Brockway
DESIGN STANDARD:	No Data Available
TANK LOCATION:	Oakland, CA
MANUFACTURER:	No Data Available
PRODUCT:	Used Oil
CATHODIC PROTECTION:	No
DATA PLATE PRESENT:	No
DOT REGULATED TANK:	No

DIMENSIONS:

DIAMETER:	10'L x 6'W x 41-46" H
-----------	-----------------------

GEOMETRY:

FOUNDATION:	Concrete Floor
воттом:	Box Shaped Fillet Welded
	Construction
FIXED ROOF:	Grating Used As Cover

DATES:

YEAR BUILT:	No Data Available	
LAST COATED:	No Data Available	
LAST INSPECTION:	No Data Available	

COATINGS:

BOTTOM:	None
SHELL:	Silver Paint



2.0 SUMMARY AND REPAIR RECOMMENDATIONS

The following is a summary of the significant findings of the inspection.

FOUNDATION: Due to drainage issues during winter months, heavy presence of water/mud/debris collects around base of this tank since it is located in the basement level of this building. Detection of a possible leak from this tank would be difficult. (Reference Repair Recommendation 1).

Tank was constructed on staggered angle iron skids of varying heights to match sloped bottom detail. At this time the skids appear to be in acceptable condition where visible.

The tank does not appear to be anchored to the concrete foundation. It should be noted that standing water around the tank limited confirmation of an anchorage system. (Reference Repair Recommendation 2)

BOTTOM: The tank was in service and no bottom inspection was performed. One (1) thickness reading taken to verify bottom thickness (0.250 inch).

SHELL: Visual (VT) inspection of the external shell found that the coating system is weathered with random failures present (*Reference Repair Recommendation 3*).

Tank has two (2) 6-inch stiffening angles which are stitch welded around the shell. These stiffening angles appear to be in acceptable condition based on a limited visual evaluation due to cleanliness issues.

NOZZLES AND APPURTENANCES: A Visual (VT) inspection of the nozzles found that the coating system is weathered with random failures present (*Reference Repair Recommendation 4*).

All valves should be serviced during the next scheduled out of service period.

The tank currently does not have a high-level alarm (Reference Repair Recommendation 5).

FIXED ROOF: The tank utilizes a steel grating system to cover the top of the tank. The coating system of the steel grating has failed. (*Reference Repair Recommendation 6*).

ADDITIONAL COMMENTS: The next external API 653 inspection should be conducted within 5 years and no later than December 2009 (Ref. API 653, Para. 6.3.2.1).



HMT Inspection December 7, 2004 Page 7 of 21

REPAIR RECOMMENDATIONS


1)


The following is a summary of the repair recommendations.

addition, consideration should be given to installing a barrier around the tank to keep flooding issues to a minimum so that a proper visual inspection can be performed at all times Comments: 2) Consideration should be given to installing an anchorage system to account for possible seismic overturning loads. Comments: 3) Consideration should be given to cleaning and recoating the tank shell at this time. Comments: 4) Consideration should be given to cleaning and recoating the shell nozzle details at this time. Comments: 5) Consideration should be given to installing a high-level alarm system or alternative overfill protection device at the next out-of-service interval. Comments: 6) Consideration should be given to cleaning and recoating the steel grating cover detail at this time. Comments:

Consideration should be given to removing the debris around the tank and to

monitoring the ground to determine if the tank bottom is possibly leaking. In






4.0 INSPECTION REPORT

4.1 FOUNDATION

4.1.1 FOUNDATION INSPECTION CHECKLIST

/	#	DESCRIPTION	COMMENTS					
Y	1	Inspect foundation for damage. Reference Section 2.0						
Υ	2	Search for indications of bottom leakage.	Reference Section 2.0					
N	3	Inspect for cavities and vegetation under foundation.	N/A					
Y	4	Check for proper water runoff and drainage away from the tank.	Reference Section 2.0					
Y	5	Check for grade or other material covering the shell-to-bottom junction. Detail findings.	Acceptable					
N	6	Check for settlement around the perimeter of the tank.	N/A					
N	7	Check for presence or condition of moisture barrier.	N/A					
Y	8	Check for anchorage. Record sizes, spacing between anchors and condition.	Reference Section 2.0					



4.2 SHELL

4.2.1 SHELL INSPECTION CHECKLIST

I	#	DESCRIPTION	COMMENTS				
Y	1	Inspect external shell for coating failure, corrosion or leaks.	Reference Section 2.0				
Υ	2	Inspect external shell-to-bottom weld area for corrosion, defects, or thinning on weld, shell, or bottom.	Acceptable				
N	3	Inspect internal shell surface for corrosion or leaks.	N/A				
Y	4	Inspect weld seams for corrosion or defects. Visually inspect rivet joint details and record findings.	Fillet welded Acceptable				
N	5	Inspect wind girder for corrosion or damage.	Tank has stiffening system/ 6" angle Acceptable				
Υ	6	Check support welds to shell for corrosion or defects.	Acceptable				
N	7	Note whether supports have reinforcing pads welded to shell.	N/A				
N	8	Conduct Visual Inspection of shell insulation. Inspect for damage.	N/A				
N	9	Visually inspect shell for out-of-roundness.	N/A: Box shaped tank				
N	10	Shell mounted vents, Check for debris covering or condition of screens.	N/A				




4.3 NOZZLES AND APPURTENANCES

4.3.1 NOZZLE AND APPURTENANCE INSPECTION CHECKLIST

1	#	DESCRIPTION	COMMENTS					
Y	1	Inspect for signs of corrosion or other defects around all manways, nozzles, and attachments.	Reference Section 2.0					
N	2	Inspect for flange leaks and leaks around bolts.	N/A					
Υ	3	Check piping and valves for leaks, thermal relief, or signs of damage.	Acceptable					
N	4	Inspect condition of stairway ladder and platform	N/A					
N	5	Check welds on shell mounted davit clips above large valves or equipment.	N/A					
N	6	Describe and verify operability of gauging devices, if applicable.	N/A					
N	7	Inspect mixer for support, leakage, and defects.	N/A					
N	8	Check for adequate reinforcement around nozzles and appurtenances.	N/A					
N	9	Verify adequate weld spacing around nozzles and appurtenances.	N/A					
N	10	Check floating suction for damage and proper support. Check condition of shell mounted angle limiting brackets or angle limiting chains mounted to bottom	N/A					

					Reinforcing Plate									
Item	Description	Pipe Size (in.)	Station (ft.)	CL Elev. (in.)	Width (in.)	Height (in.)	Thick (in.)	Shape	Neck Thick (in.)	Fing Thick (in.)	Cover Thick (in.)	Tell- tale	Weld Space (in.)	Comments
Α	Nozzle (East side)	3.0	-	-	-	-	-	-	0.187	-		-	-	To oil skimmer
В	Nozzle (West side)	3.0	-	-	-	-	-	-	0.176	-	-	-	-	
С	Nozzle	4	-	-	_	-	-	-	0.196		_	-	•	Bottom drain
	The stations are measured circumferentially counterclockwise from Manway A.													

Shape



5.0 NDE INSPECTION

5.1 NDE INSPECTION SCOPE

The following Nondestructive Examinations (NDE) were conducted to evaluate the physical characteristics of the tank:

- A) Visual Inspection (VT) of areas for the detection of anomalies or significant internal metal loss which may affect the integrity. Performed in accordance with HMT Inspection VT Procedure No. 1611.4, Revision No. 1.
- B) Random UT readings on shell plates. Performed in accordance with HMT Inspection UT Procedure No. 1611.1, Revision No. 3.
- C) Random UT readings on shell nozzles. Performed in accordance with HMT Inspection UT Procedure No. 1611.1, Revision No. 3.

5.2 BOTTOM EXAMINATION

The external shell-to-bottom weld was examined utilizing VT inspection methods. There were no recordable indications.

5.3 SHELL READINGS

The tank shell plate UT data was collected utilizing random readings. Ten (10) readings were taken on the north and south sides and five (5) readings were taken on the east and west sides (Ref. Table A).

5.4 NOZZLE READINGS

The tank shell nozzle UT data was collected utilizing random readings. One (1) reading per nozzle was taken (Ref. Sections 4.4.2).



6.0 EQUIPMENT

6.1 ULTRASONIC

The UT equipment utilized for the inspection was a Krautkramer USN-52R Flaw Detector.


The transducer utilized was a KBA Model FH2E-WR, 7.5 MHz, 0.375 inch dual element and a Xactex CM-HR, 5.0 MHz, 0.250 inch single element.

The calibration block utilized was a 5 step, 4340 steel test block.

Echogel 20 was used as a couplant.

6.2 PIT GAUGE

The pit gauge utilized was a W.R. Thorpe Co. standard pipe pit gauge.



7.0 TABLES

TABLE A SHELL READINGS (in inches)

READING	SOUTH	WEST	NORTH	EAST
1	0.243	0.247	0.246	0.247
2	0.246	0.246	0.244	0.249
3	0.244	0.247	0.246	0.248
4	0.246	0.247	0.243	0.248
5	0.246	0.247	0.242	0.248
6	0.244	-	0.249	-
7	0.248	-	0.249	-
8	0.244	-	0.245	-
9	0.246	-	0.244	-
10	0.244	-	0.244	_



Page 16 of 21

8.0 WARRANTY

WARRANTY

HMT Inspection, a division of HMT Inc. has evaluated the condition of this tank based on the observations and measurements made by the HMT Inspection tank Inspector. While our evaluation accurately describes the condition of the tank at the time of inspection, the tank owner/operator must independently assess the inspection information/report provided by HMT Inspection and any conclusions reached by the tank owner/operator and any action taken or omitted to be taken are the sole responsibility of the owner/operator. With respect to inspection and testing, HMT Inspection warrants only that the services have been performed in accordance with accepted industry practice. If any such services fail to meet the foregoing warranty, HMT Inspection shall re-perform the service to the same extent and on the same conditions as the original service.


The preceding paragraph sets forth the exclusive remedy for claims based on failure or of defect in materials or services, whether such claim is made in contract or tort (including negligence) and however instituted, and, upon expiration of the warranty period, all such liability shall terminate. The foregoing warranty is exclusive and in lieu of all other warranties, whether written, oral, implied or statutory. NO IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR PURPOSE SHALL APPLY, nor shall HMT Inspection be liable for any loss or damage whatsoever by reason of its failure to discover, report, repair or modify latent defects or defects inherent in the design of any tank inspected. In no event, whether a result of breach of contract, warranty or tort (including negligence) shall HMT Inspection be liable for any consequential or incidental damages including, but not limited to, loss of profit or revenues, loss of use of equipment tested or services by HMT Inspection or any associated damage to facilities, down-time costs or claims of other damages.



Used Oil A Sump



Used Oil A Sump



Used Oil A Sump



Used Oil A Sump

9.0 PHOTOGRAPHS Page 18 of 21










Standing Water Under Sump

View Under Sump Tank







Stiffening Angle Detail



Grating On Sump Tank



Coating Condition









Drain Piping



ATMOSPHERIC STORAGE TANK
INTERNAL / EXTERNAL & ULTRASONIC
OUT-OF-SERVICE INSPECTION REPORT

07 12 512 512 7 70 - 2 34-2


OWENS-BROCKWAY

D-SUMP (USED OIL BIN)

OAKLAND FACILITY

OAKLAND, CA

DECEMBER 7, 2004



Prepared by:

HMT Inspection A Division of HMT Inc. 250 W. Channel Rd., Suite D Benicia, CA 94510 707.747.0444

INTRODUCTION

Owens-Brockway contracted with HMT Inspection, a division of HMT Inc. to provide inspection services for the D-Sump (Used Oil Bin). The tank is located at the Oakland facility in Oakland, CA.

This report documents the findings of the examinations performed on December 7, 2004 and provides an evaluation of the inspection results per the applicable criteria of API Standard 653.

Matthew K. Orr API 653 Aboveground Storage Tank Inspector Certification Number: 6158 Level II Technician

Mike Domralski Technician

SUITABILITY FOR SERVICE

D-Sump (Used Oil Bin) is suitable for service according to the applicable criteria of API Standard 653 if the following conditions are met:

1. The repair recommendations in Section 2.0 Summary and Repair Recommendations of this report have been implemented.

TABLE OF CONTENTS

1.0 DESCRIPTION	5
2.0 SUMMARY AND REPAIR RECOMMENDATIONS	6
3.0 DRAWINGS	9 9
4.0 INSPECTION REPORT 4.1 FOUNDATION 4.1.1 FOUNDATION INSPECTION CHECKLIST 4.2 SHELL 4.2.1 SHELL INSPECTION CHECKLIST 4.3 NOZZLES AND APPURTENANCES 4.3.1 NOZZLE AND APPURTENANCE INSPECTION CHECKLIST 4.3.2 NOZZLE AND APPURTENANCE TABLE	10 11 11 12
5.0 NDE INSPECTION 5.1 NDE INSPECTION SCOPE 5.2 BOTTOM EXAMINATION 5.3 SHELL READINGS 5.4 NOZZLE READINGS	14 14 14
6.0 EQUIPMENT	15
7.0 TABLES	
8.0 WARRANTY	17
9.0 PHOTOGRAPHS	18



HMT Inspection December 7, 2004 Page 5 of 22

1.0 DESCRIPTION

GI	EΝ	EF	₹А	L:
----	----	----	----	----

TANK NUMBER:	D-Sump (Used Oil Bin)
OWNER:	Owens-Brockway
DESIGN STANDARD:	No Data Available
TANK LOCATION:	Oakland, CA
MANUFACTURER:	No Data Available
PRODUCT:	Used Oil
CATHODIC PROTECTION:	No
DATA PLATE PRESENT:	No
DOT REGULATED TANK:	No

DIMENSIONS:

DIAMETER:	 10'L	x 6'W x	41-46"	Н	

GEOMETRY:

FOUNDATION:	Concrete Floor
BOTTOM:	Box Shaped Fillet Welded
	Construction
FIXED ROOF:	Grating Used As Cover

DATES:

YEAR BUILT:	No Data Available
LAST COATED:	No Data Available
LAST INSPECTION:	No Data Available

COATINGS:

BOTTOM:	None
SHELL:	Silver Paint



2.0 SUMMARY AND REPAIR RECOMMENDATIONS

The following is a summary of the significant findings of the inspection.

FOUNDATION: Due to drainage issues during winter months, heavy presence of water/mud/debris collects around base of this tank since it is located in the basement level of this building. Detection of a possible leak from this tank would be difficult. (*Reference Repair Recommendation 1*).

Tank was constructed on staggered angle iron skids of varying heights to match sloped bottom detail. At this time the skids appear to be in acceptable condition where visible.

The tank does not appear to be anchored to the concrete foundation. It should be noted that standing water around the tank limited confirmation of an anchorage system. (Reference Repair Recommendation 2)

BOTTOM: The tank was in service and no bottom inspection was performed. One (1) thickness reading taken to verify bottom thickness (0.250 inch).

SHELL: Visual (VT) inspection of the external shell found that the coating system is weathered with random failures present (*Reference Repair Recommendation 3*).


Tank has two (2) 6-inch stiffening angles which are stitch welded around the shell. These stiffening angles appear to be in acceptable condition based on a limited visual evaluation due to cleanliness issues.

NOZZLES AND APPURTENANCES: A Visual (VT) inspection of the nozzles found that the coating system is weathered with random failures present (*Reference Repair Recommendation 4*).

All three (3) shell nozzles have threaded connections (Reference Repair Recommendation 5).

All valves should be serviced during the next scheduled out of service period.

The tank currently does not have a high-level alarm (Reference Repair Recommendation 6).



SUMMARY OF SIGNIFICANT FINDINGS (Continued)

FIXED ROOF: The tank utilizes a steel grating system to cover the top of the tank. The coating system of the steel grating has failed. (*Reference Repair Recommendation 7*).

ADDITIONAL COMMENTS: The next external API 653 inspection should be conducted within 5 years and no later than December 2009 (Ref. API 653, Para. 6.3.2.1).



HMT Inspection

December 7, 2004 Page 8 of 22

REPAIR RECOMMENDATIONS


1)


The following is a summary of the repair recommendations.

monitoring the ground to determine if the tank bottom is possibly leaking. In addition, consideration should be given to installing a barrier around the tank to keep flooding issues to a minimum so that a proper visual inspection can be performed at all times Comments: Consideration should be given to installing an anchorage system to account for 2) possible seismic overturning loads. Comments: Consideration should be given to cleaning and recoating the tank shell at this 3) time. Comments: Consideration should be given to cleaning and recoating the shell nozzle details 4) at this time. Comments: Consideration should be given to replacing these nozzles with new API flanged 5) nozzle details the next time the tank is taken out of service. Comments: Consideration should be given to installing a high-level alarm system or 6) alternative overfill protection device at the next out-of-service interval. Comments: 7) Consideration should be given to cleaning and recoating the steel grating cover detail at this time.

Consideration should be given to removing the debris around the tank and to

Comments:






4.0 INSPECTION REPORT

4.1 FOUNDATION

4.1.1 FOUNDATION INSPECTION CHECKLIST

	#	DESCRIPTION	COMMENTS
Υ	1	Inspect foundation for damage.	Reference Section 2.0
Υ	2	Search for indications of bottom leakage.	Reference Section 2.0
N	3	Inspect for cavities and vegetation under foundation.	N/A
Υ	4	Check for proper water runoff and drainage away from the tank.	Reference Section 2.0
Y	5	Check for grade or other material covering the shell-to-bottom junction. Detail findings.	Acceptable
N	6	Check for settlement around the perimeter of the tank.	N/A
N	7	Check for presence or condition of moisture barrier.	N/A
Y	8	Check for anchorage. Record sizes, spacing between anchors and condition.	Reference Section 2.0



4.2 SHELL

4.2.1 SHELL INSPECTION CHECKLIST

I	#	DESCRIPTION	COMMENTS					
Υ	1	Inspect external shell for coating failure, corrosion or leaks.	Reference Section 2.0					
Y	2	Inspect external shell-to-bottom weld area for corrosion, defects, or thinning on weld, shell, or bottom.	Acceptable					
N	3	Inspect internal shell surface for corrosion or N/A leaks.						
Y	4	Inspect weld seams for corrosion or defects. Visually inspect rivet joint details and record findings.	Fillet welded Acceptable					
N	5	Inspect wind girder for corrosion or damage.	Tank has stiffening system/ 6" angle Acceptable					
Υ	6	Check support welds to shell for corrosion or defects.	Acceptable					
N	7	Note whether supports have reinforcing pads welded to shell.	N/A					
N	8	Conduct Visual Inspection of shell insulation. Inspect for damage.	N/A					
N	9	Visually inspect shell for out-of-roundness.	N/A: Box shaped tank					
N	10	Shell mounted vents, Check for debris covering or condition of screens.	N/A					



4.3 NOZZLES AND APPURTENANCES

4.3.1 NOZZLE AND APPURTENANCE INSPECTION CHECKLIST

	#	DESCRIPTION	COMMENTS
Y	1	Inspect for signs of corrosion or other defects around all manways, nozzles, and attachments.	Reference Section 2.0
N	2	Inspect for flange leaks and leaks around bolts.	N/A
Υ	3	Check piping and valves for leaks, thermal relief, or signs of damage.	Acceptable
N	4	Inspect condition of stairway ladder and platform	N/A
N	5	Check welds on shell mounted davit clips above large valves or equipment.	N/A
N	6	Describe and verify operability of gauging devices, if applicable.	N/A
N	7	Inspect mixer for support, leakage, and defects.	N/A
N	8	Check for adequate reinforcement around nozzles and appurtenances.	N/A
N	9	Verify adequate weld spacing around nozzles and appurtenances.	N/A
N	10	Check floating suction for damage and proper support. Check condition of shell mounted angle limiting brackets or angle limiting chains mounted to bottom	N/A

						Reinforcing I	Plate							
Item	Description	Pipe Size (in.)	Station (ft.)	CL Elev. (in.)	Width (in.)	Height (in.)	Thick (in.)	Shape	Neck Thick (in.)	Fing Thick (in.)	Cover Thick (in.)	Tell- tale	Weld Space (in.)	Comments
Α	Nozzle (East side)	3.0	-	-	-	-		-	0.202	-		-	-	To oil skimmer
В	Nozzle (West side)	3.0	-	-	-	-	-	-	0.194	-	-	-		
С	Nozzle	3.0	-	_	-	-	-	-	0.177		•		-	Bottom drain
	The stations are measured circumferentially counterclockwise from Manway A.													

Shape



5.0 NDE INSPECTION

5.1 NDE INSPECTION SCOPE

The following Nondestructive Examinations (NDE) were conducted to evaluate the physical characteristics of the tank:

- A) Visual Inspection (VT) of areas for the detection of anomalies or significant internal metal loss which may affect the integrity. Performed in accordance with HMT Inspection VT Procedure No. 1611.4, Revision No. 1.
- B) Random UT readings on shell plates. Performed in accordance with HMT Inspection UT Procedure No. 1611.1, Revision No. 3.
- C) Random UT readings on shell nozzles. Performed in accordance with HMT Inspection UT Procedure No. 1611.1, Revision No. 3.

5.2 BOTTOM EXAMINATION

The external shell-to-bottom weld was examined utilizing VT inspection methods. There were no recordable indications.

5.3 SHELL READINGS

The tank shell plate UT data was collected utilizing random readings. Ten (10) readings were taken on the north and south sides and five (5) readings were taken on the east and west sides (Ref. Table A).

5.4 NOZZLE READINGS

The tank shell nozzle UT data was collected utilizing random readings. One (1) reading per nozzle was taken (Ref. Sections 4.4.2).



6.0 EQUIPMENT

6.1 ULTRASONIC

The UT equipment utilized for the inspection was a Krautkramer USN-52R Flaw Detector.

The transducer utilized was a KBA Model FH2E-WR, 7.5 MHz, 0.375 inch dual element and a Xactex CM-HR, 5.0 MHz, 0.250 inch single element.


The calibration block utilized was a 5 step, 4340 steel test block.

Echogel 20 was used as a couplant.

6.2 PIT GAUGE

The pit gauge utilized was a W.R. Thorpe Co. standard pipe pit gauge.

Oakland, CA



7.0 TABLES

TABLE A SHELL READINGS

(in inches)

READING	SOUTH	WEST	NORTH	EAST
1	0.244	0.246	0.248	0.248
2	0.240	0.246	0.248	0.246
3	0.243	0.241	0.245	0.246
4	0.245	0.240	0.249	0.245
5	0.245	0.240	0.246	0.245
6	0.246	-	0.246	-
7	0.247	-	0.244	-
8	0.247	-	0.244	-
9	0.241	-	0.244	-
10	0.244	-	0.247	-



8.0 WARRANTY

WARRANTY

HMT Inspection, a division of HMT Inc. has evaluated the condition of this tank based on the observations and measurements made by the HMT Inspection tank Inspector. While our evaluation accurately describes the condition of the tank at the time of inspection, the tank owner/operator must independently assess the inspection information/report provided by HMT Inspection and any conclusions reached by the tank owner/operator and any action taken or omitted to be taken are the sole responsibility of the owner/operator. With respect to inspection and testing, HMT Inspection warrants only that the services have been performed in accordance with accepted industry practice. If any such services fail to meet the foregoing warranty, HMT Inspection shall re-perform the service to the same extent and on the same conditions as the original service.

The preceding paragraph sets forth the exclusive remedy for claims based on failure or of defect in materials or services, whether such claim is made in contract or tort (including negligence) and however instituted, and, upon expiration of the warranty period, all such liability shall terminate. The foregoing warranty is exclusive and in lieu of all other warranties, whether written, oral, implied or statutory. NO IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR PURPOSE SHALL APPLY, nor shall HMT Inspection be liable for any loss or damage whatsoever by reason of its failure to discover, report, repair or modify latent defects or defects inherent in the design of any tank inspected. In no event, whether a result of breach of contract, warranty or tort (including negligence) shall HMT Inspection be liable for any consequential or incidental damages including, but not limited to, loss of profit or revenues, loss of use of equipment tested or services by HMT Inspection or any associated damage to facilities, down-time costs or claims of other damages.

9.0 PHOTOGRAPHS Page 18 of 22









Used Oil D Sump

Used Oil D Sump









Top View of Grating

Top View of Grating

9.0 PHOTOGRAPHS



Top View of Grating



Top Angle Around Sump



Stiffening Angle Around Sump



Product Piping





View of Internal Components



View of Internal Components







House Keeping Issues

INSPECTION REPORT FOR DTSC COMPLIANCE

OWENS-BROCKWAY
WASTE/USED OIL TANK
OAKLAND PLANT
OAKLAND, CA
DECEMBER 7, 2004



Prepared by:

HMT Inspection A Division of HMT Inc. 250 W. Channel Rd., Suite D Benicia, CA 94510 (707) 747-0444

INTRODUCTION

Owens-Brockway contracted with HMT Inspection, a division of HMT Inc. The purpose of the contract was to provide inspection services for the Waste/Used Oil Tank. The tank is located at the Oakland Plant in Oakland, CA.

On December 7, 2004 HMT Inspection performed an external visual In-Service assessment to confirm the current status of the Waste/Used Oil tank and associated piping connected with this tank at your plant in Oakland, CA.

It should be noted that the terms "tank" and "containment area" are used in this document as defined in CA DTSC regulations.

HMT Inspection provided the following personnel:

Nelson Acosta, P.E. API 653 Certified Tank Inspector Certification Number: 0272 California Registered Professional Engineer No. C57820 (Civil)

Matthew K. Orr API 653 Certified Tank Inspector Certification Number: 6158 API 570 Certified Piping Inspector Certification Number 23186 Level II Technician

Mike Domrzalski Technician

SUITABILITY FOR SERVICE STATEMENT

The Waste/Used Oil Tank is suitable for service according to the applicable criteria of API Standard 653.

The Waste/Used Oil Tank has also been evaluated for compliance with California Dept. of Toxic Substances Control (DTSC) regulations regarding the storage of hazardous waste and was found to be acceptable per the requirements of Title 22, Division 4.5, Chapter 14, Article 10, Para. 66265.192 as amended. This assessment will be valid for a period not exceeding one (1) year from the date given above or until the next external inspection and assessment if done prior to the end of that period

Certification per Title 22, Section 66270.11

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

Nelson J. Acosta, P.E.	Date

Hazardous Waste Systems Integrity Report for

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 4 of 28

TABLE OF CONTENTS

1.0 DESCRIPTION	5
2.0 SUMMARY AND REPAIR RECOMMENDATIONS	6
3.0 SUITABILITY FOR SERVICE	8
4.0 DRAWINGS	13
5.0 INSPECTION CHECKLIST	
6.0 NDE INSPECTION	17 17
7.0 EQUIPMENT	18 18
8.0 TABLES TABLE A SHELL READINGS TABLE B HEAD READINGS	19
9.0 WARRANTY	21
9.0 PHOTOGRAPHS	22

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank

Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 5 of 28

1.0 DESCRIPTION

GENERAL:

DATE OF INSPECTION:	December 7, 2004	
OWNER:	Owens-Brockway	
DESIGN STANDARD:	Underwriters Laboratories Inc. (UL)	
VESSEL LOCATION:	Oakland, CA	
MANUFACTURER:	N.J. McCutchen Inc.	
MATERIALS:	Carbon Steel	
HEADS:	Carbon Steel	
SHELL:	Carbon Steel	
SERVICE / PROCESS:	Waste/Used Oil	
NAME PLATE DATA:	Yes	
MFG. S/N:	No Data Available	

DIMENSIONS:

INSIDE DIAMETER:	6.25 ft.
TANGENT LENGHT/HEIGHT	17.0 ft.
NOMINAL SHELL THICKNESS:	0.187 in.
NOMINAL HEAD THICKNESS:	0.187 in.

GEOMETRY:

FOUNDATION:	Concrete Saddles (2) on Concrete Slab			
VESSEL ORIENTATION:	Horizontal			
HEAD TYPE:	Carbon Steel			
CIRCUMFERENTIAL WELDS:	Butt Welded			
LONGITUDINAL WELDS:	Butt Welded			

DATES:

YEAR BUILT:	1986	
LAST COATED:	No Data Available	
LAST INSPECTION:	No Data Available	

ACCESS:

STAIRWAY: Ladder			 			
	İ	STAIRWAY:	 Ladder			

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



Dec. 7, 2004 Page 6 of 28

2.0 SUMMARY AND REPAIR RECOMMENDATIONS

The following is a summary of the significant findings of the inspection.

Inspection of the Waste/Used Oil tank at the Oakland plant did not reveal any areas of significant metal loss, defects, or anomalies that would require immediate corrective action at this time. Reference Section 4.0 for physical description, diagram and containment area layouts of the tank inspected.

FOUNDATION: Due to recent heavy rains, there is 4 inches of standing water inside the containment wall. In addition, there is debris with miscellaneous equipment such as hoses and plastic piping present. The water should be removed and the containment area not used for storage for miscellaneous plant equipment.

The tank rests on concrete saddles that are in acceptable condition at this time.

SHELL: Visual (VT) inspection of the external shell found the coating to be weathered with areas of random failure present. Consideration should be given to cleaning and recoating the tank shell at this time.

Ultrasonic (UT) thickness data was collected at random locations. No areas of significant metal loss were detected. Reference Section 8.0 for Ultrasonic (UT) data. No internal Visual (VT) inspection was performed at this time since the tank was in service.

NOZZLES AND APPURTENANCES: Visual (VT) inspection of the nozzles found that the coating is weathered with areas of random failure present. Consideration should be given to cleaning and re-coating the nozzles at this time.

All shell nozzles have threaded connections with product stains present at some. Consideration should be given to replacing these nozzles with new API flanged nozzle details the next time the tank is taken out of service

The existing float system utilizes a 1-inch diameter hole in the top of the tank in lieu of a standard coupling or nozzle detail. Consideration should be given to replacing this detail with a new API flanged nozzle the next time the tank is taken out of service

All valves should be serviced during the next scheduled out-of-service period.

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



Dec. 7, 2004 Page 7 of 28

SUMMARY AND REPAIR RECOMMENDATIONS (Continued)

NOZZLES AND APPURTENANCES: The tank currently does not have a high-level alarm. Consideration should be given to installing a high-level alarm system or alternative overfill protection device at the next out-of-service interval.

SECONDARY CONTAINMENT EVALUATION: The original existing secondary containment details included a 31-inch high by 23.75-foot long by 9.33-foot wide concrete wall and these details were inadequate for the capacity of the tank. Also, deterioration of the concrete was such that it warranted repair. The height of the existing containment wall was increased to 48 inches to comply with the inadequate containment volume. In addition, the cold joints need to be sealed or the entire containment area coated to comply with existing DTSC requirements for secondary containment details.

ADDITIONAL COMMENTS: The next external API 653 inspection should be conducted within 5 years and no later than December 2009 (ref. API 653, Para. 6.3.2.1).

Hazardous Waste Systems Integrity Report for Owens-Brockway

Waste/Used Oil Storage Tank Oakland, CA



Page 8 of 28

3.0 SUITABILITY FOR SERVICE

Evaluation for DTSC Compliance

The results of our limited In-Service external inspection indicates that the current condition of this tank is acceptable for continued service for a period of one (1) year based on the fact that a new secondary containment wall has been installed.

We have evaluated this tank, connecting piping and surrounding area in accordance with the specified requirements of California Dept. of Toxic Substances Control Regulations 66265.190 through 66265.200 (as applicable) and find the following to be true:

- Pursuant to 66265.191 (a)(1), this structure now contains and will continue to contain for the foreseeable future products that can be classified as liquids falling within the CA DTSC regulations:
- Pursuant to 66265.191 (a)(1)(A) and (B), this structure is of sufficient capacity as to not be exempt from this regulation;
- Pursuant to 66265.191(b)(5)(B), the concrete containment floor under this tank has also been adequately designed to ACI 318 criteria and has sufficient wall thickness. structural strength and product compatibility to store this liquid on a long-term basis without collapse, rupture or failure:
- Pursuant to 66265.191(e)(1), the tank has secondary containment details that meet the requirements of 66265.193; It should be noted that a new secondary containment detail was installed after this visual inspection was performed. Confirmation that the containment is lined with a coating that makes these surfaces sufficiently impervious to leaks and spills and that has acceptable product compatibility to store this RCRA hazardous waste until such leaks or spills are detected and removed was not possible at this inspection.

Hazardous Waste Systems Integrity Report for

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 9 of 28

SUITABILITY FOR SERVICE (Continued)

Waste/Used Oil Storage Tank

(b)(1) The tank is designed and manufactured to Underwriters Laboratories (UL) criteria. This tank has been adequately designed according to accepted industry practice for a horizontal storage tank and has sufficient structural strength and product compatibility to store RCRA hazardous wastes on a long-term basis without collapse, rupture or failure. This tank now contains and will continue to contain for the foreseeable future products that can be classified as RCRA hazardous wastes:

(b)(2) The tank is constructed of carbon steel and is compatible with the intended hazardous waste product storage.

Material thickness for shell and heads:

Shell = 0.187 inch

(from ultrasonic thickness (UT) collection)

Heads = 0.187 inch

- (b)(3) This tank is above ground and not in direct contact with soil or groundwater on a continuous or consistent basis, therefore this requirement is not applicable.
- (b)(3)(A)(1) through (8) This tank is not in contact with soil and these requirements are not applicable.
- (b)(3)(B)(1) through (3) This tank is not in direct contact with soil or water and is constructed of coated carbon steel material.
- (b)(4) This tank is above ground, not underground, and within a separate containment area not accessible to vehicular or other plant traffic on an uncontrolled basis, therefore this requirement is not applicable.
- (b)(5)(A) Currently installed foundation details include a full concrete slab with concrete saddles adequate to support the loading imposed by the stored waste oil in this tank.
- (b)(5)(B) The tank rests on two (2) separate concrete saddle supports. These saddles are raised above the level of the containment floor and are not subject to external liquid loads that might result in flotation when empty or nearly so.
- (b)(5)(C) Since this tank is not in direct contact with the ground and is in a location not subject to extended low temperatures in winter weather, they are not subject to frost heave and this requirement is not applicable.

Hazardous Waste Systems Integrity Report for Owens-Brockway

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 10 of 28

SUITABILITY FOR SERVICE (Continued)

- (b)(6) The tank configuration is horizontal and cylindrical with major outside dimensions of 17.0 ft. in length x 6.25 ft. in diameter and has a working capacity of approximately 3,900 gallons (tank is not operated completely full). Secondary containment to prevent leakage into the ground is provided by a suitably sized concrete containment wall. Verification of suitable coating applied over the floor and walls (i.e. cold joints) of the concrete containment area was not possible during this inspection.
- (c)(1) through (6) The condition of this tank at the time of inspection was such that there are no structural integrity issues (no cracks, corrosion, punctures) visible
- and no installation issues evident (no obvious tank construction defects) that

result in possible leaks from the tank. The current condition of the tank walls and heads indicates no leaks when full of product.

- (d) This tank is above ground and this backfill requirement is not applicable.
- (e) This tank was visually and ultrasonically tested for leak integrity and no leaks were detected.
- (f) There is no permanent ancillary equipment within the containment area associated with the operation of this tank, therefore, this requirement is not applicable.
- (g) This tank is constructed of coated carbon steel material that is compatible with the stored waste oil and does not require further independent corrosion protection.
- (h) This report includes the appropriate certification statement required under Section 66270.11(d) on the Suitability for Service Statement page at the beginning of this report.

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank

Oakland, CA



Dec. 7, 2004 Page 11 of 28

SUITABILITY FOR SERVICE (Continued)

Waste/Used Oil Tank Storage Area

- Pursuant to 66265.175(a), this containment area has now and will continue to contain for the foreseeable future wastes that can be classified as RCRA hazardous wastes;
- Pursuant to 66265.175(b), the following assessment details are known or have been evaluated:
- (b)(1), the containment area has been adequately designed to ACI 318-77 design requirements. Confirmation that the containment is lined with a coating that makes these surfaces sufficiently impervious to leaks and spills and that has acceptable product compatibility to store this RCRA hazardous waste until such leaks or spills are detected and removed was not possible during this inspection;
- (b)(2), the containment floor has a concrete wall surrounding it on all 4 sides (now approximately 48 inches high) and the waste storage tank is of carbon steel construction stored up off the containment floor on concrete saddles to avoid direct contact with any spills or liquid accumulations;
- (b)(3) This tank storage area is exposed to the weather, therefore, this area is subject to the 24-hour, 25-year storm (7.0 in. of rain for this location) plus 10% of the aggregate volume of the storage therein and meets this volume requirement based on the area contained and height of the walls (886.35 cu. ft. available volume vs. 650.85 cu. ft. minimum volume required);
- (b)(4) Currently installed details include a full concrete slab foundation with a concrete wall on all 4 sides. There is full exposure to normal weathering environment and no run-on liquid collection is possible into the area with this arrangement:
- (b)(5) The hazardous waste area inspection plan currently in place provide for any leakage or spills from the tanks in this area to be cleaned up as soon as detected (visual inspection of this area is performed on a daily basis).
- (c) This report meets the requirements of 66265.175 (c).
- Pursuant to 66265.175(d), this requirement is not applicable as there are free liquids present in the tanks in this area.
- Pursuant to 66265.175(e), this requirement is not applicable as there are free liquids present in the tanks in this area.

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 12 of 28

SUITABILITY FOR SERVICE (Continued)


Waste/Used Oil Tank Storage Area (cont'd.)

There is no waste treatment performed in this containment area where the waste materials are stored. No concern is attached to this storage arrangement under the conditions seen at the site and as described further herein.

We believe that the above information provides the assessment of Owens-Brockway Waste/used Oil Tank Storage Area at Oakland, CA that is required by California DTSC requirements for structures containing RCRA hazardous wastes. This report is intended to provide adequate documentation for that purpose.

Based on information provided by Owens-Brockway, no chemical reactions or subsequent temperature rise from such reactions are anticipated. Thermal cycling of tank contents is possible due to changes in ambient air temperatures and direct exposure to sunlight. These factors may raise the temperature of the waste stream a small amount (on the order of 5 to 10 °F or less) but this heat would be dissipated very quickly in this volume of stored liquid. No concern is attached to this part of the process regarding performance of the tank.

- Pursuant to 66265.192, these requirements are applicable since all systems inspected exist and have been in service.
- Pursuant to 66265.193, the tank does currently comply with the requirements for secondary containment details as outlined in this regulation. The associated piping outside the confines of the containment building does not have secondary containment.
- Pursuant to 66265.194, the tank has sufficient excess capacity during normal operations.
- Compliance with, or input regarding applicability or method of compliance in the future, for regulations 66265.195 through 66265.200 will be supplied directly by Owens Brockway as appropriate in the regulatory review process.



Hazardous Waste Systems Integrity Report for

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 15 of 28

5.0 INSPECTION CHECKLIST

/		DESCRIPTION	COMMENTS
Υ	1.	Inspect foundation for damage.	Saddles – Acceptable Containment Wall - Reference Section 2.0
Υ	2.	Search for indications of leakage.	None found, Acceptable
Υ	3.	Inspect for cavities and vegetation around foundation	Acceptable
Y	4.	Check for proper water runoff and drainage away from the foundation.	4 in. of standing water inside containment with debris present (hoses; garbage; plastic piping, etc.)
Y	5.	Check for settlement around the foundation for the vessel.	Visual – Acceptable
N	6.	Inspect vessel skirt and anchor bolts (if present).	
Υ	7.	Inspect for coating failure, pitting and corrosion.	Coating weathered with random failure
Y	8.	Visually inspect entire vessel surface (shell and heads) for leaks or corrosion.	Acceptable
N	9.	Inspect vessel insulation (if present) note condition and damage (if any)	N/A
Y	10.	Check support welds to vessel for corrosion or defects.	Ladder attachments/ misc. pump stands – Acceptable
Y	11.	Visually inspect entire vessel (shell and heads) for bulges or deformation.	Acceptable
Υ	12.	Check piping, valves flanges and bolting for leaks or signs of damage.	Item C product stains @ threaded connections. Float system has 1 in. dia. hole in top of vessel.
Y	13.	Inspect for signs of corrosion or other defects around all manways, nozzles, and attachments.	Reference Section 2.0
Υ	14.	Inspect all pressure relieving devices and record data on vessel nozzle table.	Acceptable
N	15.	Conduct Ultrasonic Thickness readings of entire vessel (shell and heads). Record all data.	Reference Section 8.0, Tables A & B for UT readings
Υ	16.	Inspect vessel access structures, ladders, stairway cages and handrails.	Acceptable

Hazardous Waste Systems Integrity Report for

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 16 of 28

5.1 TANK NOZZLE TABLE

item	Description	Pipe Size (in.)	Location	Neck Thick (in.)	Comments
Α	Nozzie	4.0	Top North	-	threaded/ capped
В	Nozzle	4.0	Top North	-	threaded/plugged
С	Nozzle	4.0	Top North	-	threaded
D	Gauge Float	1.0 (Hole)	Top Center	-	0.250 in. shaft attached to mechanical gauge
Е	Manway	20.0	Top Center	0.240	flange = 0.370 in. cover = 0.246 in.
F	Nozzle	4.0	Top South	-	threaded
G	Nozzle	4.0	Top South	-	Out of service/ threaded
Н	Nozzle	4.0	Top South		with 2.5 in. coupling – capped/threaded

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



Dec. 7, 2004 Page 17 of 28

6.0 NDE INSPECTION

6.1 NDE INSPECTION SCOPE

The following Nondestructive Examinations (NDE) were conducted to evaluate the physical characteristics of the tank:

- A) Visual Inspection (VT) of all accessible areas for the detection of anomalies or significant defects that may affect the tank integrity.
- B) Random UT thickness readings on the tank shell for the detection of significant internal metal loss. Performed in accordance with HMT UT Procedure No. 1611.1, Revision No. 1.

Hazardous Waste Systems Integrity Report for Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 18 of 28

7.0 EQUIPMENT

7.1 ULTRASONIC

The UT equipment utilized for the inspection was a Krautkramer USN-52R Flaw Detector.

The transducer utilized was a KBA Model FH2E-WR, 7.5 MHz, 0.375 inch dual element and a Xactex CM-HR, 5.0 MHz, 0.250 inch single element.

Ultragel and water were used as a couplant.

The calibration block utilized was a 5 step, 4340 steel test block.

Hazardous Waste Systems Integrity Report for

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 19 of 28

8.0 TABLES

TABLE A SHELL READINGS

(in inches)

READING	EAST	BOTTOM	WEST	TOP
1	0.156	0.183	0.179	0.182
2	0.176	0.164	0.181	0.185
3	0.162	0.185	0.181	0.185
4	0.164	0.156	0.181	0.182
5	0.162	0.159	0.171	0.181
6	0.153	0.160	0.154	0.185
7	0.179	0.159	0.161	0.183
8	0.180	0.176	0.181	0.183
9	0.181	0.180	0.179	0.185
10	0.181	0.156	0.180	0.185

Hazardous Waste Systems Integrity Report for

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 20 of 28

TABLE B HEAD READINGS (in inches)

Tank Head readings were taken in a X-pattern along north to south and east to west lines.

NORTH HEAD

Location	READING
1	0.191
2	0.192
3	0.189
4	0.172
5	0.191
6	0.193
7	0.189
8	0.187
9	0.190
10	0.190

SOUTH HEAD

Location	READING
1	0.196
2	0.194
3	0.194
4	0.176
5	0.192
6	0.169
7	0.174
8	0.172
9	0.196
10	0.196

Hazardous Waste Systems Integrity Report for Owens-Brockway

Owens-Brockway Waste/Used Oil Storage Tank Oakland, CA



HMT Inspection

Dec. 7, 2004 Page 21 of 28

9.0 WARRANTY


WARRANTY

HMT Inspection, a division of HMT Inc. has evaluated the condition of this tank based on the observations and measurements made by the HMT Inspection Tank Inspector. While our evaluation accurately describes the condition of the tank at the time of inspection, the tank owner/operator must independently assess the inspection information/report provided by HMT Inspection and any conclusions reached by the tank owner/operator and any action taken or omitted to be taken are the sole responsibility of the owner/operator. With respect to inspection and testing, HMT Inspection warrants only that the services have been performed in accordance with accepted industry practice. If any such services fail to meet the foregoing warranty, HMT Inspection shall re-perform the service to the same extent and on the same conditions as the original service.

The preceding paragraph sets forth the exclusive remedy for claims based on failure or of defect in materials or services, whether such claim is made in contract or tort (including negligence) and however instituted, and, upon expiration of the warranty period, all such liability shall terminate. The foregoing warranty is exclusive and in lieu of all other warranties, whether written, oral, implied or statutory. NO IMPLIED WARRANTY OF MERCHANTABILITY OR FITNESS FOR PURPOSE SHALL APPLY, nor shall HMT Inspection be liable for any loss or damage whatsoever by reason of its failure to discover, report, repair or modify latent defects or defects inherent in the design of any tank inspected. In no event, whether a result of breach of contract, warranty or tort (including negligence) shall HMT Inspection be liable for any consequential or incidental damages including, but not limited to, loss of profit or revenues, loss of use of equipment tested or services by HMT Inspection or any associated damage to facilities, down-time costs or claims of other damages.









Used Oil Tank Standoff







Containment Wall



Data Plate



Condition Of Containment Wall

9.0 PHOTOGRAPHS



Foundation Saddle



Foundation Saddle



Foundation Saddle



Saddle Gasket

9.0 PHOTOGRAPHS



Saddle Gasket





Nozzles A & B



Hole In Tank For Float System







Nozzles G & H



Water Outlet to Oil Skimmer



Nozzle G Piping

9.0 PHOTOGRAPHS



Ladder Detail



Debris & Equipment



Pump Stand




Debris & Equipment



New Secondary Containment



New Secondary Containment





Curtis & Tompkins, Ltd., Analytical Laboratories, Since 1878

2323 Fifth Street, Berkeley, CA 94710, Phone (510) 486-0900

Laboratory Job Number 226031 ANALYTICAL REPORT

Owens Brockway 3200 Alameda Ave. Oakland, CA 94601 Project : STANDARD

Level : II

<u>Sample ID</u> OILY GLOVES <u>Lab ID</u> 226031-001

This data package has been reviewed for technical correctness and completeness. Release of this data has been authorized by the Laboratory Manager or the Manager's designee, as verified by the following signature. The results contained in this report meet all requirements of NELAC and pertain only to those samples which were submitted for analysis. This report may be reproduced only in its entirety.

Deinei 71. Tetralt

Project Manager

Date: <u>02/23/2</u>011

NELAP # 01107CA



CASE NARRATIVE

Laboratory number:

226031

Client:

Owens Brockway

Request Date:

02/17/11

Samples Received:

02/17/11

This data package contains sample and QC results for one cloth sample, requested for the above referenced project on 02/17/11. The sample was received intact.

TPH-Purgeables and/or BTXE by GC (EPA 8015B):

No analytical problems were encountered.

TPH-Extractables by GC (EPA 8015B):

No analytical problems were encountered.

Metals (EPA 6010B and EPA 7471A):

Low recovery was observed for mercury in the MSD for batch 172021; the parent sample was not a project sample, and the associated RPD was within limits. No other analytical problems were encountered.

CHAIN OF CUSTODY

	Name:	Phone (5	usiness Since 16 510) 486-09 510) 486-05 ampler:	000 32 31 31	Bc B	25 CG 25 CG 25 CG 25 CG	دد ددن	-1		6C	3	<u>}</u> 		, motor oil		A	NA	LYI				Cust QU		#_		of _	
EDD For			elephone:	510	4;	36-2	216	6				_	4	die													
Turnarou	nd Time: Rush 3 day	Standard E	mail: b:11.b	05C4	cei.		0 -1	، د	0~			-	.—	641		1											
Lab	Sample ID.	SAMP	PLING	MA	TRIX	Container		CHE			E		AM	PH (
No.		Date Collected	Time Collected	Water		o Co	EC!	H2SO4	HNO3	MOOH	None		J	<u> </u>													
	Oily Gloves	2/14/11	1030	X		l					X		Х	X		1	1	1	I	I	1	I	I	丰			
				-	H	├-	-	\vdash		-				-	-	+	+	+	+	+	+	+	+-	+		H	\dashv
																#	1	1	丰	I	1	丰	上	\perp			\exists
				-	+	├-	-	\vdash	-	\dashv	\dashv				-+	+	+	+	+	+	╀	+	+	+	\vdash		\dashv
																\perp		\pm	土	\pm	1	土	上	上			
															\dashv	1	1	Ţ	Ţ	Ŧ	Ţ	T	F	\bot			\dashv
					+	├	-	H		\dashv	\dashv				-	+	+	+	+	+	+	+	+	十	\vdash	Н	\dashv
																1	1	I	1	1	1	1	工	二			\Box
			-	+	+	-	-	\vdash		\dashv	\dashv		-		+	+	+	+	+	+	+	+	+	+	\vdash	H	\dashv
Notes:		SAMPLE			REL	NQU	SHE	D B	Y:							_				EIV		BY:			_		
ema	il With cost	RECEIPT	Sill bocc	u:	- , , , , , , , , , , , , , , , , , , ,			DATE	2][] :	#/ _T	IME:	123	0	K	esi	u	12	te	in	lt	_	DAT	211	7/14	ME:	123	30
10 45		☐ intact ☐ Cold						DATE	<u>:</u>	T	IME:											DATE	Ē:	TI	ME:		_
		☐ On Ice ☐ Amblent						DATE	<u>:</u>	T	IME:	<u> </u>	-									DATE	<u>:</u>	TI	ME:		_

3 of 30

COOLER RECEIPT CHECKLIST



Login # 22003) Client Wells	Date Received 2 17 Project	Number of coolers
Date Opened 2/17/11 By	u /	sign)
	pping slip (airbill, etc)	YES NO
How many	ent?	Date
3. Were custody papers dry a 4. Were custody papers filled	nd intact when received?	YES NO
☐ Bubble Wrap ☐ Cloth material 7. Temperature documentation	☐ Cardboard ☐ Styrof	☐ None ☐ Paper towels
Type of ice used:	Wet Blue/Gel Non	ne Temp(°C)
☐ Samples Received	on ice & cold without a temper	rature blank
☐ Samples received	on ice directly from the field. C	ooling process had begun
8. Were Method 5035 sampl If YES, what time we	ing containers present?	
9. Did all bottles arrive unbro		YES NO
	opriate containers for indicated t t, in good condition and comple	
	ee with custody papers?	YES NO
13. Was sufficient amount of	sample sent for tests requested	
1 11 1	ately preserved?	
15. Are bubbles > 6mm absert	oncerning this sample delivery	YES NO N/A YES (NO
If YES, Who was call		Date:
comments abel pro	acent on cample wh	en rec'd

SOP Volume:

Client Services

Section:

Page:

1.1.2

1 of 1

Rev. 6 Number 1 of 3 Effective: 23 July 2008

Z:\qc\forms\checklists\Cooler Receipt Checklist_rv6.doc



Total Volatile Hydrocarbons 226031 Prep: EPA 5030B Lab #: EPA 8015B Client: Owens Brockway Analysis: Project#: STANDARD Field ID: Sampled: 02/14/11 OILY GLOVES Units: mg/Kg Received: 02/17/11 02/22/11 Basis: as received Analyzed: Batch#: 172006

Type:
Lab ID:

SAMPLE

226031-001

Matrix: Diln Fac: Miscell.

5.000

 Analyte
 Result
 RL

 Gasoline C7-C12
 ND
 10

Surrogate)	%REC	Limits	
Bromofluorobenzene	(FID)	84	67-140	

Type:

BLANK

Matrix:

Soil

Lab ID:

QC580700

Diln Fac:

1.000

Analyte	Result	RL	
Gasoline C7-C12	ND	0.20	

Surrogate	%REC	Limits
Bromofluorobenzene (FID)	107	67-140

ND= Not Detected
RL= Reporting Limit
Page 1 of 1

10.0



	Total Volatile Hydrocarbons										
Lab #:	226031	Prep:	EPA 5030B								
Client:	Owens Brockway	Analysis:	EPA 8015B								
Project#:	STANDARD										
Type:	LCS	Diln Fac:	1.000								
Lab ID:	QC580699	Batch#:	172006								
Matrix:	Soil	Analyzed:	02/22/11								
Units:	mg/Kg										

Analyte	Spiked	Result	%REC	Limits
Gasoline C7-C12	1.000	0.9710	97	79-121



Total Volatile Hydrocarbons						
Lab #:	226031	Prep:	EPA 5030B			
Client:	Owens Brockway	Analysis:	EPA 8015B			
Project#:	STANDARD					
Field ID:	ZZZZZZZZZZ	Diln Fac:	1.000			
MSS Lab ID:	226037-001	Batch#:	172006			
Matrix:	Soil	Sampled:	02/17/11			
Units:	mg/Kg	Received:	02/17/11			
Basis:	as received	Analyzed:	02/22/11			

Type:

MS

Lab ID:

QC580701

Analyte	MSS Result	Spiked	Result	%REC	Limits
Gasoline C7-C12	0.09165	9.615	6.998	72	41-120

Surrogate	%REC	Limits
Bromofluorobenzene (110	67-140

Type:

MSD

Lab ID:

QC580702

Analyte	Spiked	Result	%REC	Limits	RPD	Lim
Gasoline C7-C12	9.346	7.680	81	41-120	12	47

Surrogate	%REC	Limits
Bromofluorobenzene (F	117	67-140



Total Extractable Hydrocarbons					
Lab #:	226031	Prep:	EPA 3550B		
Client:	Owens Brockway	Analysis:	EPA 8015B		
Project#:	STANDARD				
Field ID:	OILY GLOVES	Sampled:	02/14/11		
Units:	mg/Kg	Received:	02/17/11		
Basis:	as received	Prepared:	02/17/11		
Batch#:	171953	Analyzed:	02/18/11		

Type: Lab ID: SAMPLE

226031-001

Miscell.

Matrix: Miscer 100.0

Analyte	Result	RL	
Diesel C10-C24	95,000 Y	400	
Motor Oil C24-C36	120,000	2,000	

Surrogate	%REC	Limits	
o-Terphenyl	DO	52-130	
Hexacosane	DO	46-137	

Type:

BLANK

Matrix: Soil

Lab ID:

QC580491

Diln Fac:

1.000

Analyte	Result	RL	
Diesel C10-C24	ND	1.0	
Motor Oil C24-C36	ND	5.0	

Surrogate	%REC	Limits
-Terphenyl	116	52-130
2-rerbuenyr	110	32-130
Hexacosane	115	46-137

Y= Sample exhibits chromatographic pattern which does not resemble standard

DO= Diluted Out

ND= Not Detected

RL= Reporting Limit

Page 1 of 1



Total Extractable Hydrocarbons						
Lab #:	226031	Prep:	EPA 3550B			
Client:	Owens Brockway	Analysis:	EPA 8015B			
Project#:	STANDARD					
Type:	LCS	Diln Fac:	1.000			
Lab ID:	QC580492	Batch#:	171953			
Matrix:	Soil	Prepared:	02/17/11			
Units:	mg/Kg	Analyzed:	02/18/11			

Cleanup Method: EPA 3630C

Analyte	Spiked	Result	%REC	Limits
Diesel C10-C24	49.94	47.72	96	44-151

	Surrogate	%REC	Limits
o-Terphen	ıyl	116	52-130
Hexacosan	ne	113	46-137



Total Extractable Hydrocarbons				
Lab #:	226031	Prep:	EPA 3550B	
Client:	Owens Brockway	Analysis:	EPA 8015B	
Project#:	STANDARD			
Field ID:	ZZZZZZZZZZ	Batch#:	171953	
MSS Lab ID:	226027-004	Sampled:	02/17/11	
Matrix:	Soil	Received:	02/17/11	
Units:	mg/Kg	Prepared:	02/17/11	
Basis:	as received	Analyzed:	02/17/11	
Diln Fac:	1.000			

Type: Lab ID:

MS QC580493

Cleanup Method: EPA 3630C

Analyte	MSS Result	Spiked	Result	%REC	Limits
Diesel C10-C24	4.993	50.34	53.39	96	39-146

St	Surrogate	%REC	Limits
o-Terphenyl		115	52-130
Hexacosane		108	46-137

Type:

MSD


Cleanup Method: EPA 3630C

Lab ID:


QC580494

Analyte	Spiked	Result	%REC	Limits	RPD	Lim
Diesel C10-C24	49.96	49.99	90	39-146	6	61


Surrogate	%REC	Limits	
o-Terphenyl	109	52-130	
Hexacosane	103	46-137	



\Lims\gdrive\ezchrom\Projects\GC15B\Data\049b007, B



\Lims\gdrive\ezchrom\Projects\GC15B\Data\048b017, B



\Lims\gdrive\ezchrom\Projects\GC15B\Data\048b018, B



California Title 22 Metals					
Lab #:	226031	Project#:	STANDARD		
Client:	Owens Brockway				
Field ID:	OILY GLOVES	Diln Fac:	1.000		
Lab ID:	226031-001	Sampled:	02/14/11		
Matrix:	Miscell.	Received:	02/17/11		
Units:	mg/Kg	Prepared:	02/22/11		
Basis:	as received				

Analyte	Result	RL	Batch#	Analyzed	Prep	Analysis
Antimony	55	0.50	172048	02/23/11	EPA 3050B	EPA 6010B
Arsenic	1.2	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Barium	6.3	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Beryllium	ND	0.10	172048	02/23/11	EPA 3050B	EPA 6010B
Cadmium	0.32	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Chromium	3.2	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Cobalt	4.2	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Copper	19	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Lead	6.1	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Mercury	ND	0.020	172021	02/22/11	METHOD	EPA 7471A
Molybdenum	1.8	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Nickel	96	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Selenium	1.3	0.50	172048	02/23/11	EPA 3050B	EPA 6010B
Silver	ND	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Thallium	ND	0.50	172048	02/23/11	EPA 3050B	EPA 6010B
Vanadium	2.6	0.25	172048	02/23/11	EPA 3050B	EPA 6010B
Zinc	94	1.0	172048	02/23/11	EPA 3050B	EPA 6010B



California Title 22 Metals				
Lab #:	226031	Prep:	METHOD	
Client:	Owens Brockway	Analysis:	EPA 7471A	
Project#:	STANDARD			
Analyte:	Mercury	Diln Fac:	1.000	
Type:	BLANK	Batch#:	172021	
Lab ID:	QC580744	Prepared:	02/22/11	
Matrix:	Soil	Analyzed:	02/22/11	
Units:	mg/Kg			

Result	RL	
ND	0.020	



California Title 22 Metals					
Lab #:	226031	Prep:	METHOD		
Client:	Owens Brockway	Analysis:	EPA 7471A		
Project#:	STANDARD				
Analyte:	Mercury	Batch#:	172021		
Matrix:	Soil	Prepared:	02/22/11		
Units:	mg/Kg	Analyzed:	02/22/11		
Diln Fac:	1.000				

Туре	Lab ID	Spiked	Result	%REC	Limits	RPD	Lim
BS	QC580745	0.2500	0.2440	98	80-120		100.00
BSD	QC580746	0.2500	0.2410	96	80-120	1	20



California Title 22 Metals					
Lab #:	226031	Prep:	METHOD		
Client:	Owens Brockway	Analysis:	EPA 7471A		
Project#:	STANDARD				
Analyte:	Mercury	Diln Fac:	1.000		
Field ID:	ZZZZZZZZZ	Batch#:	172021		
MSS Lab ID:	225851-001	Sampled:	02/08/11		
Matrix:	Soil	Received:	02/09/11		
Units:	mg/Kg	Prepared:	02/22/11		
Basis:	as received	Analyzed:	02/22/11		

Туре	Lab ID	MSS Result	Spiked	Result	%REC	Limits	RPD	Lim
MS	QC580747	0.2151	0.2500	0.4160	80	72-124		
MSD	QC580748		0.2451	0.3863	70 *	72-124	6	31

^{*=} Value outside of QC limits; see narrative RPD= Relative Percent Difference Page 1 of 1



California Title 22 Metals					
Lab #:	226031	Prep:	EPA 3050B		
Client:	Owens Brockway	Analysis:	EPA 6010B		
Project#:	STANDARD				
Type:	BLANK	Diln Fac:	1.000		
Lab ID:	QC580862	Batch#:	172048		
Matrix:	Soil	Prepared:	02/22/11		
Units:	mg/Kg	Analyzed:	02/23/11		

Analyte	Result	RL	
Antimony	ND	0.50	
Arsenic	ND	0.25	
Barium	ND	0.25	
Beryllium	ND	0.10	
Cadmium	ND	0.25	
Chromium	ND	0.25	
Cobalt	ND	0.25	
Copper	ND	0.26	
Lead	ND	0.25	
Molybdenum	ND	0.25	
Nickel	ND	0.25	
Selenium	ND	0.50	
Silver	ND	0.25	
Thallium	ND	0.50	
Vanadium	ND	0.25	
Zinc	ND	1.0	

ND= Not Detected RL= Reporting Limit Page 1 of 1



Batch OC Report

Bacon go no		rnia Title 22 Meta	ils	
Lab #: Client: Project#:	226031 Owens Brockway STANDARD	Prep: Analysis:	EPA 3050B EPA 6010B	
Matrix: Units: Diln Fac:	Soil mg/Kg 1.000	Batch#: Prepared: Analyzed:	172048 02/22/11 02/23/11	

Type:

BS

Lab ID:

QC580863

Analyte	Spiked	Result	%REC	Limits
Antimony	100.0	105.0	105	80-120
Arsenic	50.00	51.58	103	80-120
Barium	100.0	102.7	103	80-120
Beryllium	2.500	2.690	108	80-120
Cadmium	10.00	10.54	105	80-120
Chromium	100.0	101.9	102	80-120
Cobalt	25.00	24.87	99	80-120
Copper	12.50	12.73	102	78-120
Lead	100.0	100.6	101	80-120
Molybdenum	20.00	20.83	104	80-120
Nickel	25.00	24.92	100	80-120
Selenium	50.00	50.82	102	80-120
Silver	10.00	10.02	100	80-120
Thallium	50.00	50.49	101	80-120
Vanadium	25.00	25.49	102	80-120
Zinc	25.00	25.93	104	80-120

Type:

BSD

Lab ID:

QC580864

Analyte	Spiked	Result	%REC	Limits	RPD	Lim
Antimony	100.0	105.8	106	80-120	1	20
Arsenic	50.00	51.67	103	80-120	0	20
Barium	100.0	97.54	98	80-120	5	20
Beryllium	2.500	2.541	102	80-120	6	20
Cadmium	10.00	10.43	104	80-120	1	20
Chromium	100.0	97.02	97	80-120	5	20
Cobalt	25.00	24.61	98	80-120	1	20
Copper	12.50	11.85	95	78-120	7	20
Lead	100.0	99.76	100	80-120	1	20
Molybdenum	20.00	20.55	103	80-120	1	20
Nickel	25.00	24.68	99	80~120	1	20
Selenium	50.00	50.51	101	80-120	1	20
Silver	10.00	9.542	95	80-120	5	20
Thallium	50.00	49.89	100	80-120	1	20
Vanadium	25.00	24.37	97	80-120	4	20
Zinc	25.00	25.78	103	80-120	1	20



Batch OC Report

	Califo	rnia Title 22 Meta	ils	
Lab #: Client: Project#:	226031 Owens Brockway STANDARD	Prep: Analysis:	EPA 3050B EPA 6010B	
Field ID: MSS Lab ID: Matrix: Units: Basis: Diln Fac:	ZZZZZZZZZZ 225851-001 Soil mg/Kg as received 1.000	Batch#: Sampled: Received: Prepared: Analyzed:	172048 02/08/11 02/09/11 02/22/11 02/23/11	

Type:

MS

Lab ID:

QC580865

Analyte	MSS Result	Spiked	Result	%REC	Limits
Antimony	10.97	98.04	48.66	38	7-120
Arsenic	6.225	49.02	53.08	96	66 - 122
Barium	57.45	98.04	141.0	85	51-135
Beryllium	0.5202	2.451	3.086	105	73-120
Cadmium	0.1023	9.804	9.790	99	64-120
Chromium	52.57	98.04	141.1	90	57-122
Cobalt	15.22	24.51	37.29	90	53-122
Copper	79.73	12.25	102.3	184 NI	M 33-157
Lead	20.32	98.04	105.7	87	52-123
Molybdenum	1.312	19.61	18.56	88	66 - 120
Nickel	52.83	24.51	73.64	85	42-137
Selenium	3.935	49.02	50.05	94	64-120
Silver	<0.07401	9.804	9.237	94	65-120
Thallium	<0.1614	49.02	44.06	90	55-120
Vanadium	56.04	24.51	76.63	84	49-139
Zinc	84.58	24.51	97.00	51	32-155

Type:

MSD

Lab ID:

QC580866

Analyte	Spiked	Result	%REC	Limits	RPD	Lim
Antimony	90.09	48.09	41	7-120	6	44
Arsenic	45.05	49.96	97	66-122	1	35
Barium	90.09	126.9	77	51-135	5	42
Beryllium	2.252	2.721	98	73-120	6	22
Cadmium	9.009	9.059	99	64-120	1	36
Chromium	90.09	137.6	94	57-122	3	34
Cobalt	22.52	33.20	80	53-122	6	32
Copper	11.26	73.82	-52 NM	33-157	31	41
Lead	90.09	103.4	92	52-123	5	41
Molybdenum	18.02	18.01	93	66-120	5	20
Nickel	22.52	66.86	62	42-137	7	36
Selenium	45.05	48.56	99	64-120	5	28
Silver	9.009	8.975	100	65-120	6	27
Thallium	45.05	41.38	92	55-120	2	27
Vanadium	22.52	72.13	71	49-139	4	32
Zinc	22.52	94.06	42	32-155	1	45

NM= Not Meaningful: Sample concentration > 4X spike concentration RPD= Relative Percent Difference Page 1 of 1

-	,	,		
			i.	
į				
			,	

CK 500 58 Ren A 34 -

Leak Detection and Daily Inspection Checklist for the Hazardous Waste Used Oil Tanks

For every day the Plant is operating, mark a Y = Yes if the daily inspection indicates the tank is intact. Or mark a N = No if the daily inspection indicates the tank is leaking and report this condition to the Plant Engineer

Month: F≥l₀. A-Sump D-Sump Skim Pond Used Oil Tank 1 Y Y Y 2 Y Y Y 3 Y Y Y 4 Y Y Y 5 Y Y Y 6 Y Y Y 7 Y Y Y 8 Y Y Y 9 Y Y Y 9 Y Y Y 10 Y Y Y 11 Y Y Y 12 Y Y Y 13 Y Y Y 14 Y Y Y 15 Y Y Y 16 Y Y Y 17 Y Y Y 20 Y Y Y 21 Y Y Y 22 Y Y Y 26 27 <t< th=""><th></th><th>A-01</th><th>A-02</th><th>A-03</th></t<>		A-01	A-02	A-03
Pond Used Oil Tank	Month:	A-Sump	D-Sump	Skim
Date	tab. 2011	1		
1 Y Y Y 2 Y Y Y 3 Y Y Y 4 Y Y Y 5 Y Y Y 6 Y Y Y 7 Y Y Y 8 Y Y Y 9 Y Y Y 10 Y Y Y 11 Y Y Y 12 Y Y Y 13 Y Y Y 14 Y Y Y 15 Y Y Y 16 Y Y Y 17 Y Y Y 18 Y Y Y 20 Y Y Y 21 Y Y Y 22 Y Y Y 23 24 25 26 27 28 29 30	Date			
2				Tank
3		y	Υ	У
4		Y	У	· Y
5	3	y	Y	Y
6		У	γ	ΥΥ
7		Y	У	ý
8		<i>y</i>	, y	΄χ΄
9		Ý	Ý	4
10		У	Y	У
11		У	у	У
12 13 14 14 15 16 17 18 19 20 21 21 22 23 24 25 26 27 28 29 30	10	У	У	У
13		У	Y	y
14	12	У	У	У
15	13	y	y	ý
16		Ý	Ý	Y
17	15	γ	Ý	У
18		Υ	Υ	Y
19		Y	Y	Y
20	1	Y	У	у
21	L	У	У	ý
22		У	У	ý
23 24 25 26 27 28 29 30		Y	Y	Y
24 25 26 27 28 29 30		Ý	y	<i>y</i>
25 26 27 28 29 30				
26 27 28 29 30	24			
27 28 29 30				
28 29 30	L			
29 30	27			
30	28			
	29			
31	30			
	31			

DESIGNATED FACILITY TO GENERATOR STATE (IF REQUIRED)

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039 2. Page 1 of 3. Emergency Response Phone UNIFORM HAZARDOUS 1. Generator ID Number 003501897 JJK 800 368 4778 WASTE MANIFEST CAT 000618918 5. Generator's Name and Mailing Address
Owens Illinois Inc. Plant 20-09kland
3600 Alameda Avenue
Ogliand CA 49769766
Generator's Phone: 510 436-2766 3600 Alamoda Avene Oatland CA 94604 6. Transporter 1 Company CAR000030114 NRC Environmental Services
7. Transporter 2 Company Name 8. Designated Facility Name and Site Address VS Ecology

Hwy 95, 121 miles South

Beatty, NV 89008 U.S. EPA ID Number NVT330010000 10. Containers 12. Unit 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 11. Total 13. Waste Codes Quantity Wt./Vol. No Hazardous Waste Solid, No.S., 9, NA3077, PG 111 0005 D007 D010 ((admium, chromium) 띪 961) 07-013-3287-0 Funace / Checker Dust ERG# 981 171 ERSW.0.#62197 ECP 14. Special Handling Instructions and Additional Information Bin # V159 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged. marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. Generator's/Offeror's Printed/Typed Name 08/10 OSCACC Export from U.S. Port of entry/exit: Transporter signature (for exports only): Date leaving U.S.: 17. Transporter Acknowledgment of Receipt of Materials 18. Discrepancy 18a. Discrepancy Indication Space Туре Partial Rejection Full Rejection Manifest Reference Number: 18b. Alternate Facility (or Generator) U.S. EPA ID Number Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Day 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) 20. Designated Facility Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a Month Day 102 109 1

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.

DISC: 04200: 1337 Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form Approved. OMB No. 2050-0039 1. Generator ID Namber 2. Page 1 of 3. Emergency Response Phone UNIFORM HAZARDOUS (800) 368-4778 35888 WASTE MANIFEST CAT000618918 Generator's Site Address (if different than mailing address) 5. Generator's Name and Mailing Address **3500 ALAMEDA AVENUE** OWENS ILLINOIS INC PLANT 20 - OAKLAND 3600 ALAMEDA AVENUE OAKLAND CA 94504 OAKLAND QARDA 510 435-2166 Generator's Phone: U.S. EPA ID Number Bluewatte Environmental SERVILES INC CARONO19 2229 7. Transporter 2 Company Name U.S. EPA ID Number 8. Designated Facility Name and Site Address US ECOLOGY HWY 95, 12 MILES SOUTH BEATTY 89003 NVT330010000 (775)553-2203 9b. U.S. DOT Description (including Proper Shipping Name, Hazard Class, ID Number, 10. Containers 11. Total 12. Unit 13. Waste Codes Quantity Wt./Vol. and Packing Group (if any)) Type HAZARDOUS WASTE, SOLID, N.O.S., 9, NASO77, PGIII (CADMIUM, DÓ06 D007 **D010** GENERATOR CHROMIUM CM IJ Y 181 14. Special Handling Instructions and Additional Information ERG#:981, 171 * ER5 W.O.#61576 - EC8 * 981) 07-013-3287-0 - FURNACE / CHECKER DUST BILL TO ENVIROSERY WEAR PROPER PPE 15. GENERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. If export shipment and I am the Primary Exporter, I certify that the contents of this consignment conform to the terms of the attached EPA Acknowledgment of Consent. I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true. s/Offeror's Printed/Typed Name SCACE Export from U.S. Port of entry/exit: 눌 Transporter signature (for exports only): Date leaving U.S. 17. Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Transporter 2 Printed/Typed 18. Discrepancy 18a. Discrepancy Indication Space Partial Rejection Manifest Reference Number 18b. Alternate Facility (or Generator) U.S. EPA ID Number : 4. Facility's Phone: 18c. Signature of Alternate Facility (or Generator) Day DESIGN 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treatment, disposal, and recycling systems) Owner or Operator: Certification of receipt of hazardous materials covered by the manifest except as noted in Item 18a 01/12/10-

DESIGNATED FACILITY TO GENERATOR STATE (IF REQUIRED)

EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete

Plea	se pri	int or type. (Form desig		2-pitch) typewriter.)								Approved.	OMB No.	2050-0039
1		LOKIN UNKENKOODS	1. Generator ID Number	• •	2		3. Emergency			4. Manifest 1	•		^ I	11/
Ш	W	ASTE MANIFEST	CATOD	0 6 1 8 9	18		NRCES			1 005	539	187	6 J.	JK
Ш		enerator's Name and Mailin		Att	BILL BOS	CAUCI	Generator's Si	te Address	(if different tha	an mailing addres	s)			-
Ш		OWENS ILLINOIS		PLT 20			•		•	•	•			•
		800 ALAMEDA'A		•					•				• •	
		DAKLAND CA 9 Prator's Phone: 5 1	•	2166	•	· 1	٠.	•	•.	-				· .
		ansporter 1 Company Nam		2300		;	,		-	U.S. EPÁ ID N	lumber		4	
Ш		IRC ENVIRON		ICES INC.						CAR	0 0	n n 3.	D 1. 1	· 4
П		ansporter 2 Company Nam								U.S. EPA ID N				
Ш		'A			•.		• .		:	1		•		
Ш.	8 00	signated Facility Name an	d Site Address	· · · · · · · · · · · · · · · · · · ·			<u> </u>			U.S. EPA ID N	lumber	<u> </u>		
	ا" تر	IS ECOLOGY	u olie Audiess	. •		٠.				0.3. EFAID I	RUI ILU O I			
		iighway 9 5, 18		OF LATHROP	WEL			٠.					• .	.
		BEATTY NV 890			•••		**			1 34 34 7				_
$\ \cdot\ $	Facili	ty's Phone: 800 23	39-3943	*.	·		· ·			NVT	3 3	י ט ט	000	U
Ш	9a.	9b. U.S. DOT Description	on (including Proper Shipp	ing Name, Hazard Cla	ss, ID Number,			10. Contain	ners	11. Total	12. Unit	:13.	Waste Code	s
Ш	НМ	and Packing Group (if a						Ňo.	Туре	Quantity	WL/Vol.			
2	U		rdous waste, sul	id, n.o.s.						•		D008	D007	D008
12	X	9, PGIII					' _ '							
2				·	•		U,U	0 1	СМ	12	Y	132		
GENERATO		2.		1			. 🗀							, · ·]
10	١ ٠			:			٠,		.			,	H	<u>``</u>
Π	L		<u> </u>				<u> </u>				<u> </u>	<u> </u>	<u> </u>	
	Π	3.			· ·	34					<i>'</i> , .	1270-		1
Ш			_	The state of the s	**************************************									
\mathbf{H}									1: 1	. ,				1. 1
		4.												
Π			•	',	. J		.				Ι.	<u> </u>		
Ш	ŀ	l .			3		1,	•		•		١.		
Ш	14. S	pecial Handling Instruction	s and Additional Informati	on	,							L		<u> </u>
		ELP APPROPR	IATE PERSON	AL PROTEC	TIVE EQU	IPMEN	T JOB	#/PO#	· 4-1	1494.			•	
Π		TROES 1605 F	148825~A	(EPS)	73 04501				, , ,	' ' ' '				
11	,	Rin in		AUDRILLIAN,	CT 24201	•.					•			
П	15.	GENERATOR'S/OFFERO	R'S CERTIFICATION: 11	ereby declare that the	contents of this co	nsignment a	re fully and ac	curately de	scribed above	by the proper shi	ipoina name	and are cla	ssified, pack	aged.
	1	marked and labeled/placa	rded, and are in all respec	ts in proper condition f	or transport accord	ling to applica	able internatio	nal and nati	onal governm	ental regulations.	If export sh	ipment and 1	am the Prim	ary
Ш	ŀ	Exporter, I certify that the of I certify that the waste min	contents of this consignme imization statement identi	ent conform to the term feel in 40 CER 262 27/	s of the attached & a) (if I am a lame)	PA Acknowle	edgment of Co	insent. 'Lama ema	all ausantiby agu	nerator) is to se		_		
Н	_	rator's/Offeror's Printed/Ty		100 21 40 01 11 202.21	cy (ii i biii a laige i		ature	1 . /	/	norator) is ado.		Mo	nth Day	Year
Ш		A	DOCCACO			l I	1.19	14	مما				221.0	
H	16, In	ternational Shipments	Sistan				V	α ν) WK	<u> 1011.C1</u>			<u> </u>	0110
Z	l	•	Import to U.S.		LLE	xport from U.	S.	Port of en		 	4	·		
-		sporter signature (for exporansporter Acknowledgmen		•	<u>.</u>	7		Date leavi	ng U.S.:		•			
TRANSPORTER		porter 1) Printed/Typed Nar				Çinn	altire)	·				Mo	nth Day	Year
ĺŘ			>	Ani		l I	ブ	N	0					.1
ş	Trans	porter 2 Printed/Typed Nat	CINPU	TIN	<u> </u>	· · · ·	<i>CPLI</i> ature	¥^>	cas	zeel	<u>ee s</u>	<u>ال - حرا</u> Mo	2 2 0 8	Year
R		,			•	ongra I				· .* .		. wo	Day	10di
片	10 5	icampanay		 		L		·		•	Ĺ			
1	_	iscrepancy									. \			
	18a. (Discrepancy Indication Spa	Quantity		Туре		□Re	sidue		Partial Reje	ection		Full Rej	ection
Ш			. '						•			,		* * .
الحا	405	Marrata Casilla (C	-11	· · · · · · · · · · · · · · · · · · ·			Manifes	Reference	Number:				<u> </u>	
FACILITY	100.	Alternate Facility (or Gener	awrj .			<i>,</i> .	: :			U.S. EPA ID N	umber			
Į			•	, .		٠		•						
		y's Phone:		# J		• .	•, *;	•			•			
쁘	18c. S	Signature of Alternate Facil	ity (or Generator)		•	<u></u>		,				Mo	onth Day	/ Year
¥			· · · · · · · · · · · · · · · · · · ·		· warmen	· · · · · · · · · · · · · · · · · · ·				·				
ESIGNATED	19. H	azardous Waste Report Ma	anagement Method Codes	(i.e., codes for hazard	lous waste tréatme	ent, disposal,	and recycling	systems)					· 1	
8	1,	11100	2.	•		3.				4.			Tayler	
$[\gamma]$		HI 30	<u> </u>				٠.	*						, x, d 14
Ш	20. Di	esignated Facility Owner o	r Operator: Certification of	receipt of hazardous r	naterials covered i	y the manife	st except as n	oted in Item	n 18a					
Ш		d/Typed Name	<u> </u>			, Signa		<u> </u>	·		•	Мо	nth Day	Year
	•	. Lot	Keln	(17)		1 .	164	10					AIN	1//
EPA	Form	8700-22 (Rev. 3-05) F	revious editions are of	solete.			FSIGNA	TED E	ACII ITV	TO GENER	ATOP	STATE	(IE DEC	HIPEN
				~		W			~~:-::	- 	WI VII	マラストに	ur illed	~ / /

DTSC. 01205: 1408

Plea	ise pri	int or type.:(Form desig	ned for use on elite (12-	pitch) typewriter.)					Person re		n Approved	. OMB No.	2050-003
1		FORM HAZARDOUS ASTE MANIFEST	1. Generator ID Number				CES 510-74	9-1390	4. Manifest	35°C)196	3 J.	JK
	3	enerator's Name and Mailin DWENS ILLINO! 3600 ALAMEDA A DAKLAND CA S erator's Phone: 5 1	SINC OAKLAND AVE 14601	PLT 20 A	TE BILL BC	DSCACCI Gener	ator's Site Address	(if different t	han mailing addres	es)	,		
	6. Tra	ansporter 1 Company Nan		I	ntrius	12 True	sportat	ion), U.S. EPA ID N	lumber (HKOC B-0-3	0/65	274
	7. Tra	ansporter 2 Company Nan	ne						U.S. EPA ID N				
		esignated Facility Name ar	nd Site Address						U.S. EPA ID N	lumber	· · · · · · · · · · · · · · · · · · ·		
	} 8	JS ECOLOGY HIGHWAY 95, 18 BEATTY NV 89(ity's Phone: 800 2		OF LATHROI	PWEL		. •		INVT	3 3	0 0 1	000) 0
	9a.		ion (including Proper Shippi	ng Name, Hazard C	lass, ID Number,		10. Contai	iners	11. Total	12. Unit		. Waste Code	
	HM			NIIA NAA	O NA 306	90 PAUL (D000	No.	Туре	Quantity	Wt.∕Vol.		<u> </u>	T
GENERATOR	X	D007. D008)	OUS WASTE, LIC ELECTRO PART	TCIPATOR E	., S. NA3UG EP SWRR	52, PGIII (DUUC Y	0 0 1	СМ	2500	G	D008	D007	D008
ERING STATE	\vdash	2.					0 0 1		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	-	102		
35													
		3.						—				ļ	,
$\ $	'												
		4.				,							
$\ $	ļ. 		1.000					<u> </u>			<u></u>	<u> </u>	
,	VR 1	WEAR APPROP US'ECOLOGY	ns and Additional Informatic RIATE PERSON BIS# 07014865 FERRY POINT	AL PROTEC 9-0		_	J0B#/P0# →	_	94			,	વ
	15.	marked and labeled/place Exporter, I certify that the	OR'S CERTIFICATION: I harded, and are in all respect contents of this consignment ingization statement identification.	s in proper condition nt conform to the ter	n for transport acoms of the attach	is consignment are full cording to applicable in ed EPA Acknowledgme	y and accurately de eternational and nate ant of Consent.	escribed abortional govern	mental regulations.				
	Gene	erator's/Offetor's Printed/T	ped Name SoscACC	·		Signature	1,12	Ro	prae	ci	Mc	onth Day	9 Year
E	ı	international Shipments	Import to U.S.			Export from U.S.	Port of ea	-					
_		Transporter Acknowledgme				·	. Date leav	ing 0.3					
ORT	Trans	sporter 1 Printed/Typed N	\sim ~ 11	· .		Signature	\mathbb{Z}	16	; m.			onth Day	
TRANSPORTER	Trans	sporter 2 Printed/Typed N	ame		est in the second	Signature	/	//		Maral A	A C	onth Day	
TR	10.5								·				_L
\prod		Discrepancy Discrepancy Indication Sp	pace Quantity		Туре		Residue		Partial Rej	laction		Full Rej	iection
			La domain		1,740	•		a khumbasi	ratea (14)	JOGUUII			COOT
E	18b.	Alternate Facility (or Gene	erator)				Manifest Reference	e Number:	U.S. EPA ID	Number	1,50		
FACILITY	Facil	lity's Phone:			•				ı		٠,		
DESIGNATED	18c.	Signature of Alternate Fac	ility (or Generator)	,							*: M	onth Da	y Year
SIGN.	19. F	lazardous Waste Report	Management Method Codes	(i.e., codes for haze	indous waste trea	atment, disposal, and a	ecyclina systems)		· · ·	·		<u> </u>	
PES	1.	Ш	$\frac{2}{3}$			3.			4.				
			or Operator: Certification of	receipt of hazardou	s materials cover	red by the manifest ex	cept as noted in Ite	m 18a					
		ed/Typed Name	HIT	2	1	Signature	11	C			N _M	ooth Bay	
	Form	n 8700-22 (Rev. 3-05)	Previous editions are of	solete				401117	ATO OFNIE			715 056	~~~

		•		
	·			
•				
			¥	
				•
				•
				1
				•
		ı		
ĺ				
İ				
[
l				
			-	
				*
l				

Report run on: December 8, 2010 - 3:28 PM

User Selection Criteria

BR Cycle: 2009

Number of GM Forms: 25

Handler ID: CAT000618918

Number of WR Forms: 25

Included in National Report: Yes

GM and WR Form Sort Order: Descending Order by Waste Amount

Results:

Data meeting the criteria you selected follows.

Total Pages: 3

Report Description

This report is designed to provide all information from the Biennial Report forms in a concise manner. This report should be used after identifying facilities with potential problems using the Preliminary State Detail Analysis volume, the Preliminary TSD & LQG List volumes or the Top Generator/Manager/Shipper/Receiver List reports below. If the user is not interested in seeing GM or WR forms, 0 (zero) may be specified to omit this portion of the report. The user may restrict data to records that were actually included in the National Biennial RCRA Hazardous Waste Report.

Report Information

Name:

b_comprehensive.rdf

Deployed: Last Revised: April 2003 June 2010

Contact:

rcrainfo.help@epa.gov

327213 - GLASS CONTAINER MANUFACTURING

NAICS Codes:

State Activity: No State Activity Information

Report run on: December 8, 2010 - 3:28 PM

Location Address: County:	3600 ALAMEDA AVENUE OAKLAND, CA 94601 ALAMEDA		Mailing Address:	3600 ALAMEDA AVENUE OAKLAND, CA 94601 UNITED STATES
Contact Person:	BILL BOSCACCI 3600 ALAMEDA AVENUE OAKLAND, CA 94601 UNITED STATES Ph: (510) 436-2166, Fax:(510) 43 BILL.BOSCACCI@O-I.COM	96-2032	Certifying Person: Signed:	PLANT MANAGER LOREN JOHNSON 02/18/2010
Owner (current) OWENS ILLINOIS From: 01/01/1937		ONE O-ł PLAZA ONE MICHAEL OWENS WA PERRYSBURG, OH 43551 PERRYSBURG	Type: Y Phone	Private e: (567) 336-8682 F
Operator (current) OWENS ILLINOIS From: 01/01/1937 Notes:			Туре:	Private F
Notes:	Activities			ranger i de la companya da la compan
Notes: Regulated Waste A Hazardous Waste Ge Federal: LARG	enerator Status GE QUANTITY GENERATOR GE QUANTITY GENERATOR Industrial Furnace	<u> </u>	sed Oil Activities Used Oil Transporter Activity Transfer Facility: Transporter:	Off-Specification Used Oil Burner: Used Oil Fuel Marketer Activity
Notes: Regulated Waste A Hazardous Waste Ge Federal: LAR(State: LAR(Exempt Boiler and/or Importer Activity: Mixed Waste Ge Transporter Activity: Tsd Activity: Recycler Activity: Other Hazardous Wa	enerator Status GE QUANTITY GENERATOR GE QUANTITY GENERATOR Industrial Furnace	U	Used Oil Transporter Activity	Off-Specification Used Oil Burner:

Report run on: December 8, 2010 - 3:28 PM

EPA ID: CAT000618918 - OWENS BROCKWAY GLASS CONTAINERS (continued)

Form GM - Page: 1

ELECTROSTATIC PRECIPITATOR DUST EPA Waste Codes: D006 D007 D008 D010

State Waste Codes: CA-181

Notes:

Source: HQ-G15-EQUIPMENT CHANGE

Form: HQ-W319-OTH INORGANIC SOLIDS

Quantity

Waste Minimization: Recycling on-site was implemented

RCRA-radioactive Mixed: NO

On-Site Process:

94.52

Qtv Generated: 189.030.00

UOM: HQ-POUNDS

Density: 0.00/ HQ-

Generation Included in NBR: Yes

Qty Generated (tons):

EPA ID

Sequence Number 1

2

Quantity (tons)

Management Method

Off-Site Shipments:

NVT330010000 CAT000646117

27.15 67.37

54,290.00 H132 - LANDFILL OR SURFACE IMPOUNDMENT 134,740.00 H132 - LANDFILL OR SURFACE IMPOUNDMENT Shipment Included in NBR Yes

Yes

Form GM - Page: 2

ELECTROSTATIC PRECIPITATOR RINSATE

EPA Waste Codes: D007 D008 State Waste Codes: CA-135

Notes: CLEANING OF AIR POLLUTION CONTROL EQUIPMENT

Source: HQ-G13-CLEANING EQUIPMENT

Form: HQ-W504-OTHER SLUDGES

RCRA-radioactive Mixed: NO

On-Site Process:

Waste Minimization: No waste minimization efforts were implemented

Qty Generated (tons):

27.90

Qty Generated: 55,800.00

UOM: HQ-POUNDS

Density: 0.00/HQ-

Generation Included in NBR: Yes

Off-Site Shipments:

EPA ID

Sequence Number 1

Quantity

Management Method

Shipment Included in NBR

CAD008488025

27.90

Quantity (tons)

55,800.00 H121 - NEUTRALIZATION ONLY

Yes

Form GM - Page: 3

IGNITABLE SPENT SOLVENT AND INK, MEK EPA Waste Codes: D001 D035 F005

State Waste Codes: CA-214

Notes: CLEANING OF SPRAY HEADS

Source: HQ-G01-RINSING

Form: HQ-W209-PAINT, INK, ETC.

RCRA-radioactive Mixed: NO

On-Site Process:

Waste Minimization: No waste minimization efforts were implemented

UOM: HQ-GALLONS

Density: 6.70/ HQ-lbs/gal

Generation Included in NBR: Yes

Qty Generated (tons): Off-Site Shipments:

EPA ID

Qty Generated: 55.00 Sequence Number

Quantity (tons)

Quantity

Management Method

Shipment Included in NBR

ARD981057870

0.18

55.00 H061 - FUEL BLENDING

No Form WR Pages Submitted

0.18

Yes

^{*} End of Report *

- ,			
· ·			

Report run on: December 8, 2010 - 5:17 PM

Version 5.0

User Selection Criteria

BR Cycle: 2007

Number of GM Forms: 25

Handler ID: CAT000618918

Number of WR Forms: 25

Included in National Report: Yes

GM and WR Form Sort Order: Descending Order by Waste Amount

Results:

Data meeting the criteria you selected follows.

Total Pages: 3

Report Description

This report is designed to provide all information from the Biennial Report forms in a concise manner. This report should be used after identifying facilities with potential problems using the Preliminary State Detail Analysis volume, the Preliminary TSD & LQG List volumes or the Top Generator/Manager/Shipper/Receiver List reports below. If the user is not interested in seeing GM or WR forms, 0 (zero) may be specified to omit this portion of the report. The user may restrict data to records that were actually included in the National Biennial RCRA Hazardous Waste Report.

Report Information

Name:

b comprehensive.rdf

Deployed: Last Revised: April 2003 June 2010

Contact:

rcrainfo.help@epa.gov

Report run on: December 8, 2010 - 5:17 PM

NAICS Codes:

State Activity: No State Activity Information

327213 - GLASS CONTAINER MANUFACTURING

Site Name: OWEN	IS BROCKWAY GLASS CONTAINE	RS	Activity Location: CALIFOR	NIA	Land Type: Private	
Location Address: County:	3600 ALAMEDA AVENUE OAKLAND, CA 94601 ALAMEDA		Mailing Address:	3600 ALAMEDA AVENUE OAKLAND, CA 94601 UNITED STATES		
Contact Person:	BILL L BOSCACCI Ph: (510) 436-2166 BILL.BOSCACCI@US.O-I.COM		Certifying Person: Signed:	PLANT MANAGER LORE 02/26/2008	N JOHNSON	
Owner (current) OWENS ILLINOIS From: 01/01/1937 Notes:		ONE MICHAEL OWEN: PERRYSBURG, OH 43 PERRYSBURG		: Private	F	
Operator (current) OWENS ILLINOIS From: 01/01/1937 Notes:			Туре	: Private	F CA	
Regulated Waste	Activities				CA	
Hazardous Waste Ge						
Federal: LARC	GE QUANTITY GENERATOR		Used Oil Activities			
	GE QUANTITY GENERATOR		Used Oil Transporter Activity	Off-Specificatio	n Used Oil Bumer:	
Exempt Boiler and/or Importer Activity:		1	Transfer Facility:	Used Oil Fuel N	Marketer Activity	
Mixed Waste Ge	nerator:	.	Transporter:	1	ho first claims the used oil	
Transporter Activity: Tsd Activity: Recycler Activity:			Used Oil Processor and/or Re-refiner Activity	meets the s	pecifications: ho directs shipment ation used oil to off-specification	
Small Quantity O	ste Generator Activities nsite Burner Exemption: , Refining Furnace Exemption:		Processor: Refiner: Underground Injection Control:	used oil bur		
EPA Waste Codes: State Waste Codes:	D001 D006 D007 D008 D0 No State Waste Codes Found	010 D035 F003 F005				
Universal Waste						
No Universal Waste	e Information					

Report run on: December 8, 2010 - 5:17 PM

EPA ID: CAT000618918 - OWENS BROCKWAY GLASS CONTAINERS (continued)

Form GM - Page: 1

REFRACTORY BRICK DERIVED FROM THE REPAIR OF A GLASS FURNACE, CONTAMINATED WITH HEAVY METALS

EPA Waste Codes: D007 D008 D010

State Waste Codes: No State Waste Codes Found

Notes: GLASS FURNACE RUBBLE.

Source: HQ-G15-EQUIPMENT CHANGE Form: HQ-W319-OTH INORGANIC SOLIDS RCRA-radioactive Mixed: NO

On-Site Process: Waste Minimization: None

Qty Generated (tons): 154.73 Qty Generated: 309,460.00 UOM: HQ-POUNDS Density: 0.00/ Generation Included in NBR: Yes

Off-Site Shipments: EPA ID Sequence Number Quantity (tons) Quantity Management Method Shipment Included in NBR

NVT330010000 1 154.73 309,460.00 H112 - MACRO-ENCAPSULATION Yes

Form GM - Page: 2

TOXIC FURNANCE DUST DERIVED FROM THE CLEANING OF REGENERATORS, CONTAINING HEAVY METALS

EPA Waste Codes: D006 D007 D008 D010
State Waste Codes: No State Waste Codes Found

Notes: REGENERATOR OR CHECKER DUST AND ELECTROSTATIC PRECIPITATOR DUST. +WM

Source: HQ-G13-CLEANING EQUIPMENT Form: HQ-W319-OTH INORGANIC SOLIDS RCRA-radioactive Mixed: NO

On-Site Process: Waste Minimization: None

 Qty Generated (tons):
 14.84
 Qty Generated:
 29,680.00
 UOM: HQ-POUNDS
 Density:
 0.00/
 Generation Included in NBR: Yes

 Off-Site Shipments:
 EPA ID
 Sequence Number
 Quantity (tons)
 Quantity
 Management Method
 Shipment Included in NBR

CAD009452657 2 10.00 20,000.00 H112 - MACRO-ENCAPSULATION Yes

NVT330010000 1 4.84 9,680.00 H112 - MACRO-ENCAPSULATION Yes

Form GM - Page: 3

IGNITABLE SPENT SOLVENT AND INK FROM CLEANING SPRAY HEADS, MEK

EPA Waste Codes: D001 D035 F003 F005 **State Waste Codes:** No State Waste Codes Found

Notes: +WM

Source: HQ-G01-RINSING Form: HQ-W209-PAINT, INK, ETC. RCRA-radioactive Mixed: NO

On-Site Process: Waste Minimization: None

Qty Generated (tons): 0.18 Qty Generated: 55.00 UOM: HQ-GALLONS Density: 6.70/ HQ-lbs/gal Generation Included in NBR: Yes

Off-Site Shipments: EPA ID Sequence Number Quantity (tons) Quantity Management Method Shipment Included in NBR

CAD009452657 1 0.18 55.00 H020 - SOLVENTS RECOVERY Yes

No Form WR Pages Submitted

^{*} End of Report *

•			



Evaluation List



OWENS BROCKWAY GLASS CONTAINERS

OAKLAND

CAT000618918

EPA Unaddressed SNC: N	EPA Addressed SNC: N	EPA SNC with Compliance Schedule Established: N
State Unaddressed SNC: N	State Addressed SNC: N	State SNC with Compliance Schedule Established: N
Out of State SNC: N		

Add New Evaluation Show All Violations

4 Evaluation(s) found.

Page: 1	Go To

		\	Violations						
	Act Loc	A Identifier	A Type ¥	▲ Date ¥	Agency	Resp Person	Evaluation Desc	Count	
1	СА	200	CEI	10/19/2004	S		COMPLIANCE EVALUATION INSPECTION ON-SITE	1	Show Violations
2	СА	001	CEI	02/25/2004	E	NRUMR	COMPLIANCE EVALUATION INSPECTION ON-SITE	1	Show Violations
3	CA	001	CEI	04/09/1998	E	CSEIT	COMPLIANCE EVALUATION INSPECTION ON-SITE	2	Show Violations
4	СА	001	CEI	04/13/1994	В	R9STA	COMPLIANCE EVALUATION INSPECTION ON-SITE	No vid	olations found.

URL: /rcrainfo/cme/cme_eval_list.jsp

OWENS-BROCKWAY

RCRA	Description									
Code		2002	2003	2004	2005	2006	2007	2008	2009	2010
	Blank/Unknown	213.0629	243.63758	22.1711	45.62698	36.11414	124.22158	35.4696	81.8601	36.253
	Blank/Unknown					2.30435				
D001	Ignitable	0.60465	0.8135	0.783	0.7715	0.108				
D002	Corrosives	0.45				0.0417				
D006	Cadmium			52.2112	72.9068	15.7704			47.1968	
D007	Chromium	25.284	160.132	281.856	1,622.75	0.8428			10.5	
D008	Lead	54.882	166.8744	16.856		15.1704	8.428	34.0564	64.9506	30.9636
D010	Selenium						137.6624	19.6814	10.1136	18.5416
D039	Tetrachloroethylene	0.22509	0.0834							
F002	Halogenated solvents									
F005	Non-halogenated solvents						0.1815	0.1815	0.198	
NONE	Blank/Unknown			12.97874	17.61976					
	TOTALS	294.50864	571.54088	386.85604	1,759.68	70.35179	270.49348	89.3889	214.8191	85.7582

Plea	se p	rint or type. (Form desig			writer.)							Approved.	OMB No. 2	2050-0039
1		IFORM HAZARDOUS NASTE MANIFEST	1. Generator ID Num		8918	2. Page 1 of	NRCE	ency Response S 510-749	-1390		539	167	7 J.	JK
	(Senerator's Name and Mailin	ng Address SINC OAKLAN		Att BILL B	OSCACCI	Generator	r's Site Address ((if different tha	an malling addre	ss)	•		
	Ger	BOO ALAMEDA A	4801) - 2 1 A	A					II.O. EDILIO		· ·		
	1	ransporter 1 Company Nam			10					U.S. EPAID				
		NRC ENVIRON ransporter 2 Company Nam		KVICESII	<u>vc.</u>					. U.S. EPAID		103	<u>v 1 1</u>	4
		Designated Facility Name ar								U.S. EPA ID	Number			
	! :	Chemical Waste M 35251 Old Skyline Kettleman Hills C	Rd	(HF	·					i		-		
		0, 110 5008 30		Chinning Name Ho	azard Class ID Numb	ar .		10. Contair	ners	11. Total	10 0 12. Unit	8 4	8-1-1	7
	9a HN	' I		Shipping Hains, the	Zaig Gass, ib Hamb			No.	Туре	Quantity	Wt./Vol.	13.	Waste Code	s
GENERATOR	X		ADMIUM) 9,			HECKER		0 0 1	СМ	18		181	D006	
		2. PROFILE# C	401888)											
	L			e ja		, EN								
		3.												
П	-	4.		$\overline{}$							 			
Ш	14.	Special Handling Instruction	ns and Additional Info	rmation	\		1			l				
	1	WEAR APPROPE PROFILE#: CI NRCES 1605 E	1579986		}		nt j	OB#/PO#	: 450€	ig Bir	vt	32	48	
	15.	GENERATOR'S/OFFER marked and labeled/place exporter, I certify that the	arded, and are in all re contents of this consi	espects in proper c ignment copform to	ondition for transport the terms of the atta	according to app ched EPA Ackno	olicable intér owledgment	mational and nat of Consent.	ional governn	nental regulation	hipping names. If export st	e, and are cla nipment and I	ssified, pack am the Prim	aged, ary
П	Ge	I certify that the waste mi nerator's/Offeror's Printed/I		dentified in 40 CF	R 262.27(a) (if I am a	 	enerator) or signature	(b) (if I am a sma	all quantity ge	nerator) is true.		Мо	nth Day	Year
↓		1 WC	305ea	CCi-		L	[_h	I K	Picac	KI		—) <i>[</i>	03	209
FN	16. Tra	International Shipments ansporter signature (for exp	Import to orts only):	U.S.	•	Export from	1 U.S.	Port of en Date leav				<i>-</i>		
TER	17.	Transporter Acknowledgme		ials '			ignature	,	\wedge			Мо	nth Day	Year
S S)ohn	, ,	12011	ė,	ľ	.gradato	loha	(01	roni	wi		0 30	_
TRANSPORTER	Tra	insporter 2 Printed/Typed N	ame	,,,		s I	ignature			1,0		, Mo		
1	_	Discrepancy												
	188	a. Discrepancy Indication Sp	pace Quan	tity	Туре			Residue		Partial R	ejection		Full Rej	ection
È	188	o. Alternate Facility (or Gene	erator)				M	anifest Reference	e Number:	U.S. EPA ID	Number	<u> </u>		
FACI	Fac	cility's Phone:								1				
DESIGNATED FACILITY	180	c. Signature of Alternate Fac	zility (or Generator)									M	onth Da	y Year
Sign	19.	Hazardous Waste Report I	Management Method (Codes (i.e., codes	for hazardous waste	treatment, dispor	sai, and rec	yding systems)						
	1.	+	H32	2.		3.				4.				
	_	Designated Facility Owner	or Operator: Certifical	tion of receipt of ha	azardous materials co			ot as noted in Ite	m (1)Ba				-4 5	
	Pri	nted/Typed Name	in air	\mathscr{A}	Cans	, 	Signature	و ا	11	No	Q,	Mc	onth Day	Year NAS
EP.	A Fo	m 8700-22 (Rev. 3-05)	Previous editions a	are obsolete.			DESIG	NATED FA	CILITY	TO DESTI	NATION	STATE	(IF REC	UIRED)

Ple	ase	print (or type. (Form design			ter.)								OMB No. 2	050-0039
1		WAS	TE MANIFEST		0 0 6 1 8	918	2. Page 1 of 1	I .	gency Response ES 510-74		4. Manifest 1			8 J J	K
	5.	Gener	rator's Name and Mailin VENS ILLINIOS 10 ALAMEDA A	g Address	ND PPT 20	Att BILL BO	SCACCI	Generato	or's Site Address	(if different th					
$\ $		OA	NI ALAMEDA A KLAND CA 94	1801											
$\ $			or's Phone: 5 1		3 - 2',1 8 8						U.S. EPA ID N	lumber			
$\ $	"	NR	C ENVIRON	MENTAL SE	RVICES IN	3 .					CAR	0 0	0 3	0 1 1	4
П	7.	Trans	porter 2 Company Nam	0							U.S. EPA ID N	umber			
Ш	8.	Desig	nated Facility Name an	d Site Address	rue .						U.S. EPA ID N	lumber			
		352	51 Old Skyline	Rd	MTF										ļ
Ш	F		tleman Hills CA Phone: 559 38								C A T	000	0 6 4	6 1 1	7
$\ $			9b. U.S. DOT Description and Packing Group (if a		Shipping Name, Haza	rd Class, iD Number,			10. Contai	ners Type	11. Total Quantity	12, Unit Wt./Vol.	13.	Waste Codes	,
		1	RQ NA3077 H		WASTE SOLI	D, N.O.S. (CH	HECKER		No.	1,00			181	D006	
GENERATOR	4		DUST WITH C		PGIII (D006)				001	СМ	20	Y			
FINER	-	2	<u> </u>							-					
1	1				•	•				1					
$\ $	r	3		****						<u> </u>					
$\ $			٠-												
	r	4													
	1	WE.	cial Handling Instruction	ns and Additional Info	mation ONAL PROT	ECTIVE E	DUIPMEN	er j	OB#/PO#	: 450	59 0.	//			
$\ $	$\parallel /$	PR	OFILE#: CA	579986	1						59 Bin	I	31	93	
	1	- 1	ENERATOR'S/OFFERO		/										
	"	m	rked and labeled/placa	arded, and are in all re	specia in proper cond	lition for transport ac	cording to appl	icable inte	mational and na	tional govern	mental regulations	. If export sh	ipment and	am the Prim	ary
П	G		certify that the waste min		dentified in 40 CFR 2	62.27(a) (if I am a lar		nerator) o	r (b) (if I am a sm	all quantity g	enerator) is true.		Mo	onth Day	Year
		ſ		Boser	+CCI				WZ	430	Doacci		/	0 0	OG
E	:		rnational Shipments orter signature (for expo	Import to	U.S.		Export from	U.S.	Port of e Date leav						
-	-	7. Tran	sporter Acknowledgmer	nt of Receipt of Materi	als			Δ						nth Day	Vans
TOANSDODTED	[[anspo	Plinted/Typed Na		VAN	()	1/	gnature)	rell		nu	<u></u>		nth Day	Pear Pear
MV	Ī	ranspo	orter 2 Printed/Typed Na				Š	gnature					Mo	onth Day	Year
F	━	3. Disc	repancy												
	1	Ba. Dis	screpancy Indication Sp	ace Quan	tity	Туре		[Residue		Partial Re	jection		Full Rej	ection
								M	lanifest Reference	e Number:					
DESIGNATED FACILITY	1	Bb. Alte	emate Facility (or Gene	erator)							U.S. EPA ID I	Number	,		
EAC	F		s Phone:				,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,						-		
ĀŢĀ		3c. Sig ∴:	nature of Alternate Fac	ility (or Generator)		•								lonth Day	Year
NO IV		9. Hazi	ardous Waste Report M	lanagement Method (hazardous waste trea		al, and re	cycling systems)						
12	\$ 1·		11	132	2.		3.				4.				
			ignated Facility Owner	or Operator: Certifical	tion of receipt of haza	rdous materials cove			pt as noted in Ita	em 18a					
	.	nnted/	Typed Name	1000	Solo	242	Si 	gnature A		1	She		. "	onth Day	Year
EF	ΆF	orm 8	700-2 2 (R ev. 3-05)	Previous editions	are obsolete.			DESIG	NATED F	ACILITY	TO DESTIN	IATION	STATE	(IF REC	UIRED

· 子の 3かつつ DTSC. 01130. 2344

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)	10 0027	Form Ap	proved. OMB No. 2050-0039
UNIFORM HAZARDOUS Generator ID Number	Page 1 of 3. Emergency Response Phone	4. Manifest Tracking Numb	
WASTE MANIFEST CATOOOS 18918	1 NRCES 510-749-1390 Generator's Site Address (if differen	005391	681 JJK
5. Generator's Name and Mailing Address OWENS ILLINIOS INC OAKLAND PPT 20 Att BILL BO	SCACCI Generator's Site Address (if differen	it trail maining address)	
3600 ALAMEDA AVE			
_OAKLAND CA 94801	ı		
6. Transporter 1 Company Name 4 3 6 - 2 1 6 6		U.S. EPA ID Number	
NRC ENVIRONMENTAL SERVICES INC.		CAROOD	030114
7. Transporter 2 Company Name		U.S. EPA ID Number	
Designated Facility Name and Site Address		U.S. EPA ID Number	
Chemical Waste Management-KHF		,	,
35251 Old Skyline Rd	•		
Kettleman Hills CA 93239 Facility's Phone: 559 398-8484		LCATOOO	846117
9a. 9b. U.S. DOT Description (Including Proper Shipping Name, Hazard Class, ID Number,		11. Total 12. Unit Quantity Wt./Vol.	13. Waste Codes
HM and Packing Group (if any))	No. Type	Guanuty Willyon.	
g RQ NA3077 HAZARDOUS WASTE SOLID, N.O.S. (CH	HECKER	10/ 4	81 0006
DUST WITH CADMIUM) 9, PGIII (D006) /	0 0 1 CM	18 ,	
RQ NA3077 HAZARDOUS WASTE SOLID, N.O.S. (CH DUST WITH CADMIUM) 9, PGIII (D006)			
		-	
3.			
· ·			
4.			·
14. Special Hapfilling Instructions and Additional Information			
	QUIPMENT JOB#/PO#: 45	069 1 4/7	£ 3137
PROFILE#: CA579986		DAN +	2107
NRCES 1605 FERRY POINT ALAMEDA, CA 9450			
 GÉNERATOR'S/OFFEROR'S CERTIFICATION: I hereby declare that the contents of this marked and labeled/placarded, and are in all respects in proper condition for transport acc 	cording to applicable international and national government	pove by the proper snipping name, ar emmental regulations. If export shipm	ent and I am the Primary
Exporter, I certify that the contents of this consignment conform to the terms of the attache I certify that the waste minimization statement identified in 40 CFR 262.27(a) (if I am a lan	ed EPA Acknowledgment of Consent. ge quantity generator) or (b) (if i am a small quantit	y generator) is true.	,
Generator (Offeror's Printed/Typed Name	Signature / \	The second secon	Month Day Year
W. HOSCAECI	MODI	Deacc	10 240,
16. International Shipments Import to U.S. Transporter signature (for exports only):	Export from U.S. Port of entry/exit:	***	
	Date leaving U.S.:		
Transporter Acknowledgment of Receipt of Materials Transporter 1 Printed/Typed Name Transporter 2 Printed/Typed Name	Signature		Month Day Year
& SAN CANEULAN	Man Ca	nesso	10 20 02
Transporter 2 Printed/Typed Name	Signature		Month Daly Year
18a. Discrepancy	<u> </u>	Π	
18a. Discrepancy Indication Space Quantity Type	Residue	Partial Rejection	Full Rejection
	Manifest Reference Number		
18b. Alternate Facility (or Generator)		U.S. EPA ID Number	
		1	
□ Facility's Phone: □ 18c. Signature of Alternate Facility (or Generator)			Month Day Year
 			
18b. Alternate Facility (or Generator) Facility's Phone: 18c. Signature of Alternate Facility (or Generator) 19. Hazardous Waste Report Management Method Codes (i.e., codes for hazardous waste treating to the code of th	atment, disposal, and recycling systems)		
1 H127 2	3.	4.	
20. Designated Recitity Owner or Operator: Certification of receipt of hazardous materials cover			
1.1. L.C. LIRSIGNATED MECHIN CONTROL Of Contractor Continuation of receipt of hazardous materials on an	and by the mentions event so anded in New 10s	//	
Printed/Typed Name		1 1	Month Day Year
Printed/Typed Name Printed/Typed Name Printed/Typed Name EPA Form 8700-22 (Rev. 3-05) Previous editions are obsolete.	Signature	Ade	Month Day Year

ase pri	nt or type. (Form desig	gned for use on eli	te (12-pitch) typewriter.)		04				m Approved	. OMB No.	2050-003
	FORM HAZARDOUS	1. Generator ID Nur CATOOO6	and o ic rate and is	1 (y. 2. Page 1 of	3 Emergency Response (800) 368-477	. 4.4	AA	Tracking N 554	398	7 J	JK
	nerator's Name and Mailir	ing Address	Property of the property of the		Generator's Site Address			88) -	12 Nov. 15	war e	0.1, 27
35.	OWENS ILLINOIS	INC PLANT 20	OAKLAND	- (40	3500 ALAMEDA AV	ENTR.	ar F		าร อยู่สร้าง เลก (ก) เอาซุล ในได้ไดย (ก)		roden uselini
	MANI ABITS	A MARKET	CA BATTA	``>-0a1	CAKLAND	,	92 - 21 CI		94604		mori e
	ansporter 1 Company Nam		માં છે. જેવા છે. કર્યા કર્યા છે. પ્રાથમ પ્રાથમ		- miles costs		U.S. EPAID N	Number			
1417	ENVIRONMENTA	, a'man	وحليفا فيستنبه بالموران والشائد فالمال	1 - ५१	sign in the second	janute i eriger Gren i jinarek	1 640		88201		at the said
7. Tra	ansporter 2 Company Nam			. 1.	CONTRACTO	History	U.S. EPAID N	Vumber -		erice :	199 3 0 (1.0
	Aller Land		אלוופר אין	ালু বং জন্ম			and and the modern of			دار پردر ۱۸۰	કર્યાઇકાર્યા જ
8. De	signated Facility Name ar	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1	in Countries of Countries in it				U.S. EPA ID N	lumber	. •	ar in self	1 1
.ધોલ્ડ લ	8881 DICE ROAD	addition to the first	्य किया नामक्ष्ये कर कि इस्ताम क्षेत्रीयुर्गात् इ.स.च्या कर सम्बद्धाः अस्तानक व्यवस्थान	7世纪/- 100世纪/-		होती	uns for Caracol	ni di selimin	1.1		
Carlling B	MANAGEMENT I'M MALLERA	165 1696-6056	CA 90670 Isu	2-12h-23	alattic (I CAD	0084	88028	R Marie	STA DA
Pacili 9a	A) O' HONO		Shipping Name, Hazard Class, ID Nun	mber,	Cas of 10. Contain	ners, ye ?	11. Total	12: Unit	1	Waste Code	of Still and
HM	and Packing Group (if	any))	or of smoo salvenies	etter and	No.	- Туре	Quantity	WL/Vol.	13.	Waste Cour	38
	HAZARDOUS	WASTE LIQUID), N.O.S. 9, NA3082, PGM (CH	,	D) Lingiant all	i.t. i Mamk	Taring defents	ic som	0007	0008	138
, <u>.</u>	100	i.	के स्मित्यूका झाटा प्र किस पुत्रा		\ \mathread \mathread \ \mathread \ \mathread \ \mathread \ \mathread \ \mathread \ \mathread \ \mathread \mathread \ \mathread \mathread \ \mathread \mathrea	TT	1500	of G.	~		0.02
	200.		1 (1 (Ja) ak,	· i ·	www.mer.co.		त्त्रका स्टब्स् इ	1, 1, 1	_E an	-	10 m 12 m 1
	:		अ) सन् जाम				รัชทางกรีมแล้ว ธ.สทวับกระสักษา	B .		16 C 16 T	ranga.
់ជ	studies po ma	ra in riji	and Charles and	ė ioi'	1 is 1382 this is	. 5-3	d Jugaritha y	in my		~	COLUMN COLUMN
j	3.5	\$	To Chilis	gga englige	1 4 St 57-5	v.33855.	Base day of	4 33 74	16 47 5	(° 5' +	1,00
bet.	क्षेत्री वर्डकुर का अपने	omand≠ di	en en hastelak et	tsu idoli	t	1. p. di. :-3	හෝ ද් ආශ්රීම ප්රීම	genetrijke Othersk	* * *	940.5	1.1.17
c-;*	4. v	to Arthur To Table	୍ର ପ୍ରଥମ ପ୍ରଥମ ଅନ୍ୟୁକ୍ତ । ୧୯୬୩ ଅନ୍ୟୁକ୍ତ	\$54.62 IS	- 	12 12 1		-	eles veren	1.1.	1
1 и, -	Methodological Comments			ers ,	i sa sta i	\$ 15000	come revisars			ENCERT	0.09
		Quarter .	10000000000000000000000000000000000000		ar in the telephone	760 Phy. 2.	जिल्लेखाः काम र	110 A A -1	Brazion e	F. 11. 2	3 .16
14. S	Special Handling Instruction	ins and Additional Info	ormation :	teges.	respondent of the state of the	OF 1 1 1.15/61	in the section	પ્રદેશો કહે	grand and the	. P. 51 19 14 14 14 19 19	"一个时间
121	E3981) 2008EP - E	EP WATER	a so sendid are nieuc \	geria:	no favor o de da pr	di perior per	entre acid v		地名 化	ALUCE ST	But small
Marin.	alaba relacide delle si Remain lab ancie delle	egi asofigano in mo Analisia eta entre e per	त्यत्य स्तापनाः इतस्य सम्बद्धाः । । कृतिकारिकाः विस्ताः अस्य सम्बद्धाः ।	ोर्ड कि भारतिकार	of South Consider.		SERV - WEA				
15	GENERATOR'S/OFFER	OR'S CERTIFICATIO	ON: I hereby declare that the contents	of this consignment a	are fully and accurately des	scribed above	e by the proper shi	ipoino name	e and are da	esified, pack	Mina
	marked and tabeled/place	arded, and are in all n	respects in proper condition for transpor signment conform to the terms of the at	ort according to applic	cable international and national	onal governm	ental regulations.	If export sh	ipment and I	am the Prim	NEW CONST
- 4,	certify that the waste mi	inknization statement	identified in 40 CFR 262.27(a) (if I am	a large quantity gen	nerator) or (b) (if I am a sma	all quantity ger	enerator) is true	ي استدره ك.	ំពុងកោត្តសៀ	edito entin	rinter thoir
Gene	erators/Offerer's Printed/T	yand Name (1)	The grade is the regal to be a recommendation of	Sign	gnature	GARAGE CO	2000	THE PROPERTY OF	ANTERIA MO	ith io: Day ジェロア	Year.
<u> </u>	Tamational Chinments	Dysev	S CC) are now		Marie de la companya della companya de la companya de la companya della companya						
	sporter signature (for expo		อับเราะสาราชาน เกาะสาราชาน	Export from U	J.S. Port of ent	ry/exit.	12 - 20 10 10 10 10 10 10 10 10 10 10 10 10 10	i destination in description	\$1955 (195 3345 - 18	4 56 5 - 6 5 - 16 . 2 16	Granda
	sporter signature (for exporansporter Acknowledgme)	JCI 25 5127/1:		- 2.		1	****V. #. 4		ija ta ta	44 100 4 1	
Trans	sporter 1 Printed/Typed Na	ame:i	AINE STO	Sign	nature	25	ラ		Mor		
rii.	TOTAL PARTY		41 744	, Sie		er(GG! >)		, 	and a straight		
	sporter 2 Printed/Typed Na	lame.	in the second of) .	gnature :		erigil († 35.) 12 Mai - Arthur		Moi	onth Day	Year .
	screpancy		A September 1	, 13			<u>बर दिश्रा (१८ ५२ ६) ५ ५</u> पुरस्कार जन्म १९५५	<u> </u>		14 1 12 A	
÷	Discrepancy Indication Sp	nace Couer	ntity Tune		Donaidus	Table 1	Partial Reje	400		-ti-	. ,
£;;;•,		L. Quan	Signal of the	3	Residue 3			COOH		Full Rej	ecuon
_	** · · · · · · · · · · · · · · · · · ·		Te death has		Manifest Reference	Number:	*		/;		
<i>),</i>	Alternate Facility (or Gene	rator)	1. 1. 1.				U.S. EPA ID N	umber			
	ty's Phone		Mark Marine			: • 1				•	
	ty's Phone: Signature of Alternate Fac	cility (or Generator)			***	* , * * * .		,	. Mr	onth Day	y Year
. ' : :	(F. M.) Sections And Section 1		. 3		• • •					1	1.
		Management Method	Codes (i.e., codes for hazardous waste	e treatment, disposa	d, and recycling systems)						
1."			2.	3.	Ş		4.		ı	,	
	مراك المستادة في الأ		La contraction			<u> </u>		· 5			
	esignated Facility Owner of ed/Typed Name	or Operator. Certificat	ation of receipt of hazardous materials o		ifest except as noted in Item mature	18a		/-	Mr	onth Day	Year
	W 1 ypour Hulling			ا	naturo .					onth Day	Tear

(m) For all variances, the petitioner must also demonstrate that compliance with any given treatment variance is LAND DISPOSAL RES (m) For all variances, the petitioner must also demonstrate that computative with any given treatment variance mize threats to human health and the environment posed by land disposal of the waste. In evaluating this day mize threats to human health and the environment posed by land disposal of the waste. In evaluating this dentake into account whether a treatment variance should be approved if the subject waste is to be used in a man posal pursuant to 40 CFR 266.20 through 266.23.

(o) The following facilities are excluded from the treatment standards under § 268.40 and are subject to the following

TABLE—WASTES EXCLUDED FROM THE TREATMENT STANDARDS UNDER \$ 283

Facility name				DAHDS		3 253.40	
and address	Waste	Table CCWE	Regulated hazardous constituent	Wastewaters			
Ball-Foster Glass Container Corporation, El Monte, CA ^{(6),(7)}				Concentration (mg/L) Notes		Normalienan	
	D010					Concerne	Concernment
Crafton		in 268.40	Selenium	NA :	i bisha	(mg/kg	No.
Craftsman Plating and Tinning, Corp., Chicago, IL	F006				1341	25	
	1006	Table CCWE	Cyanidas		ne chille		
		in 268.40	Cyanides (Total) Cyanides (Amenable)	1.2	(3)	noses a	
			Cadmium	.86	AT ACCUMENT	100000000000000000000000000000000000000	No.
			Chromium	1.6		90 1 30	海にり
Northwestern Plating Works, Inc., Chicago, IL	1		Lead	.32		uis NA	
	F006	Table	Nickel	.040		o no	193
		Table CCWE in 268.40	Cyanides (Total)	.44		TON CONT	
		0.40	Cyanides (Amenable)	1.2	(2 and 3)	Form	
		· ·	Caumium		(2)	30	17
			Chromium	1.6 .32		NA TO	0
wens Brockway Glass Container Company, Vernon, CA ^{(5),(7)}		•	Lead	.040		NATION	0: 1
	D010	Terr	Nickel	.44		NAT SO	i d
		Table CCWE in 268.40	Selenium			MA(i)	- 1
facility may certify come!			, ,	NA	NA	51	NA

⁽¹⁾A facility may certify compliance with these treatment standards according to provisions in 40 CFR 268.7. (2) Cyanide Wastewater Standards for F006 are based on analysis of composite samples.

[51 FR 40642, Nov. 7, 1986; 52 FR 21017, June 4, 1987 as amended at 53 FR 31221, Aug. 17, 1988: 54 FR 36077

ment standards for hazardous debris.

ds Hazardous debris must be treated prior to land disposal as follows unless EPA determine this chapter that the debris is no longer contaminated with hazardous waste or the debris is treated to at standard provided in this subpart for the waste contaminating the debris:

Hazardous debris must be treated for each "contaminant subject to treatment" defined by paragraph the technology or technologies identified in Table 1 of this section.

deristic debris. Hazardous debris that exhibits the characteristic of ignitability, corrosivity, or reactivity 18 261.21, 261.22, and 261.23 of this chapter, respectively, must be deactivated by treatment using one of the rified in Table 1 of this section.

for each type of debris types. The treatment standards of Table 1 in this section must be achieved for each type of debris types. in a mixture of debris types. If an immobilization technology is used in a treatment train, it must be the last

Vintures of contaminant types. Debris that is contaminated with two or more contaminants subject to treatment paragraph (b) of this section must be treated for each contaminant using one or more treatment technological Table 1 of this section. If an immobilization technology is used in a treatment train, it must be the last treat

Waste PCBs. Hazardous debris that is also a waste PCB under 40 CFR Part 761 is subject to the requirement CFR Part 761 or the requirements of this section, whichever are more stringent.

minants subject to treatment. Hazardous debris must be treated for each "contaminant subject to treatmen subject to treatment must be determined as follows:

in Toxicity characteristic debris. The contaminants subject to treatment for debris that exhibits the Toxicity C TC) by § 261.24 of this chapter are those EP constituents for which the debris exhibits the TC toxicity chara in Debris contaminated with listed waste. The contaminants subject to treatment for debris that is contaminate bild listed hazardous waste are those constituents or wastes for which treatment standards are established for der § 268.40.

(3) Cyanide reactive debris. Hazardous debris that is reactive because of cyanide must be treated for cyanide Conditioned exclusion of treated debris. Hazardous debris that has been treated using one of the specified extracti intechnologies in Table 1 of this section and that does not exhibit a characteristic of hazardous waste identified un M 161, of this chapter after treatment is not a hazardous waste and need not be managed in a subtitle C facility. Ha autominated with a listed waste that is treated by an immobilization technology specified in Table 1 is a hazard mst be managed in a subtitle C facility.

PCRA-501 RDB-6477

Treatment residuals—(1) General requirements. Except as provided by paragraphs (d)(2) and (d)(4) of this s

- (i) Residue from the treatment of hazardous debris must be separated from the treated debris using sim mechanical means; and
- (ii) Residue from the treatment of hazardous debris is subject to the waste-specific treatment standar Subpart D of this part for the waste contaminating the debris.
- (2) Nontoxic debris. Residue from the deactivation of ignitable, corrosive, or reactive characteristic hazardous d cyanide-reactive) that is not contaminated with a contaminant subject to treatment defined by paragraph (b) of t be deactivated prior to land disposal and is not subject to the waste-specific treatment standards of Subpart 1
- (3) Cyanide-reactive debris. Residue from the treatment of debris that is reactive because of cyanide must m standards for D003 in "Treatment Standards for Hazardous Wastes" at § 268.40.

Tonitable nonwastewater residue containing equal to or greater than 1 C. DOO1. Ionitable Liquids.

⁽³⁾ These facilities must comply with 0.86 mg/L for amenable cyanides in the wastewater exiting the alkaline chlorination system. These facilities must also comply with 40 CER \$ 260 7 and 500 mg/L for amenable cyanides in the wastewater exiting the alkaline chlorination system. These facilities must also comply with 40 CER \$ 260 7 and 500 mg/L for amenable cyanides in the wastewater exiting the alkaline chlorination system. These facilities must also comply with 40 CER \$ 260 7 and 500 mg/L for amenable cyanides in the wastewater exiting the alkaline chlorination system. ply with 40 CFR § 268.7.a.4 for appropriate monitoring frequency consistent with the facilities' waste analysis plan. (4) Cyanide nonwastewaters are analyzed using SW-846 Method 9010 or 9012, sample size 10 grams, distillation time, 1 hour and 15 minutes.

⁽⁵⁾ Alternative D010 selenium standard only applies to dry scrubber solid from glass manufacturing wastes.

⁽⁶⁾ Alternative D010 selenium standard only applies to electrostatic precipitator dust generated during glass manufacturing operations.

⁽⁷⁾D010 wastes generated by these two facilities are subject to the following conditions: (a) the wastes must be treated by Chemical Waste Management, Inc. at their Kettleman Hills facility in Kettleman City Collisonia; and (b) this results are subject to the following conditions: (a) the wastes must be treated by Chemical Waste Management, Inc. at their Kettleman Hills facility in Kettleman City, California; and (b) this treatment variance will be valid until May 11, 2002.


November 23, 2010


Got a phone message from Leroy Griffin of the Alameda County CUPA ((510) 755-5785) concerning the upcoming Owens-Brockway inspection. I sent him the following email (Igriffin@oaklandnet.com):

Leroy,

Thanks for, your phone message. The Owens-Brockway facility is scheduled to be inspected on Thursday, December 9. Hopefully, we can talk before then to set up the logistics. I will be accompanied by another EPA inspector, Amy Miller. Could we meet you at the facility itself at 8:00 am? Usually when I'm meeting a CUPA representative at a jobsite, I try to find the nearest Starbucks to meet, so that whoever arrives first has a comfortable place to wait for the other inspector. If you're okay with that, it looks like the Starbucks nearest to the facility is located at 3060A E 9th St., Oakland.

Between now and the inspection, would it be possible to look at prior inspection reports and the business plan for the facility?





	•	,			
			\$		
				•	
:					
			,		
				-	
				•	
				• • • • • • • • • • • • • • • • • • •	

May 22, 2004



Nancy Rumrill
Enforcement Officer
Environmental Protection Agency
WST-3
75 Hawthorne Street
San Francisco, CA 94105

Dear Ms. Rumrill,

This letter is intended to respond to your warning letter dated May 3, 2004 in which you are requiring Owens to correct three areas of noncompliance and submit the documentation of their correction to U.S. EPA.

The three requested items of information are:

- 1. Photograph showing that the spent solvent accumulated in one liter containers for cleaning ink heads are properly labeled, pursuant to 22 CCR § 66262.34(e).
- 2. A written description of training provided to hazardous waste handlers that includes their specific emergency procedures (e.g., containment and/or cleanup of spills), pursuant to 22 CCR § 66265.16(a)(2).
- 3. Provide a description and certification of compliance related to our recycling of Electrostatic Precipitator (EP) dust and glass bead blast with California Health and Safety Code Section 25143.9.

The attachments that follow provide you with the requested information. I certify that these corrections have been completed as illustrated by the attachments. If you require additional information about the contents of this letter please contact Bill Boscacci at (510) 436-2166.

Sincerely,

Dwayne Wendler
Plant Manager

Re: EPA ID. No. CAT000618918

Certified Mail 7099 3220 0004 0214 4032

Attachment 1

Photograph of spent solvent container



Attachment 2

Waste Handlers Training Description

Hazard Communication Standard

Ensures that employees are aware of the hazards of chemicals they work with and understand their rights under the standard.

Summary of Requirements

- 1. Inventory of all chemicals
- 2. Material Safety Data Sheets for all chemicals
- 3. Written program
- 4. Labeling
- 5. Training

Written Program contains:

- a) Name of person responsible for program
- b) Name of those responsible for employee information & training, MSDS files, labeling procedures, etc.
- c) Method of determining whether a chemical is hazardous
- d) Copy of current inventory and where hazardous materials are located.
- e) Methods used to comply with labeling requirements, MSDS files, employee information & training, Proposition 65 warnings.
- f) Method for informing employees of hazards of non-routine tasks and working on unlabeled pipes.
- g) Method of informing contractors of our chemicals & of them informing us of what they have
- h) Location of MSDS's & how employees can obtain copies.
- i) What to do in an emergency

Labeling:

They understand the use of HMIS labeling and hazardous waste labels.

Training:

All personnel will be trained at the time of initial assignment, when changes in job duties require additional training, or when procedures are changed.

Personnel Protective Equipment (PPE) and Hearing Protection

Emergency Evacuation and Spill Response

This is described in the following sections.

Respiratory Training (If Required)

Hazardous Waste Management.

This is described in the following sections.

Asbestos Awareness Training

Employees know where asbestos is located in their workplace.

They understand their limitations under the training and company policy.

- Comprehensive Spill Training -

- Specific "Materials of Concern" in O-B glass facility
- General Principles of "Materials of Concern"
- Best Management Practices
- Applicable Spill Related Plans
- NAERG 2000
- Prepare To Respond Video ~ 18 min
- O-B Spill Contingency Plan
- Emergency Response 1-2-3

- Comprehensive Spill Training -

"MATERIALS OF CONCERN"
Anhydrous Ammonia - hot end coating (HEC)
Anhydrous Tin Tetrachloride - hot end coating
(HEC)
Methyl Ethyl Ketone - bottle coding
Sulfuric Acid - water treatment
Muriatic Acid - demineralizer regenerant
Propane - mobile equipment
"Caustic" Materials - water treatment, degreasing
Safety-Kleen Parts Washers - cleaning / degreasing
Gasoline / Kerosene / "Oils" - fuels, lubricants, etc.
Checker Dust - checker cleaning
Tin Reclaimable Material - HEC abatement system
Oxygen - supports combustion

- Comprehensive Spill Training -

- General Principles of "Materials of Concern"
 These materials may exhibit a physical and/or health (biological) hazard.
- **Physical** hazards : act <u>indirectly</u> to cause harm; include fires or explosions or other effects by mechanical means. Gasoline is a good example classified as a flammable liquid, it is both a fire hazard and an explosive hazard. Even the vapors can be explosive.
- Other examples include oils, compressed gases, cryogenic liquids, and oxidizers.

- **Health (biological)** hazards: act <u>directly</u> to cause harm; if these materials contact your body directly, they cause biological reactions, destroying tissue or make you ill. The response or adverse reaction may be immediate (acute) or delayed (chronic).
- Most common examples include categories of materials defined as poisons, irritants, allergens, carcinogens, mutagens, and teratogens) and corrosives (such as acids, bases, caustics, alkalis).

"MATERIALS OF CONCERN"	HAZARD TYPE
	H = health P = physical
Anhydrous Ammonia	H - acute
Anhydrous Tin Tetrachloride	H - acute
Methyl Ethyl Ketone (MEK)	H - acute/chronic + P
Sulfuric Acid	H - acute/chronic
Muriatic Acid	H - acute
Propane	H - acute + P
"Caustic" Materials	H - acute
Safety Kleen Parts Washer	H - acute/chronic
Gasoline / Kerosene / "Oils"	H - acute/chronic + P
Checker Dust	H - chronic
Tin Reclaimable Material	H - acute
Oxygen	H - acute + P

- Best Management Practices:
 - Good housekeeping
 - Timely and appropriate spill report / response
 - Utilize inside or covered storage areas
 - Store materials in low traffic areas, away from drains, in areas that provide secondary containment controls
 - Routinely inspect potential storm water impact and spill areas
 - Dispose of obsolete equipment
 - Follow proper material management practices
 - Insure that all secondary containment valves are locked in a closed position, allowing only authorized access visually observe and document release of accumulated stormwater.

- Applicable Spill Related Plans:
 - Storm Water Pollution Prevention Plan
 - Identifies areas with the potential to pollute storm water
 - Spill response procedure
 - Good Housekeeping Measures
 - Material Management Practices
 - Best Management Practices
 - Monthly / Quarterly / Semi Annual / Annual Evaluations

- Applicable Spill Related Plans:
 - Spill Prevention Control and Countermeasure Plan
 - Written description of spill events and corrective action taken
 - Appropriate containment and/or diversionary structures or equipment to prevent discharged oil from reaching navigable waterways
 - A written commitment of manpower, equipment and materials required to expeditiously control and remove any harmful quantity of oil discharged
 - Spill response internal / external notification procedure 8

- North American Emergency Response Guide (NAERG 2000)
 - contains placard table
 - lists DOT hazardous materials by 4 digit UN number (yellow pages) that will cross reference an emergency response guide
 - lists DOT hazardous materials in alphabetical order (blue pages) that will cross reference an emergency response guide
 - contains response guides that will summarize hazards and emergency action measures (orange pages)
 - provides initial isolation and protective
 distances (green pages) by UN number

RG NUMBER
Gases - Corrosive)
Water Reactive - Corrosive)
Flammable Liquids)
Water Reactive - Corrosive)
Toxic +/- Corrosive)
Gases - Flammable)
Toxic +/- Corrosive)
Flammable Liquids)
Flammable Liquids)
_ow to Moderate Hazard)
Toxic +/- Corrosive)
Gases - Oxidizing)

II

KESBOND AIDEO BEBY LO

O-B Spill Contingency Plan:

If a release is detected, the employee should implement the following:

- Attempt to identify the source of the leak and stop it, if you can do it without <u>risk</u>.
- Notify Forming Dept. Shift Foreman
- Shift Foreman will evacuate and contact local rescue service, if necessary.
- Depending on severity of the situation, the Shift Foreman should immediately notify Emergency Coordinator of the spill/release situation.


- Emergency Coordinator will assess the spill/release and determine if can handle internally or need outside assistance.
- Emergency Coordinator will communicate any spill situation to the appropriate authorities, after consulting with O-B Environmental Affairs.


- Emergency Response 1-2-3

Any of the following would be considered to be "emergency" situations..

- 1 The immediate area needs to be evacuated is the release forcing workers out of the area?
- 2 Is the required level of PPE exceed the level that is provided to the employee for normal handling?
- 3 Is there a potential / probable risk to health and safety?

If one or more of the conditions listed above is present - an emergency response situation exists. Assessment of hazardous conditions and substances is a case-by-case requirement when determining the potential for an emergency situation.





JS WASTE ENT ⊃le - Video ~ 20 min as Waste, Generation Hazardous Waste —ating Points criptions dure

e Mistakes

- Hazardous Waste Life Cycle Video ~ 20 min
 - Definition of Hazardous Waste, Generation
- Owens-Brockway Specific Hazardous Waste Streams
 - Seven Common Generating Points
- Hazardous Waste Job Descriptions
- Spill Contingency Plan
 - O-B Notification Procedure
- Top Ten Hazardous Waste Mistakes

HAZARDOUS WASTE VIDEO LIFE CYCLE

Owens-Brockway Specific Hazardous Waste Streams:

- Safety-Kleen Parts Washers
- Caustic Degreaser Tanks
- Imaje / Video Jet Printing Waste
- Solvent Rags
- SFL Spray Booth
- EP Dust / Glass Bead Blast
- Old, Outdated Chemicals

- Hazardous Waste Management Positions
 - Job Titles
 - Hazardous Waste Accumulator
 - Hazardous Waste Coordinator
 - Hazardous Waste Inspector

- Hazardous Waste Accumulator
 - Duties (IMAJE Ink Jet Coders Satellite)
 - Wash heads per specification as necessary
 - Accumulate waste liquid MEK in appropriate container
 - Ensure that accumulation drums are labeled and labels visible
 - Ensure that accumulation drums are closed at all times except when adding or removing waste
 - General housekeeping

- Hazardous Waste Accumulator
 - Duties (Satellite / Main)
- Accumulate waste in appropriate container
- Ensure that accumulation drums are labeled and labels visible
- Ensure that accumulation drums are closed at all times except when adding or removing waste
- Ensure that accumulation start date is on container (for non-satellite areas)
- General housekeeping

- Hazardous Waste Coordinator
 - Duties
 - Provide proper storage area for 90-day storage of full hazardous waste drums
 - Provide proper hazardous waste labels and properly affix to waste container
 - Provide necessary manifest and LDR
 - Ensure containers are properly closed and lids secured
 - Follow up to ensure that return copy of signed manifest is received within 35 days

- Hazardous Waste Inspector
 - Duties (Inspect and record:)
 - If materials are stored in designated areas
 - Evidence of container leakage
 - Spillage in loading/unloading areas
 - Integrity of containment systems
 - Storage containers properly labeled and dated
 - Waste accumulation does not exceed 90 days
 - Condition of waste oil accumulation areas

- Hazardous Waste Inspector (continued)
 - Duties (Inspect and record:)
 - Adequate emergency response equipment
 - Condition of emergency response equip
 - Integrity of housekeeping measures at storage areas

Inspections will be conducted weekly. Any unsafe, unusual, or improprieties will be verbally communicated to the SPCCP Coordinator. All inspections will be documented.

Spill Contingency Plan:

If a release is detected, the employee should implement the following:

- Attempt to identify the source of the leak and stop it, if you can do it without <u>risk</u>.
- Notify Shift Foreman (hot end or cold end)
- Shift Foreman will evacuate and contact local rescue service, if necessary.
- <u>Depending on severity of the situation</u>, the Shift Foreman should immediately notify SPCCP Coordinator of the spill/release situation.

- SPCCP Coordinator will assess the spill/release and determine if can handle internally or need outside assistance.
- SPCCP Coordinator will communicate any spill situation to the appropriate authorities, after consulting with O-B Environmental Affairs.

- TEN TOP HAZARDOUS WASTE MISTAKES

√ 10 Misclassifying non-hazardous waste as hazardous (costs money), or hazardous waste as non-hazardous (risks penalties)

- TEN TOP HAZARDOUS WASTE MISTAKES

- √ 10 Misclassifying non-hazardous waste as hazardous (costs money), or hazardous waste as non-hazardous (risks penalties)
- ✓ 9 Accumulating waste over 90 days for LQG or 180 days for SQG

- TEN TOP HAZARDOUS WASTE MISTAKES

- ✓ 10 Misclassifying non-hazardous waste as hazardous (costs money), or hazardous waste as non-hazardous (risks penalties)
- ✓ 9 Accumulating waste over 90 days for LQG or 180 days for SQG
- ✓ 8 Accumulating too much waste at satellite accumulation points. 55 gal. is the limit

. FINAL DRAFT

WHY THESE INSTRUCTIONS MUST BE FOLLOWED PRECISELY

- 1. How this waste must be handled is precisely specified by State and Federal regulations. **IT IS THE LAW!!**
- 2. Proper waste management keeps you and your fellow workers safe.
- 3. Failure to follow good practices can result in stiff fines.
- 4. Internal inspections are being performed and documented.
- 5. Prompt action must be taken to correct noted deficiencies.
- 6. Following the specified practices is not optional. They must be followed precisely and they must be correct all the time. It is O-I policy and it is the law!!
- 7. O-I is committed to full compliance with environmental laws and regulations.
- 8. O-I management expects you do your part to be sure it is right.

Updated: January 12, 2004 Page 1 of 10

. FINAL DRAFT

TRAINING THAT IS COVERED BY THE INTERACTIVE LEARNING CENTER AND BY THE CORPORATE HEALTH AND SAFETY DEPARTMENT

- 1. Hazard Communication (including MSDS training)
- 2. Personnel Protective Equipment (PPE) and Hearing Protection
- 3. Emergency Evacuation and Spill Response
- 4. Respiratory Training (If Required)
- 5. Hazardous Waste Management.
- 6. Make sure that all of your employees are up to date on Items 1, 2, 3, 4, and 5. This includes records that prove training was successfully completed. The Environmental Supervisor needs to interface with Health and Safety personnel to understand whether these training requirements are being met.

Updated: January 12, 2004 Page 2 of 10

OILY WASTE SOLIDS MANAGEMENT (Rags and Absorbents)

- 1. Make sure that the hazardous waste label is visible and readable. (Trainer to illustrate the label.)
- 2. Read the label, only add waste that is listed on the label.
- 3. The drum must be closed except to add waste.
- 4. Keep the area clean. Wipe oil from the drum top, drum sides, and floor.
- 5. If the label is damaged or if there is a spill, or for more information, contact the Environmental Supervisor (Bill Boscacci) at ext. 2166 or on the radio.
- 6. Do not move drums without notifying the Environmental Supervisor, Bill Boscacci.

Updated: January 12, 2004 Page 3 of 10

, FINAL DRAFT

USED OIL WASTE MANAGEMENT

- 1. Make sure that the hazardous waste label is visible and readable. (Trainer to illustrate the label.)
- 2. Read the label, only add waste that is listed on the label.
- 3. The drum must be closed except to add waste.
- 4. Keep the area clean. Wipe oil from the drum top, drum sides, and floor.
- 5. If the label is damaged or if there is a spill, or for more information, contact the Environmental Supervisor (Bill Boscacci) at ext. 2166 or on the radio.
- 6. Do not move drums without notifying the Environmental Supervisor, Bill Boscacci.

Updated: January 12, 2004 Page 4 of 10

, FINAL DRAFT

INK AND SOLVENT WASTE MANAGEMENT

- 1. Make sure that the hazardous waste label is visible and readable. (Trainer to illustrate the label.)
- 2. Read the label, only add waste that is listed on the label.
- 3. Solvent drum:
- The drum must be closed except to add waste.
- Must keep in a flammable materials cabinet with a fire extinguisher nearby.
- Drum must be grounded.
- **4.** Keep the area clean. Wipe oil from the drum top, drum sides, and floor.
- 5. If the label is damaged or if there is a spill, or for more information, contact the Environmental Supervisor (Bill Boscacci) at ext. 2166 or on the radio.
- 6. Do not move drums without notifying the Environmental Supervisor, Bill Boscacci.

Updated: January 12, 2004 Page 5 of 10

. FINAL DRAFT

AEROSOL CAN WASTE MANAGEMENT

- 1. Make sure that the universal waste label is visible and readable. (Trainer to illustrate the label.)
- 2. Read the label, only add waste that is listed on the label.
- 3. Aerosol Can waste drum:
- The drum must be closed except to add waste.
- 4. Keep the area clean.
- 5. If the label is damaged or if there is a spill, or for more information, contact the Environmental Supervisor (Bill Boscacci) at ext. 2166 or on the radio.
- 6. Do not move drums without notifying the Environmental Supervisor, Bill Boscacci.

Updated: January 12, 2004 Page 6 of 10

. FINAL DRAFT

SWAB HEAD MANAGEMENT

- 1. Be sure the hazardous waste label is visible and readable. (Trainer to illustrate the label.)
- 2. Read the label, only add waste that is listed on the label.
- 3. The drum must be closed except to add waste.
- 4. If the label is damaged or if there is a spill, or for more information, contact the Environmental Supervisor (Bill Boscacci) at ext. 2166 or on the radio.
- 5. Do not move drums without notifying the Environmental Supervisor, Bill Boscacci.

To add swab head to the drum:

- Open the slide gate on the drum top below the cutter.
- Insert used swab into cutter blades and slide swab head back against blades.
- Cut swab head off and make sure it goes into the drum.
- After cutting last swab. Close slide gate on drum and dispose of handle for recycling.

Updated: January 12, 2004 Page 7 of 10

, FINAL DRAFT

BIN ACCUMULATION(EP Dust, Waste Batch Dust, Mold Dust and Oily Cullet)

- 1. Be sure the hazardous waste label is visible and readable. (Trainer to illustrate the label.)
- 2. Read the label, only add waste that is listed on the label.
- 3. The bin must be closed except to add waste.
- 4. Any questions about adding waste to bins should be brought to Bill Boscacci (the Environmental Supervisor) immediately.
- 5. Any spilled material should be immediately reported to the Environmental Supervisor for instructions on cleanup.
- 6. Contact the Environmental Supervisor, Bill Boscacci, at ext. 2166 or on the radio.

Updated: January 12, 2004 Page 8 of 10

AMMONIA, PROPANE, and DIESEL FUEL DELIVERIES (SECURITY GUARD INSTRUCTIONS)

1. Accept deliveries between the hours of 7:00 a.m. and 2:30 p.m. **WEEKDAYS ONLY**

If a truck arrives at other times, instruct the driver to return within these specified time periods.

2. Contact Bill Boscacci at ext. 2166 or by radio to advise him that a truck has arrived. Instruct the driver to wait until checked in by Bill or his designated assistant.

Jaime Moreno is the alternate contact if Bill is not available.

- 3. Advise the driver that he is not to connect for filling until instructed to do so by Bill or his assistant.
- 4. If an appropriate plant person is not available to oversee the unloading, instruct the driver to return when an appropriate person is available.

Updated: January 12, 2004 Page 9 of 10

. FINAL DRAFT

HAZARDOUS WASTE ACCUMULATION AREA

- 1. This door must be closed and locked except to add or remove waste.
- 2. Do not leave containers outside the locked containment area. Call the Environmental Supervisor, Bill Boscacci, at ext. 2166 for instruction on proper handling.
- 3. No material is to be placed in this area unless it is properly containerized and labeled.
- 4. Containers must be clean sealed and properly labeled.
- 5. Containers must be stored so each label is clearly visible and readable in its designated area.
- 6. Spilled material must be cleaned up immediately according to instructions from Bill Boscacci.
- 7. If any of the above are not correct, if there is a spill, or for more information, contact Bill Boscacci, at ext. 2166 or on the radio.
- 8. Do not move drums without notifying Bill Boscacci.
- 9. In case of emergency, call security or plant emergency at ext. 2020.

I:\owens\training\workerinstructions.rev073101.doc

Updated: January 12, 2004 Page 10 of 10

Attachment 3


Recycling of EP dust and Glass bead blast

EP Dust


Owens claims an exemption according to § 25143.2(b) (3) for the EP dust because it is material derived from the process being returned to the process. The material is not reclaimed, rather it is used in its original form as a raw material feedstock. Under California's statute, Owens qualifies for the waste exemptions, pursuant to Health and Safety code (HSC) § 25143.2(b), which says:

- (b) Except as otherwise provided in subdivisions (e), (f), and (g), recyclable material that is managed in accordance with Section 25143.9 and is or will be recycled by any of the following methods shall be excluded from classification as a waste:
- (1) Used or reused as an ingredient in an industrial process to make a product if the material is not being reclaimed.
- (2) Used or reused as a safe and effective substitute for commercial products if the material is not being reclaimed.
- (3) Returned to the original process from which the material was generated, without first being reclaimed, if the material is returned as a substitute for raw material feedstock, and the process uses raw materials as principal feed-stocks.

EP dust is raw material used to manufacture glass that is collected in the electrostatic precipitator and transferred automatically via pipe to a silo in the batch house where it is mixed into the batch.




Pipe used to transfer EP dust



EP silo in the batch house

Glass bead blast

Owens claims an exemption for the glass bead blast according to § 25143.2(b) (1) because it is a substitute material. Glass bead blast is brought for the purpose of bead blasting bottle molds smooth. The shattered glass beads are collected from the bead blast machine into storage hoppers and transferred to the batch house.



As these photos show the storage containers and transfer containers are labeled "Excluded Recyclable Material" which satisfy the requirements of § 25143.9(a) which states,

A recyclable material shall not be excluded from classification as a waste pursuant to subdivision (b) or (d) of Section 25143.2, unless all of the following requirements are met:

- (a) If the material is held in a container or tank, the container or tank is labeled, marked, and placarded in accordance with the department's hazardous waste labeling, marking, and placarding requirements which are applicable to generators, except that the container or tank shall be labeled or marked clearly with the words "Excluded Recyclable Material" instead of the words "Hazardous Waste," and manifest document numbers are not applicable. If the material is used oil, the containers, aboveground tanks, and fill pipes used to transfer oil into underground storage tanks shall also be labeled or clearly marked with the words "Used Oil".
- (b) The owner or operator of the business location where the material is located has a business plan that meets the requirements of Section 25504, including, but not limited to, emergency response plans and procedures, as described in subdivision (b) of Section 25504, which specifically address the material or that meet the department's emergency response and contingency requirements which are applicable to generators of hazardous waste.
- (c) The material shall be stored and handled in accordance with all local ordinances and codes, including, but not limited to, fire codes, governing the storage and handling of the hazardous material. If a local jurisdiction does not have an ordinance or code regulating the storage of the material, including, but not limited to, an ordinance or code requiring secondary containment for hazardous material storage areas, the material shall be stored in tanks, waste piles, or containers meeting the department's interim status regulations establishing design standards applicable to tanks, waste piles, or containers storing hazardous waste.

Additionally, our Business Plan includes the material in the material inventory list and the emergency response plan addresses the material specifically. The material is stored and handled in compliance with local ordinances and codes.

8349	OMPTIFIED	Service MAIL REC nly; No Insurance (EIPT Coverage Provided)
4540	≧:s age Certinos Fee		Postmark
0005	Niture Receipt Fee Endo Jement Regured Restricted Delivery Fee Endonement Regured		Here
0350	Total Postage & Fees Servito	\$ Ulinois Co.	Clare & Cant
7007	Street, Apt No. 36/ Oity State ZIP+4 PS Form 3800, January 20	il alameda Klan E. C	Avenue A 94601 See Reverse for Instructions



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, CA 94105

CERTIFIED MAIL NO.
RETURN RECEIPT REQUESTED

In reply, refer to: EPA ID No. CAT000618918

WARNING LETTER

Bill Boscacci Environmental Engineer Owens Illinois, Oakland Plant 3600 Alameda Avenue Oakland, CA 94601

Dear Mr. Boscacci:

On February 24, 2004, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency (U.S. EPA) at Owens Illinois, Oakland Plant, with EPA ID number CAT000618918 (O-I or the "facility"). During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act (RCRA), as amended [42 U.S.C. 6927].

A copy of the RCRA Compliance Evaluation Inspection Report (the "report") is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with the RCRA regulations and potential violations of the California authorized program under RCRA Subtitle C. Any omissions in the report shall not be construed as a determination of compliance with applicable regulations.

MAIL CODE	WST-3 WST-3
SURNAME	Result Leurian
DATE	4/20/04 4/30/04

U.S. EPA CONCURRENCES

OFFICIAL FILE COPY



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX 75 Hawthorne Street San Francisco, CA 94105

7 /

MAY 0 3 2004

CERTIFIED MAIL \$7001 0320 0002 4540 8349 RETURN RECEIPT REQUESTED

In reply, refer to: EPA ID No. CAT000618918

WARNING LETTER

Bill Boscacci Environmental Engineer Owens Illinois, Oakland Plant 3600 Alameda Avenue Oakland, CA 94601

Dear Mr. Boscacci:

On February 24, 2004, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency (U.S. EPA) at Owens Illinois, Oakland Plant, with EPA ID number CAT000618918 (O-I or the "facility"). During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act (RCRA), as amended [42 U.S.C. 6927].

A copy of the RCRA Compliance Evaluation Inspection Report (the "report") is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with the RCRA regulations and potential violations of the California authorized program under RCRA Subtitle C. Any omissions in the report shall not be construed as a determination of compliance with applicable regulations.

Pursuant to Section 3008 of RCRA [42 U.S.C. 6928], you are required to correct the identified areas of noncompliance and to submit the documentation of their correction to U.S. EPA within 30 calendar days from the date of this letter. Please provide the following requested information:

- 1. Photograph showing that the spent solvent accumulated in one liter containers for cleaning ink heads are properly labeled, pursuant to 22 CCR § 66262.34(e).
- 2. A written description of training provided to hazardous waste handlers that includes their specific emergency procedures (e.g., containment and/or cleanup of spills), pursuant to 22 CCR § 66265.16 (a)(2).
- 3. Provide a description and certification of compliance related to your recycling of EP dust and bead blast dust with California Health and Safety Code Section 25143.9, which says in part:
 - (a) If the material is held in a container or tank, the container or tank is labeled, marked, and placarded in accordance with the department's hazardous waste labeling, marking, and placarding requirements which are applicable to generators, except that the container or tank shall be labeled or marked clearly with the words "Excluded Recyclable Material" instead of the words "Hazardous Waste," and manifest document numbers are not applicable.
 - (b) The owner or operator of the business location where the material is located has a business plan that meets the requirements of Section 25504, including, but not limited to, emergency response plans and procedures, as described in subdivision (b) of Section 25504, which specifically address the material or that meet the department's emergency response and contingency requirements which are applicable to generators of hazardous waste.
 - (c) The material shall be stored and handled in accordance with all local ordinances and codes, including, but not limited to, fire codes, governing the storage and handling of the hazardous material. If a local jurisdiction does not have an ordinance or code regulating the storage of the material, including, but not limited to, an ordinance or code requiring secondary containment for hazardous material storage areas, the material shall be stored in tanks, waste piles, or containers meeting the department's interim status regulations establishing design standards applicable to tanks, waste piles, or containers storing hazardous waste.

Your response must include a letter signed by a duly authorized official of your facility, certifying correction of the identified areas of noncompliance. Where compliance cannot be achieved within 30 days, you must provide the reasons for the delay, a description of the corrective action planned and a schedule on which a corrective action will be taken.

By copy of this letter, U.S. EPA is providing the State of California with notice of the referenced violations of Subtitle C of RCRA. This letter shall not be construed as a

determination by U.S. EPA of your compliance with any other applicable regulations. O-I should continue to take the necessary steps to maintain and ensure compliance with all applicable Federal, State and local environmental requirements.

U.S. EPA routinely provides copies of inspection reports to State agencies, and upon request, to the public. Such releases will be handled according to the Freedom of Information Act regulations (40 CFR Part 2). If you believe this report contains privileged or confidential information, you may make a claim within fourteen (14) working days from the date of this letter. U.S. EPA will construe your failure to furnish a timely claim as a waiver of the confidentiality claim.

Your response to this Warning Letter, due within 30 calendar days from the date of this letter, shall be mailed to:

Nancy Rumrill, WST-3 U.S. EPA, Region 9 75 Hawthorne Street San Francisco, CA 94105

If you have questions related to the report or this letter, please contact Nancy Rumrill at (415) 972-3293.

Sincerely,

oren Henning, Manager

RCRA Enforcement Office

Enc.

cc (w/enc): Charles McLaughlin, State Regulatory Program Division, DTSC



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX

75 Hawthorne Street San Francisco, CA 94105

RCRA COMPLIANCE EVALUATION INSPECTION REPORT

Date of Inspection:

February 24, 2004

U.S. EPA Inspectors:

Nancy Rumrill

Environmental Engineer

Ron Brown

Environmental Protection Specialist

FACILITY INFORMATION

EPA ID Number:

CAT000618918

Name:

Owens Brockway Glass Containers, Plant 20

Location:

3600 Alameda Ave

Oakland, CA 94601

Representative:

William L. Boscacci

Environmental Engineering Supervisor

Phone:

(510) 436-2166

Report Prepared By:

Nancy Rumrill

Report Date:

April 16, 2004

A. INTRODUCTION

This report documents the routine RCRA Compliance Evaluation Inspection (CEI) of Owens Brockway Glass Containers, Plant 20 with EPA ID number CAD 000 618 918 (Owens or the facility), located at 3600 Alameda Ave, Oakland, California. The United States Environmental Protection Agency, Region 9, (EPA) inspected the facility to evaluate compliance with the applicable regulations in Title 22 California Code of Regulations (CCR) Division 4.5 and Title 40 Code of Federal Regulations (CFR) Parts 261 through 266, 268, 270 and 279.

B. INVESTIGATION

On February 24, 2004, Nancy Rumrill and Ron Brown of EPA conducted the inspection of the facility. EPA inspectors provided the facility representative, William Boscacci, a copy of EPA's Information Sheet for Small Businesses. During the opening interview, Mr. Boscacci briefly described the facility's operations. After that, the EPA inspectors conducted the inspection of the facility's operation and waste activities.

1. Background

The facility submitted a Notification of Hazardous Waste Activity (EPA Form 8700-12) in March, 1987. According to the California Department of Toxics Control Substances (DTSC) Hazardous Waste Tracking System, the facility has shipped various RCRA wastes including D001, D002, D007, D008, D039, and F002 in the last three years. According to the facility representative, the facility is a large quantity generator of RCRA hazardous waste.

2. Operations and Waste Generation Description

The facility manufactures UV green, dead leaf green, and clear glass bottles: currently 80% are wine bottles, and the rest are apple juice and salsa bottles. The process consists of three furnaces, forming machines, annealing ovens, automatic inspection, bottle marking, packaging, and shipment. In 2003, the facility generated approximately 210,000 tons of glass. Approximately 400 employees work at the facility.

The facility typically generates used oil, electrostatic precipitator (EP) dust, grit blast dust, waste solvent, waste paint, and safety kleen naphtha. The furnaces that produce colored glass exhaust to an electrostatic precipitator. Owens generates EP dust, which is a RCRA D008, D007 and recently a D006 waste, from clean-out of the control device and bead blast dust, which is a RCRA D008 and D007 waste, from cleaning or reconditioning glass molds. Owens also generates solvent waste, which is a RCRA D039 and D001 waste, from cleaning ink heads for marking bottles and used oil, a non-RCRA California only hazardous waste, from equipment maintenance and swap heads used to lubricate the glass molds.

Owens does not currently accumulate EP dust and bead blast dust because they are able to

reuse it as a feed material in the furnace, and, therefore, they claim to qualify for the recycling exemption, pursuant to California's Health and Safety code (HSC) 25143.2 (b) (see also 40 CFR §261.2 (e)). This exemption states:

- (b) Except as otherwise provided in subdivisions (e), (f), and (g), recyclable material that is managed in accordance with Section 25143.9 and is or will be recycled by any of the following methods shall be excluded from classification as a waste:
- (1) Used or reused as an ingredient in an industrial process to make a product if the material is not being reclaimed.
- (2) Used or reused as a safe and effective substitute for commercial products if the material is not being reclaimed.
- (3) Returned to the original process from which the material was generated, without first being reclaimed, if the material is returned as a substitute for raw material feedstock, and the process uses raw materials as principal feedstocks.

The facility representative has not yet provided information that they are managing the material in accordance with HSC Section 25143.9.

3. Walk-through

In the selective maintenance area, EPA inspectors observed the satellite location where solvent is used to clean ink heads for the glass marking process. EPA inspectors observed four one-liter bottles of waste solvent, which were not properly labeled and one of them was open. During the walk-through, EPA inspectors did not document any other potential violations.

4. Record Review

EPA inspectors reviewed manifests from the last three years, Land Disposal Restriction notifications, the Contingency Plan, and Training records. EPA inspectors found that the training program did not adequately document how Mike Burns and Kirk Washington, who are hazardous waste handlers, are trained in emergency procedures such as their response procedures related to spills, fire, or other contingencies. EPA inspectors did not document any other potential violations.

C. POTENTIAL RCRA VIOLATIONS

1. <u>Labeling Satellite Containers.</u>

22 CCR § 66262.34(e) (40 CFR § 262.34(e))

(e) (1) A generator may accumulate as much as 55 gallons of hazardous waste, one quart of acutely hazardous waste (listed in section 66261.33(e)) or one quart of extremely hazardous waste at or near any point of generation, without a permit or grant of interim status, without

complying with subsections (a), (b) and (c) of this section, if all of the following requirements are met with respect to this waste:

- (C) the initial date of waste accumulation is clearly marked and visible for inspection on each container used for accumulation of hazardous waste;
- (E) the generator complies with subsections (e)(2), (e)(3) and (f)(3) of this section.
- (f) Generators who accumulate hazardous waste on site without a permit or grant of interim status shall comply with the following requirements:
- (3) each container and tank used for onsite accumulation of hazardous waste shall be labelled or marked clearly with the words, "Hazardous Waste." Additionally, all containers and portable tanks shall be labelled with the following information:
- (A) composition and physical state of the wastes;
- (B) statement or statements which call attention to the particular hazardous properties of the waste (e.g., flammable, reactive, etc.);
- (C) name and address of the person producing the waste.

Finding:

In the selective maintenance area, EPA inspectors observed the satellite location where solvent is used to clean ink heads for the glass marking process. EPA inspectors observed four one-liter bottles of waste solvent, which were not properly labeled and one of them was open. Owens failed to label satellite containers in violation of 22 CCR §66262.34(e)(1)(C), (E), and (f)(3).

2. Open Satellite Container.

22 CCR § 66262.34(e) (40 CFR § 262.34(e))

- (e) (1) A generator may accumulate as much as 55 gallons of hazardous waste, one quart of acutely hazardous waste (listed in section 66261.33(e)) or one quart of extremely hazardous waste at or near any point of generation, without a permit or grant of interim status, without complying with subsections (a), (b) and (c) of this section, if all of the following requirements are met with respect to this waste:
 - (D) the generator complies with sections 66265.171, 66265.172, and 66265.173(a) of this division.

22 CCR § 66265.173. Management of Containers. (40 CFR § 265.173)

(a) A container holding hazardous waste shall always be closed during transfer and storage, except when it is necessary to add or remove waste.

Finding:

In the selective maintenance area, EPA inspectors observed the satellite location where solvent is used to clean ink heads for the glass marking process. EPA inspectors observed four one-liter bottles of waste solvent, which were not properly labeled and one of them was open. Owens failed to close a satellite container in violation of 22 CCR §§66262.34(e)(1)(D) and 66265.173(a).

In a letter dated March 9, 2004, the facility representative confirmed that the container has been closed (see attachment 2).

3. Training Personnel.

22 CCR § 66262.34 (40 CFR § 262.34)

- (a) Except as provided in subsection (c) and (d) of this section and section 66262.35, a generator may accumulate hazardous waste on-site for 90 days or less without a permit or grant of interim status, provided that:
- (4) the generator complies with the requirements for owners or operators in articles 3 and 4 of chapter 15 of this division and with section 66265.16, and with section 66268.7(a)(5).

22 CCR § 66265.16. Personnel Training. (40 CFR § 265.16)

(a)(2) This program shall be directed by a person trained in hazardous waste management procedures, and shall include instruction which teaches facility personnel hazardous waste management procedures (including contingency plan implementation) relevant to the positions in which they are employed.

Finding:

EPA inspectors found that the training program did not adequately document how Mike Burns and Kirk Washington, who are hazardous waste handlers, are trained in emergency procedures such as their response procedures related to spills, fire, or other contingencies. Owens failed to show that their hazardous waste handlers were adequately trained in hazardous waste management procedures (including contingency plan implementation) relevant to their positions in violation of 22 CCR §§66262.34(a) and 66265.16 (a)(2).

D. LIST OF ATTACHMENTS

Letter from Owens Illinois dated March 9, 2004

ATTACHMENT



Bill Boscacci Environmental Engineer Owens Illinois, Oakland Plant 3600 Alameda Avenue Oakland, CA 94601 (510) 436- 2166

Nancy Rumrill
Enforcement Officer
Environmental Protection Agency
WST-3
75 Hawthorne Street
San Francisco, CA 94105

Dear Ms. Rumrill,

You will find enclosed with this letter the laboratory results of a sample of the material in the drums you observed in our 90-day Hazardous Waste Storage Area. As you can see from the results the material is non-hazardous. This material will be disposed of with our non-hazardous waste.

Also, I would like to update you on the three other items of concern that you noted during your inspection of our facility on February 24, 2004.

- 1. You observed the used ink receptacle on the printer head cleaning machine had a connection on the return line that was open to the atmosphere. We have devised a new return line that seals this connection.
- 2. You expressed concern that the training documentation did not cover all of the training required of a Hazardous Waste mover. This is because we train using different modules (Hazardous Communication, Spill Response, and Hazardous Materials Management) and documented that training occurred under a single heading of Hazardous Materials Management. You have indicated that the preferred training method is train from a single program that includes the different modules and document that training was done from that single program. We have developed that inclusive training program and will train from it in the future.

3. You observed a bucket containing used swab heads and mold dope at the C-Forming Hazardous Waste Satellite Accumulation Area which had no labels designating the contents. This bucket was used to transfer used swab heads from the generation point to the Satellite Accumulation Area, so that oil would not drip on the floor. It was used more than once a shift. The Department Supervisor has determined the practice unnecessary and it has been terminated.

I hope our actions meet with your satisfaction, if there is anything you would like for me to change let me know. Although EPA inspections can be difficult to endure it does give me a certain amount of satisfaction to receive a complement from the inspector that we are well organized and our compliance programs are working.

Sincerely,

Bill Boscacci

Environmental Engineer

WI Boscoci

Owens-Illinois

Cc: Dwayne Wendler Plant Manager



California Title 26 Metals 170837 Project#: STANDARD Lab #: Client: Owens Brockway Field ID: DESICANT BEADS Basis: as received Lab ID: 170837-001 Diln Fac: 1.000 Matrix: Miscell. Sampled: 02/23/04

Received:

02/26/04

Analyte	Result	RL	Batch#	Prepared	Analyzed	Prep	Analysis
Antimony	ND	3.3	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Arsenic	1.7	0.27	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Barium	ND	0.55	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Beryllium	0.17	0.11	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Cadmium	ND	0.27	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Chromium	ND	0.55	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Cobalt	ND	1.1	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Copper	1.4	0.55	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Lead	ND	0.16	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Mercury	ND	0.019	89 101	03/08/04	03/08/04	METHOD	EPA 7471
Molybdenum	ND	1.1	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Nickel	ND	1.1	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Selenium	ND	0.27	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Silver	ND	0.27	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Thallium	ND	0.27	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Vanadium	1.2	0.55	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B
Zinc	7.5	1.1	88 920	03/01/04	03/02/04	EPA 3050	EPA 6010B

Units:

mg/Kg

				•
			•	

California Home



Home

Information Resources

My Community

Get involved

Public Notices

Calendar

Cleaning Up Sites

Managing Waste

Assessing Risk

Preventing Pollution
Evaluating Technology

Laws, Regs & Policies

Press Room

Publications & Forms

Employment Contact Us

Site Map

Department of Toxic Substances Control

DTSC: HWTS Reports

HWTS - RCRA Waste Code By Year Matrix

EPA ID: CAT000618918 Name: OWENS-ILLINOIS INC

OAKLAND PLT 20

Entity: Generator





Tuesday, October 26, 2010

RCRA	Description	L	Weight (in Tons)																
Code		1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010
	Blank/Unknown	997.68750	738.23230	76.57900	95,93840	80.53450	\$9.87600	520,39200	288,98540	214,66570	213.06290	<u>243.63758</u>	22.17110	45.62698	36,11414	124,22158	35,46960	81.86010	21.34800
	Blank/Unknown														2.30435				
D 001	Ignitable	6.68030	0.61000	0.54100		0.26400	0.20000		0.30000	0.96500	0.60465	0.81350	0.78300	0.77150	0.10800				
D002	Corrosives	1.63000	3.90750	1.20000	2.10000	1.70000	2.08500	7.67200	0.01000	4.03150	0,45000				0.04170				
D006	Cadmium			12.64200	25.28400	58,99600	30,50880						52.21120	<u>72.90680</u>	15.77040			47.19680	
D007	Chromium			16.85600		21.07000	19.38440	136,53360	78.48080		25,28400	160.13200	281,85600	1,622.75000	0.84280			10.50000	
D008	Lead						33.71200	139.81200	29.49800	123,04880	54.88200	166,87440	16.85600		15.17040	8.42800	34.05640	64.95060	20,85000
D 010	Selenium								0.00500							137.66240	19.68140	10.11360	8.42800
D039	Tetrachloroethylene		2.05150	3,65660	1.03810	0.53350	2.51850	0.08400	1.90680	5.05870	0.22509	0.08340							
F002	Halogenated solvents	0.52000	0,24750						0.05000	0.09000									
F003	Non-halogenated solvents				0.90000														
F005	Non-halogenated solvents				0.30000											0.18150	0.18150	0.19800	
NONE	Blank/Unknown												12.97874	17.61976					
	TOTALS	1,006.51780	745.04880	111.47460	125.56050	163.09800	178.28470	804.49360	399.23600	347.85970	294.50864	571.54088	386.85604	1,759.67504	70.35179	270.49348	89.38890	214.81910	50.62600

Waight (in Tong)



TOP



Cal/EPA | Air Resources Board | California Integrated Waste Management Board | Department of Pesticide Regulation Office of Environmental Health Hazard Assessment | State Water Resources Control Board

Conditions of Use | Privacy Policy | E-mail Webmaster

The content found herein may not necessarily represent the views and opinions of the Schwarzenegger Administration.

© 2003 State of California.



Department of Toxic Substances Control

9

Jesse R. Huff, Director 700 Heinz Avenue, Bldg. F, Suite 200 Berkeley, California 94710-2721

Pete Wilson Governor Peter M. Rooney Secretary for Environmental Protection

August 20, 1998

Mr. Leroy Griffin City of Oakland, Office of Emergency Services One City Hall Plaza Oakland, California 94612

Dear Mr. Griffin:

On April 9, 1998, the United States Environmental Protection Agency (U.S. EPA) conducted a hazardous waste generator inspection at Owens-Brockway Glass Containers, 3600 Alameda Avenue, Oakland. Please find attached to this letter a copy of U.S. EPA's inspection report issued by Mr. Clint Seiter. This inspection report may contain potential non-RCRA violations noted during the inspection as well as violations of RCRA regulations.

Should potential violations be noted in the report, the City of Oakland is expected to take appropriate enforcement to ensure compliance with applicable hazardous waste laws and regulations. Please be advised that this report may contain confidential trade secret information which must be handled in accordance with the requirements of California Health and Safety Code (H&SC), Section 25173.

Should you have any questions regarding the transmittal of this inspection report or the requirements of H&SC, Section 25173 please feel free to contact Mickey Pierce at (510) 540-3851. Questions regarding the contents or potential violations noted in the report should be addressed to Mr. Clint Seiter, U.S. EPA, Region 9, at (415)744-2141.

Sincerely,

Lawrence Wong, Section Chief
State Regulatory Programs Division

Northern California Branch

Attachment

bcc: Mr. Clint Seiter, WST-3-1
Waste Compliance Branch
U.S. EPA, Region 9
75 Hawthorne Street
San Francisco, California 94105

Mr. Steve Armann, WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, California 94105

Mr. Charles A. McLaughlin, Chief Northern California Branch State Regulatory Programs Division Department of Toxic Substances Control 10151 Croydon Way, Suite 3 Sacramento, California 95827-2106

Ms. Paula Rasmussen, Chief State Regulatory Programs Division Department of Toxic Substances Control 5796 Corporate Avenue Cypress, California 90630



Department of Toxic Substances Control

9

Jesse R. Huff, Director 700 Heinz Avenue, Bldg. F, Suite 200 Berkeley, California 94710-2721

Pete Wilson Governor

August 20, 1998

Peter M. Rooney Secretary for Environmental Protection

Mr. Hugh Murphy Hayward City Fire Department 777 "B" Street Hayward, California 94541

Dear Mr. Murphy:

On April 13, 1998, the United States Environmental Protection Agency (U.S. EPA) conducted a hazardous waste generator inspection at Owens-Brockway Glass Containers, 22302 Hathaway Avenue, Hayward. Please find attached to this letter a copy of U.S. EPA's inspection report issued by Mr. Clint Seiter. This inspection report may contain potential non-RCRA violations noted during the inspection as well as violations of RCRA regulations.

Should potential violations be noted in the report, the City of Hayward is expected to take appropriate enforcement to ensure compliance with applicable hazardous waste laws and regulations. Please be advised that this report may contain confidential trade secret information which must be handled in accordance with the requirements of California Health and Safety Code (H&SC), Section 25173.

Should you have any questions regarding the transmittal of this inspection report or the requirements of H&SC, Section 25173 please feel free to contact Mickey Pierce at (510) 540-3851. Questions regarding the contents or potential violations noted in the report should be addressed to Mr. Clint Seiter, U.S. EPA, Region 9, at (415) 744-2141.

Sincerely,

Lawrence Wong, Section Chief

State Regulatory Programs Division

Northern California Branch

Attachment

bcc: Mr. Clint Seiter, WST-3-1
Waste Compliance Branch
U.S. EPA, Region 9
75 Hawthorne Street
San Francisco, California 94105

Mr. Steve Armann, WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, California 94105

Mr. Charles A. McLaughlin, Chief Northern California Branch State Regulatory Programs Division Department of Toxic Substances Control 10151 Croydon Way, Suite 3 Sacramento, California 95827-2106

Ms. Paula Rasmussen, Chief State Regulatory Programs Division Department of Toxic Substances Control 5796 Corporate Avenue Cypress, California 90630



Department of Toxic Substances Control

Jesse R. Huff, Director 700 Heinz Avenue, Bldg. F, Suite 200 Berkeley, California 94710-2721

Pete Wilson Governor

August 20, 1998

Peter M. Rooney Secretary for Environmental Protection

Mr. Leroy Griffin City of Oakland, Office of Emergency Services One City Hall Plaza Oakland, California 94612

Dear Mr. Griffin:

On April 9, 1998, the United States Environmental Protection Agency (U.S. EPA) conducted a hazardous waste generator inspection at Owens-Brockway Glass Containers, 3600 Alameda Avenue, Oakland. Please find attached to this letter a copy of U.S. EPA's inspection report issued by Mr. Clint Seiter. This inspection report may contain potential non-RCRA violations noted during the inspection as well as violations of RCRA regulations.

Should potential violations be noted in the report, the City of Oakland is expected to take appropriate enforcement to ensure compliance with applicable hazardous waste laws and regulations. Please be advised that this report may contain confidential trade secret information which must be handled in accordance with the requirements of California Health and Safety Code (H&SC), Section 25173.

Should you have any questions regarding the transmittal of this inspection report or the requirements of H&SC, Section 25173 please feel free to contact Mickey Pierce at (510) 540-3851. Questions regarding the contents or potential violations noted in the report should be addressed to Mr. Clint Seiter, U.S. EPA, Region 9, at (415)744-2141.

Sincerely

Lawrence Wong, Section Chief
State Regulatory Programs Division

Northern California Branch

Attachment

bcc: Mr. Clint Seiter, WST-3-1
Waste Compliance Branch
U.S. EPA, Region 9
75 Hawthorne Street
San Francisco, California 94105

Mr. Steve Armann, WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, California 94105

Mr. Charles A. McLaughlin, Chief Northern California Branch State Regulatory Programs Division Department of Toxic Substances Control 10151 Croydon Way, Suite 3 Sacramento, California 95827-2106

Ms. Paula Rasmussen, Chief State Regulatory Programs Division Department of Toxic Substances Control 5796 Corporate Avenue Cypress, California 90630



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street San Francisco, CA 94105-3901

August 17, 1998 In reply, refer to WST-3-1

Owens-Brockway Glass Containers P.O. Box 1019 Oakland, CA 94604

Attn: Mr. Hank Wiegel, Plant Engineer

Re: Certification of Violation Correction for Owens-Brockway Glass Containers, Oakland, California

Dear Mr. Wiegel:

On April 9, 1998, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency (U.S. EPA) at Owens-Brockway Glass Containers, Oakland, CA, U.S. EPA ID # CAT000618918. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act (RCRA), as amended [42 U.S.C. 6927].

Pursuant to Section 3008 of RCRA [42 U.S.C. 6928] U.S. EPA required you to correct the identified areas of noncompliance and to submit documentation of their correction to the U.S. EPA.

The facility's subsequent responses, dated August 12, 1998, adequately addresses the violations and documents the facility's return to compliance with the regulations cited in the inspection report. This letter shall not be construed as a determination by U.S. EPA of your compliance with any other applicable regulations.

Owens-Brockway should continue to take the necessary steps to maintain and ensure compliance with all applicable Federal, State and local environmental requirements.

If you have any questions please call Clint Seiter of my staff at (415) 744-2141.

Sincerely,

Ron Brown, Acting Chief Compliance Monitoring and

Enforcement Section

cc: Paula Rasmussen, DTSC

ę .

PAT OCE 619 918

RCRA COMPLIANCE INSPECTION REPORT

U.S. ENVIRONMENTAL PROTECTION AGENCY, REGION 9

HAZARDOUS WASTE MANAGEMENT DIVISION

WASTE COMPLIANCE EVALUATION

Purpose:

RCRA Compliance Evaluation

Facility:

Owens-Brockway Glass Containers

3600 Alameda Ave. Oakland, CA 94601

EPA ID Number:

CAT000618918

Date of Inspection:

April 9, 1998

EPA Representative:

Clint Seiter

Environmental Protection Specialist

(415) 744-2141

City of Oakland

Hernan Gomez

Fire Services Agency

Hazardous Materials Inspector

Representative:

(510) 238-7253

Facility Representative:

Hank Wiegel Plant Engineer

(510) 436-2181

Report Prepared By:

Clint Seiter

Report Date:

June 16, 1998

BACKGROUND

Owens-Brockway Glass Containers, a unit of Owens-Illinois, is a glass manufacturing facility located at 3600 Alameda Avenue, Oakland, CA 94601. It has been in operation for approximately sixty years and employs approximately 500 people. 70% of the facility's product line consists of wine bottles, with the remainder being food and beverage bottles. The facility has three furnaces, each furnace devoted exclusively to a particular color of glass (green, amber and clear (or flint)). Most of the bottles manufactured come from recycled glass (cullet), which is ground down and remelted, with the remainder glass made on site from silica sand mixed with salt cake, soda ash, limestone, and colorizers or de-colorizers. Approximately 875 tons of glass containers are manufactured every working day. Each furnace has an approximate 450 ton holding capacity for molten glass. Furnaces attain a temperature of 2750 degrees to achieve proper melting of the raw materials.

The facility operates forty forklifts, three trucks, one bobcat and two payloaders, which are maintained on the site.

MANUFACTURING PROCESS

Raw materials are blended together in batches in the proper proportions for the desired quality of glass. The batches are transported via closed conveyor belts to the facility furnaces, where the batch material is melted down to molten glass. The molten glass is drawn from the bottom of the furnace, via the throat to feeders. Orifices in the feeders control the amount of molten glass let through, and shears cut off the bottoms of the gobs (discreet units of molten glass) to the desired length (the weight of the gob is determined to an accuracy of one hundreth place). The gobs are first formed into blanks, called "parisons", which are then transferred into molds (two at a time) in machines called shops (there is a total of eight shops in the facility). The molds in each shop can be configured to whatever specifications are required for the particular bottle. Bottles are formed when compressed air is blown into the molds containing the gobs. The bottles then go through an annealing process where they are reheated in lehrs to temperatures up to 1030 degrees and then gradually cooled down. After the bottles are sufficiently cooled, they are sprayed with a poly-coat mixture that increases the bottles' lubricity (scratch resistance).

The bottles are then checked by means of optical equipment for various potential defects (irregular wall thickness, blisters, cracks, specks, etc.) and defective bottles are removed from the assembly line (to be recycled as cullet). The bottles that pass inspections are eventually packaged and transported off to the customers.

WASTES GENERATED

The following wastes are generated at the facility

1. Used Oil: The hot glass is quenched by water as it is ejected out of the shop. This water picks

up lubricating oil from the shop machinery, and before the water is recycled, it is directed to a skim pond. Used oil is skimmed off the pond and diverted to an above-ground tank. Used oil is also generated through routine vehicular maintenance at the vehicle maintenance center.

- 2. Checker Dust: Dust contaminated with chromium and lead (from crushed cullet) accumulates on the bottom of the exhaust chambers that flank the furnaces. Approximately once every three years this dust is vaccuumed out and shipped off to be disposed of as D007 and D008 waste.
- 3. Methyl Ethyl Ketone (MEK): MEK used as a solvent for bottle coders eventually gets contaminated to the point where it has to be disposed of periodically as a D035 waste.
- 4. EP dust: Dust from the furnace exhaust is collected on electrostatic plates in the exhaust ducts. It generally is recycled into the batches used to make glass, but occasionally, due to recycling system breakdowns, it must be transported off-site for disposal as a D002 waste.

INVESTIGATION

On April 9, 1998, Clint Seiter, representing the Environmental Protection Agency (EPA), and Hernan Gomez, representing the City of Oakland Fire Services Agency, conducted an unannounced site investigation at the Owens-Brockway facility (EPA ID# CAT000618918), located at 3600 Alameda Ave., Oakland, CA 94601. Upon providing introductions and credentials, the inspectors contacted Mr. Hank Wiegel, the Plant Engineer of the facility. Also in attendance was Mr. Steve Springer, the facility general foreman. The inspectors explained that this was a routine inspection to determine whether or not the facility was in compliance with federal and state regulations concerning the proper management of RCRA and non-RCRA hazardous wastes. The inspection would consist of a walk-through of those areas of the facility where hazardous wastes were handled, with photos taken, followed by a record review.

Pre-Walk-Through Briefing

The facility representatives described the manufacturing process (as described above) to the inspectors. Per these representatives, enough waste is generated to qualify the facility as a Large Quantity Generator (LQG).

Walk-Through Inspection

- Raw Material Delivery

The walk-through inspection began where raw materials that make up the glass are received. Trucks delivering these materials deposit their loads through grates onto conveyor belts. The inspectors noted deposits of salt cake (anhydrous sodium sulfate) packed on the pavement surrounding the grate where this substance is off-loaded (photo 1). (The facility reps have since provided documentation that this has been cleaned up (see Attachment 2).) A post-inspection

review of the MSDS for salt cake has indicated that this substance is not a hazardous material (see Attachment 3). Cullet is kept in bins, segregated by color, until ready for use (photo #2). The conveyor belts, which transport the materials to the furnaces, are enclosed and vacuumed daily (the dust vacuumed up is re-entered into the manufacturing process).

- Used Oil Tanks #1 and #2

As mentioned above, water used to quench hot glass becomes contaminated with lubricating oil from the machinery (photo #3). The water from the quench water bins is routed to two skim sumps (photo #4), where the used oil is skimmed and pumped to two interior above-ground used oil tanks adjacent to the sumps. After the oil has been skimmed off the water in the sumps, the water is pumped to an exterior skim pond. These two used-oil tanks (Tank #1 and Tank #2) are located in the facility basement. Whereas Tank #1 (see photo #5) was correctly identified as containing non-RCRA hazardous waste, it was not marked with the words "Used Oil", as is required by Title 22 §66279.21 (this was subsequently corrected by the facility (see Attachment 2)). All other labeling requirements were in order. Similarly, while Tank #2 was also correctly identified as containing non-RCRA hazardous waste, it was not labeled with the words "Used Oil" (see photo #6). As with Tank #1, this has subsequently been corrected (see Attachment 2). Fire extinguishers were mounted close by and their tags indicated that they had been inspected within an acceptable time frame. Eye washes nearby were in working order.

Per Mr. Wiegel, the tanks have been in operation since the construction of the facility. The two tanks are located on a concrete floor which appears to be in good condition (i.e., showed no signs of cracks). The tanks are elevated approximately three inches above the concrete floor on one end (photos #7 and 8). The floor gradually slopes up until, in both instances, it touches the tank bottoms on the other end. There appears to be adequate containment of the tanks in the event of a leak. Should a leak occur, the oil could be directed to the skim sumps next to the tanks (photo #9).

- Satellite Accumulation Area, Machine Repair Shop

Used oil drum was not marked with the words "Used Oil" (see photos #10 and 11)(this has subsequently been corrected (see Attachment #2)). No other violations were noted.

- Satellite Accumulation Area, Selecting Maintenance Shop

Used oil drum was not marked with the words "Used Oil" (see photo #12) (this has subsequently been corrected (see Attachment #2)).

- Satellite Accumulation Area, Forklift Maintenance Shop

Used oil drum was not marked with the words "Used Oil" (see photos #13 and 14) (this has subsequently been corrected (see Attachment #2)).

- Exterior 4000 Gallon Above-Ground Used Oil Tank

As mentioned above, the water from the skim sumps in the basement is pumped to a skim pond after the used oil is pumped into one of two concrete above-ground tanks located in the basement. Residues of used oil can still be found in the water in the skim pond, and these residues are skimmed off the surface of the pond and pumped into an exterior 4000 gallon above-ground used oil tank. As with the other used oil containers, the tank was not marked with the words "Used Oil" (see photo #15)(this has subsequently been corrected (see Attachment #2)).

Document Review

There were no training records on file, as required by Title 22 §66265.16(d). No discrepancies were found in the manifest review. No other violations noted in facility documentation.

Post Inspection Briefing

The inspectors met with the facility representatives and emphasized the following concerns noted during the inspection:

- 1. Improper labeling of used oil tanks and containers (since corrected).
- 2. The salt cake spill in the unloading area (since corrected).
- 3. Incomplete training records.
- 4. Potential violations concerning the concrete used oil tanks in the basement.

POTENTIAL VIOLATIONS

Personnel Training

Title 22 §66262.34(a)(4)

A generator may accumulate hazardous waste on-site for 90 days or less without a permit provided that the generator complies with the requirements for owners or operators in Article 4 of chapter 15 and with section 66265.16.

Title 22 §66265.16(d)

The owner or operator shall maintain (training) documents and records at the facility.

There were no training documents at the facility conforming to the requirments of section 66265.16(d)(1)-(4).

Used Oil Labeling

Title 22 §66279.21(b)

Containers and aboveground tanks used to store used oil shall be marked or clearly labeled with the words "USED OIL".

The following facility used oil containers and tanks were not marked with the words "USED OIL" (this has since been corrected by the facility).

- Basement Tanks #1 and #2
- Drum in Machine Repair Shop
- Drum in Selecting Maintenance Shop
- Drum in Forklift Maintenance Shop
- Exterior 4000-gallon Used Oil Tank

Photo #1- Salt cake deposits on ground in material offloading area

Photo #2 - Cullet bin

BACKGROUND

Owens-Brockway Glass Containers, a unit of Owens-Illinois, is a glass manufacturing facility located at 3600 Alameda Avenue, Oakland, CA 94601. It has been in operation for approximately sixty years and employs approximately 500 people. 70% of the facility's product line consists of wine bottles, with the remainder being food and beverage bottles. The facility has three furnaces, each furnace devoted exclusively to a particular color of glass (green, amber and clear (or flint)). Most of the bottles manufactured come from recycled glass (cullet), which is ground down and remelted, with the remainder glass made on site from silica sand mixed with salt cake, soda ash, limestone, and colorizers or de-colorizers. Approximately 875 tons of glass containers are manufactured every working day. Each furnace has an approximate 450 ton holding capacity for molten glass. Furnaces attain a temperature of 2750 degrees to achieve proper melting of the raw materials.

The facility operates forty forklifts, three trucks, one bobcat and two payloaders, which are maintained on the site.

MANUFACTURING PROCESS

Raw materials are blended together in batches in the proper proportions for the desired quality of glass. The batches are transported via closed conveyor belts to the facility furnaces, where the batch material is melted down to molten glass. The molten glass is drawn from the bottom of the furnace, via the throat to feeders. Orifices in the feeders control the amount of molten glass let through, and shears cut off the bottoms of the gobs (discreet units of molten glass) to the desired length (the weight of the gob is determined to an accuracy of one hundreth place). The gobs are first formed into blanks, called "parisons", which are then transferred into molds (two at a time) in machines called shops (there is a total of eight shops in the facility). The molds in each shop can be configured to whatever specifications are required for the particular bottle. Bottles are formed when compressed air is blown into the molds containing the gobs. The bottles then go through an annealing process where they are reheated in lehrs to temperatures up to 1030 degrees and then gradually cooled down. After the bottles are sufficiently cooled, they are sprayed with a poly-coat mixture that increases the bottles' lubricity (scratch resistance).

The bottles are then checked by means of optical equipment for various potential defects (irregular wall thickness, blisters, cracks, specks, etc.) and defective bottles are removed from the assembly line (to be recycled as cullet). The bottles that pass inspections are eventually packaged and transported off to the customers.

WASTES GENERATED

The following wastes are generated at the facility

1. Used Oil: The hot glass is quenched by water as it is ejected out of the shop. This water picks

RCRA COMPLIANCE INSPECTION REPORT

U.S. ENVIRONMENTAL PROTECTION AGENCY, REGION 9

HAZARDOUS WASTE MANAGEMENT DIVISION

WASTE COMPLIANCE EVALUATION

Purpose:

RCRA Compliance Evaluation

Facility:

Owens-Brockway Glass Containers

3600 Alameda Ave. Oakland, CA 94601

EPA ID Number:

CAT000618918

Date of Inspection:

April 9, 1998

EPA Representative:

Clint Seiter

Environmental Protection Specialist

(415) 744-2141

City of Oakland

Hernan Gomez

Fire Services Agency

Hazardous Materials Inspector

Representative:

(510) 238-7253

Facility Representative:

Hank Wiegel Plant Engineer

(510) 436-2181

Report Prepared By:

Clint Seiter

Report Date:

June 16, 1998



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street San Francisco, CA 94105-3901

June 17, 1998

CERTIFIED MAIL NO. P 274 218 184 RETURN RECEIPT REQUESTED

NOTICE OF VIOLATION

In reply, refer to WST-3-1

Hank Wiegel, Plant Engineer Owens-Brockway 3600 Alameda Ave Oakland, CA 94601

Dear Mr. Wiegel

On April 9, 1998, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency (U.S. EPA) at Owens-Brockway Glass Containers at 3600 Alameda Ave., Oakland, CA, U.S. EPA Identification Number C-AT000618918. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act (RCRA), as amended [42 U.S.C. 6927]. A copy of the investigation report is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with RCRA regulations and potential violations of the California authorized program under RCRA Subtitle C. Any omissions in the report shall not be construed as a determination of compliance with applicable regulations.

- 1. Title 22 §66265.16(d) lists the following four requirements for adequate facility training records:
- a. the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
- b. a written job description for each position listed.
- c. a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position listed.
- d. records that document that the training or job experience required has been given to, and completed by, facility personnel.

The training documentation you subsequently provided to EPA on April 16, 1998 does not conform to these four requirements. Please resubmit facility training records that conform to these requirements within 30 days of receipt of this letter.

Pursuant to U.S. EPA's Federal Facilities Compliance Strategy and Executive Order 12088, this letter and enclosure require you to correct the identified areas of noncompliance and to submit documentation of their correction to U.S. EPA within 30 calendar days of your receipt of this letter. Your response must include a letter signed by a duly authorized official of your facility, certifying correction of the identified areas of noncompliance. Documentation of your return to compliance may consist of, among other things, photographs, manifests and revised records. Where compliance cannot be achieved within 30 days, you must provide the reasons for the delay, a description of each corrective action planned and a schedule on which each corrective action will be taken.

By copy of this letter, U.S. EPA is providing the State of California with notice of the referenced violations of Subtitle C of RCRA. U.S. EPA is also providing the State with notice that it may take appropriate enforcement action if the facility does not resolve the violations within the time specified above and the State does not take appropriate enforcement action. The State of California may notify U.S. EPA of its intent to assume or decline responsibility to take such action to resolve the referenced violations.

U.S. EPA reserves the right to take further enforcement action as it deems appropriate, in accordance with the Federal Facility Compliance Strategy and Executive Order 12088. However, your response to this letter will be considered in determining the need for further enforcement action. Violations of Subtitle C of RCRA such as those listed in the enclosed report may also be punishable by criminal actions, as provided by Section 3008 of RCRA.

U.S. EPA routinely provides copies of investigation reports to State agencies, and upon request, to the public. Such releases are handled according to the Freedom of Information Act regulations (40 CFR Part 2). If you believe this report contains privileged or confidential information, you may make a claim within fifteen (15) working days from your receipt of this letter. U.S. EPA will construe your failure to furnish a timely claim as a waiver of the confidentiality claim.

Your response to this Notice of Violation, due within 30 days of your receipt of this letter, shall be mailed to:

Clint Seiter WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, CA 94105 If you have questions related to technical aspects of the investigation report or this letter, please contact Mr. Seiter at (415) 744-2141.

Sincerely,

Arlene Kabei, Chief

Compliance Monitoring and

Enforcement Section

Enclosure



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthorne Street San Francisco, CA 94105-3901

June 17, 1998

CERTIFIED MAIL NO. P 274 218 184 RETURN RECEIPT REQUESTED

NOTICE OF VIOLATION

In reply, refer to WST-3-1

Hank Wiegel, Plant Engineer Owens-Brockway 3600 Alameda Ave Oakland, CA 94601

Dear Mr. Wiegel

On April 9, 1998, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency (U.S. EPA) at Owens-Brockway Glass Containers at 3600 Alameda Ave., Oakland, CA, U.S. EPA Identification Number C-AT000618918. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act (RCRA), as amended [42 U.S.C. 6927]. A copy of the investigation report is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with RCRA regulations and potential violations of the California authorized program under RCRA Subtitle C. Any omissions in the report shall not be construed as a determination of compliance with applicable regulations.

- 1. Title 22 §66265.16(d) lists the following four requirements for adequate facility training records:
- a. the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
- b. a written job description for each position listed.
- c. a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position listed.
- d. records that document that the training or job experience required has been given to, and completed by, facility personnel.

The training documentation you subsequently provided to EPA on April 16, 1998 does not conform to these four requirements. Please resubmit facility training records that conform to these requirements within 30 days of receipt of this letter.

م

Pursuant to U.S. EPA's Federal Facilities Compliance Strategy and Executive Order 12088, this letter and enclosure require you to correct the identified areas of noncompliance and to submit documentation of their correction to U.S. EPA within 30 calendar days of your receipt of this letter. Your response must include a letter signed by a duly authorized official of your facility, certifying correction of the identified areas of noncompliance. Documentation of your return to compliance may consist of, among other things, photographs, manifests and revised records. Where compliance cannot be achieved within 30 days, you must provide the reasons for the delay, a description of each corrective action planned and a schedule on which each corrective action will be taken.

By copy of this letter, U.S. EPA is providing the State of California with notice of the referenced violations of Subtitle C of RCRA. U.S. EPA is also providing the State with notice that it may take appropriate enforcement action if the facility does not resolve the violations within the time specified above and the State does not take appropriate enforcement action. The State of California may notify U.S. EPA of its intent to assume or decline responsibility to take such action to resolve the referenced violations.

- U.S. EPA reserves the right to take further enforcement action as it deems appropriate, in accordance with the Federal Facility Compliance Strategy and Executive Order 12088. However, your response to this letter will be considered in determining the need for further enforcement action. Violations of Subtitle C of RCRA such as those listed in the enclosed report may also be punishable by criminal actions, as provided by Section 3008 of RCRA.
- U.S. EPA routinely provides copies of investigation reports to State agencies, and upon request, to the public. Such releases are handled according to the Freedom of Information Act regulations (40 CFR Part 2). If you believe this report contains privileged or confidential information, you may make a claim within fifteen (15) working days from your receipt of this letter. U.S. EPA will construe your failure to furnish a timely claim as a waiver of the confidentiality claim.

Your response to this Notice of Violation, due within 30 days of your receipt of this letter, shall be mailed to:

Clint Seiter WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, CA 94105 If you have questions related to technical aspects of the investigation report or this letter, please contact Mr. Seiter at (415) 744-2141.

Sincerely,

Arlene Kabei, Chief

Compliance Monitoring and

Enforcement Section

Enclosure

review of the MSDS for salt cake has indicated that this substance is not a hazardous material (see Attachment 3). Cullet is kept in bins, segregated by color, until ready for use (photo #2). The conveyor belts, which transport the materials to the furnaces, are enclosed and vacuumed daily (the dust vacuumed up is re-entered into the manufacturing process).

- Used Oil Tanks #1 and #2

As mentioned above, water used to quench hot glass becomes contaminated with lubricating oil from the machinery (photo #3). The water from the quench water bins is routed to two skim sumps (photo #4), where the used oil is skimmed and pumped to two interior above-ground used oil tanks adjacent to the sumps. After the oil has been skimmed off the water in the sumps, the water is pumped to an exterior skim pond. These two used-oil tanks (Tank #1 and Tank #2) are located in the facility basement. Whereas Tank #1 (see photo #5) was correctly identified as containing non-RCRA hazardous waste, it was not marked with the words "Used Oil", as is required by Title 22 §66279.21 (this was subsequently corrected by the facility (see Attachment 2)). All other labeling requirements were in order. Similarly, while Tank #2 was also correctly identified as containing non-RCRA hazardous waste, it was not labeled with the words "Used Oil" (see photo #6). As with Tank #1, this has subsequently been corrected (see Attachment 2). Fire extinguishers were mounted close by and their tags indicated that they had been inspected within an acceptable time frame. Eye washes nearby were in working order.

Per Mr. Wiegel, the tanks have been in operation since the construction of the facility. The two tanks are located on a concrete floor which appears to be in good condition (i.e., showed no signs of cracks). The tanks are elevated approximately three inches above the concrete floor on one end (photos #7 and 8). The floor gradually slopes up until, in both instances, it touches the tank bottoms on the other end. There appears to be adequate containment of the tanks in the event of a leak. Should a leak occur, the oil could be directed to the skim sumps next to the tanks (photo #9).

- Satellite Accumulation Area, Machine Repair Shop

Used oil drum was not marked with the words "Used Oil" (see photos #10 and 11)(this has subsequently been corrected (see Attachment #2)). No other violations were noted.

- Satellite Accumulation Area, Selecting Maintenance Shop

Used oil drum was not marked with the words "Used Oil" (see photo #12) (this has subsequently been corrected (see Attachment #2)).

- Satellite Accumulation Area, Forklift Maintenance Shop

Used oil drum was not marked with the words "Used Oil" (see photos #13 and 14) (this has subsequently been corrected (see Attachment #2)).

- Exterior 4000 Gallon Above-Ground Used Oil Tank

As mentioned above, the water from the skim sumps in the basement is pumped to a skim pond after the used oil is pumped into one of two concrete above-ground tanks located in the basement. Residues of used oil can still be found in the water in the skim pond, and these residues are skimmed off the surface of the pond and pumped into an exterior 4000 gallon above-ground used oil tank. As with the other used oil containers, the tank was not marked with the words "Used Oil" (see photo #15)(this has subsequently been corrected (see Attachment #2)).

Document Review

There were no training records on file, as required by Title 22 §66265.16(d). No discrepancies were found in the manifest review. No other violations noted in facility documentation.

Post Inspection Briefing

The inspectors met with the facility representatives and emphasized the following concerns noted during the inspection:

- 1. Improper labeling of used oil tanks and containers (since corrected).
- 2. The salt cake spill in the unloading area (since corrected).
- 3. Incomplete training records.
- 4. Potential violations concerning the concrete used oil tanks in the basement.

POTENTIAL VIOLATIONS

Personnel Training

Title 22 §66262.34(a)(4)

A generator may accumulate hazardous waste on-site for 90 days or less without a permit provided that the generator complies with the requirements for owners or operators in Article 4 of chapter 15 and with section 66265.16.

Title 22 §66265.16(d)

The owner or operator shall maintain (training) documents and records at the facility.

There were no training documents at the facility conforming to the requirments of section 66265.16(d)(1)-(4).

Used Oil Labeling

Title 22 §66279.21(b)

Containers and aboveground tanks used to store used oil shall be marked or clearly labeled with the words "USED OIL".

The following facility used oil containers and tanks were not marked with the words "USED OIL" (this has since been corrected by the facility).

- Basement Tanks #1 and #2
- Drum in Machine Repair Shop
- Drum in Selecting Maintenance Shop
- Drum in Forklift Maintenance Shop
- Exterior 4000-gallon Used Oil Tank





Photo #1- Salt cake deposits on ground in material offloading area



Photo #2 - Cullet bin



Photo #3 - Hot glass quench water vat



Photo #4 - Oily wastewater skim pond




Photo #5 - Concrete used oil tank #1



Photo #6 - Concrete used oil tank #2



Photo #7 - Basement used oil tank, showing elevation above floor



Photo #8 - Basement used oil tank, close-up of elevation above floor



Photo #9 - Skim sump next to used oil tank




Photo #10 - Used oil drum (unmarked with the words "Used Oil") in satellite accumulation area in the Machine Repair Shop.



Photo #11 - Closeup of label of used oil drum in satellite accumulation area in the Machine Repair Shop.



Photo #12 - Used oil drum (unmarked with words "Used Oil") in Satellite Accumulation Area, Selecting Maintenance Shop




Photo #13 - Used oil drum (unmarked with words "Used Oil") in Satellite Accumulation Area, Forklift Maintenance Shop



Photo #14 - Closeup of label on used oil drum in Satellite Accumulation Area, Forklift Maintenance Shop



Photo #15 - Exterior 4000 Gallon Above-Ground Used Oil Tank, unmarked with the words "Used Oil".



Raw Material Delivery



Area were green liquid was found.

(Green liquid on basement floor was cooling tower water with dye in it to find leak)



Cylinder Storage Basement Area Between A & B Furnace



D-Furnace Peep Hole



.


Selecting Maintenance Satellite Storage Area




Oil Filter Container




Skim Pond Oil




Used Oil A-Sump Tank



Used Oil D-Sump Tank





Material Safety Data Sheet

anhydrous

North American Chemical Company

13200 Main Street Trona, California 93562

For more detailed information on the hazards of this product, write to the address above. Technical Information Bulletin is also available. For emergency information, telephone (619) 372-2291 any time.

PRODUCT IDENTIFICATION	PHYSICAL AND CHEMICAL PROPERTIES
Brand Name TRONA salt cake TRONA anhydro- sodium sulfate	Boiling Point C
Chemical Name Sodium sulfate Common Name Salt cake Formula Na ₂ SO ₄ DOT Proper Shipping Name Not applicable DOT Hazard Class Not applicable DOT I.D. Number Not applicable Reportable Quantity (RQ) Not applicable	Color
CAS Number7757-82-6	•

HAZARDOUS INGREDIENTS

Chemical Name	Common Name	CAS Number	Hazard
Sodium sulfate	Salt cake	7757-82-6	Mild irritant to eyes, nose, and skin and a strong cathartic.

PHYSICAL HAZARD INFORMATION

Explosive:

Upper Explosive Limit: Not applicable

Lower Explosive Limit: Not applicable

Pyrophoric:

Flammable: No

Flammability Class:

Not applicable

Combustible: No

Organic Peroxide:

No

Oxidizer:

No

Compressed Gas:

No

Reactivity:

Stable at ordinary and expected temperatures and pressures.

Incompatibilities; Aluminum powder and molten sodium sulfate has exploded.

Hazardous

Molten sodium sulfate decomposes, evolving toxic sulfur oxides.

Decomposition:

Conditions

Temperatures at or above the melting point,

To Avoid:

HEAL	TH	INFOR	AAT	ON
HEAL		INCURE	MAI	

Precaution	nary Information:	CAUTION! May cause irritation. May be harmful if swallowed.				
Symptom	s Of Exposure:	Burning sensation in the eyes or nose, coughing or sneezing or rash on the skin.				
Restrictiv Condition	e Medical ha:	Skin disorders may be aggravated by the dehydrating action of this product. Gastrointestinal and kidney disorders may be aggravated by the cathartic action of this product.				
	PRIMARY ROUTE(S) OF ENTRY					
Inhalatio	nhalation (breathing), eye and skin contact and ingestion (swallowing).					
		TOXICITY INFORMATION				
		city to humans; no lethal doses for humans were reported in the literature; Oral-mouse use LDLo 1220 mg/kg.				
********		EXPOSURE LIMITS				
ACGIH:	Not established. Not established. ACGIH nuisance	dust TLV-TWA is 10 mg/m³ total dust or 5 mg/m³ respirable dust.				

Or Carcinogen	ntial Carcinogen	™ Not Applicable ☐ OSHA	National Toxicology ProgramInternational Agency For Research On Cance			
	PRECAU	TIONS FOR SAFE HAN	NDLING AND USE			
Avoid breathing dus Avoid contact with e Use only with adequ Wash thoroughly aft	eyes and skin. Nate ventilation.					
······································	· · · · · · · · · · · · · · · · · · ·	CDIL AND LEAK SOO	CEDI IDEC			
Soil Release:	Shovel and sweep	SPILL AND LEAK PRO up into a container and re cordance with federal, stat	claim for salvage value or dispose of at an industrial			
Water Spill:	Disperse and dilute	Disperse and dilute with water jets, propellers or other similar devices.				
Air Spill:	Let dust settle and	dispose of as in Soil Relea	ase above.			
Occupational Spill:	_	up into a container. Recla an industrial sewer.	im for salvage value, or as permitted, small amounts			
RCRA Waste Number:	Not applicable.					
E1	NGINEERING COM	NTROLS AND PERSON	AL PROTECTIVE EQUIPMENT			
Ventilation:	Use general dilutio	n ventilation techniques.				
Respirator:	Use NIOSH/MSH/ exposure limit.	approved dust and mis	it respirator for exposure above the nuisance dust			
Eye Protection:	Safety glasses or v	ented safety goggles.				
Gloves:	No special require	ments, Ordinary work glov	ves.			

Mr. John Verber, esq. May 28, 1998 Page 2

If you have any questions or need clarifications on any of the items listed above, please contact Mr. David Bacharowski at (213) 266-7546, or Mr. Rick Vergets at (213) 266-7556. You may also contact USEPA's project managers, Mr. Steve Linder at (415) 744-2036 or Mr. Sean Condry at (415) 744-2112 regarding technical issues. Please contact Mr. Jorge Leon at (916) 657-2428 or Ms. Laurie Williams at (415) 744-1387 with respect to any legal issues. We look forward to working with you.

Sincerely,

DAVID A. BACHAROWSKI
Environmental Program Manager
Regional Water Quality Control Board
Los Angeles Region

SEAN T. CONDRY Project Manager Waste Management Division U.S. EPA Region 9

cc: Jorge Leon, Office of Chief Counsel, SWRCB

David Spath, Division of Drinking Water and Environmental Management, State Department of Health Services

Gary Yamamoto, Drinking Water Field Operations, State Dept. of Health Services

Steve Linder, United States Environmental Protection Agency

Laurie Williams, United States Environmental Protection Agency

Carl Sjoberg, Environmental Programs Division, Los Angeles County Department of Public Works

Capt. Dennis Wilcox, Underground Storage Tank Program, City of Los Angeles Fire Dent.

Keith Pritsker, City Attorney's Office, City of Los Angeles

Walter Crone, Ninyo & Moore

Michael Schwennesen, Ecology and Environment, Inc.

Craig Perkins, Environmental & Public Works, City of Santa Monica

Joseph Lawrence, Assistant City Attorney, City of Santa Monica

Rey Rodriguez, Utilities Engineer, City of Santa Monica

Brian Johnson, Underground Storage Tank Program, City of Santa Monica

Barry Groveman, Special Environmental Counsel for City of Santa Monica

Denise Kruger, Southern California Water Company

Rob Saperstein, Counsel for Southern California Water Company

Toby Moore, Mission Geoscience

Angelo Bellomo, Environmental Strategies Corporation

Gino Bianchi-Mosquera, Geomatrix Consultants, Incorporated

Brad Boschetto, Shell Oil Company

Adam Leiter, Wayne Perry, Inc.

	•	,		
-			÷	
				•
			,	

n the reverse side?	SENDER: Complete items 1 and/or 2 for additional services. Complete items 3, 4a, and 4b. Print your name and address on the reverse of this form so that we card to you. Attach this form to the front of the mailpiece, or on the back if space permit. Write "Return Receipt Requested" on the mailpiece below the article The Return Receipt will show to whom the article was delivered and delivered.	I also wish to receive the following services (for an extra fee): 1. Addressee's Address 2. Restricted Delivery Consult postmaster for fee.			
completed on	3. Article Addressed to: Hank Wiegel Plant Engineer Owens-Brockway	4a. Article N	umber 27 # 2/8	184	
dmo	Dovens-Brokway	4b. Service	Гуре		
		☐ Registere	ed	Certified	
ADDRESS	3600 Clame Va Uvenue			☐ Insured	
굨	Ookland, CA 94601		☐ Return Receipt for Merchandise ☐ COD		
N AD	Outense, Cit / 4007	7. Date of Delivery			
RETUR	5. Received By: (Print Name)	8. Addressee and fee is	e's Address (Only paid)	if requested	
s your <u>f</u>	6. Signature: Addressee of Agent)				
	PS Form 3011 , December 1994		Domestic Re	turn Receipt	

UNITED STATES POSTAL SERVICE

j

			l
		I	l

First-Class Mail Postage & Fees Paid USPS Permit No. G-10

Print your name, address, and ZIP Code in this box ●

Print your name, address, and zir Gode in this some Clint Sciter (2057-3-1) U.S. EPA, Region 9 75 Howthorne St. San Francisco A 94105

Adam to to a Million belong the belong the best of the

2

W

DRAFT

CERTIFIED MAIL NO.
RETURN RECEIPT REQUESTED

NOTICE OF VIOLATION

In reply, refer to WST-3-1

Hank Wiegel, Plant Engineer Owens-Brockway 3600 Alameda Ave Oakland, CA 94601

Dear Mr. Wiegel

On April 9, 1998, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency (U.S. EPA) at Owens-Brockway Glass Containers at 3600 Alameda Ave., Oakland, CA, U.S. EPA Identification Number CAT000618918. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act (RCRA), as amended [42 U.S.C. 6927]. A copy of the investigation report is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with RCRA regulations and potential violations of the California authorized program under RCRA Subtitle C. Any omissions in the report shall not be construed as a determination of compliance with applicable regulations.

- 1. Title 22 §66265.16(d) lists the following four requirements for adequate facility training records:
- a. the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
- b. a written job description for each position listed.
- c. a written description of the type and amount of both introductory and continuing training that will be given to each person filling a position listed.
- d. records that document that the training or job experience required has been given to, and completed by, facility personnel.

The training documentation you subsequently provided to EPA on April 16, 1998 does not conform to these four requirements. Please resubmit facility training records that conform to these requirements within 30 days of receipt of this letter.

Pursuant to U.S. EPA's Federal Facilities Compliance Strategy and Executive Order 12088, this letter and enclosure require you to correct the identified areas of noncompliance and to submit documentation of their correction to U.S. EPA within 30 calendar days of your receipt of this letter. Your response must include a letter signed by a duly authorized official of your facility, certifying correction of the identified areas of noncompliance. Documentation of your return to compliance may consist of, among other things, photographs, manifests and revised records. Where compliance cannot be achieved within 30 days, you must provide the reasons for the delay, a description of each corrective action planned and a schedule on which each corrective action will be taken.

By copy of this letter, U.S. EPA is providing the State of California with notice of the referenced violations of Subtitle C of RCRA. U.S. EPA is also providing the State with notice that it may take appropriate enforcement action if the facility does not resolve the violations within the time specified above and the State does not take appropriate enforcement action. The State of California may notify U.S. EPA of its intent to assume or decline responsibility to take such action to resolve the referenced violations.

U.S. EPA reserves the right to take further enforcement action as it deems appropriate, in accordance with the Federal Facility Compliance Strategy and Executive Order 12088. However, your response to this letter will be considered in determining the need for further enforcement action. Violations of Subtitle C of RCRA such as those listed in the enclosed report may also be punishable by criminal actions, as provided by Section 3008 of RCRA.

U.S. EPA routinely provides copies of investigation reports to State agencies, and upon request, to the public. Such releases are handled according to the Freedom of Information Act regulations (40 CFR Part 2). If you believe this report contains privileged or confidential information, you may make a claim within fifteen (15) working days from your receipt of this letter. U.S. EPA will construe your failure to furnish a timely claim as a waiver of the confidentiality claim.

Your response to this Notice of Violation, due within 30 days of your receipt of this letter, shall be mailed to:

Clint Seiter WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, CA 94105

If you have questions related to technical aspects of the investigation report or this letter,

please contact Mr. Seiter at (415) 744-2141.

Sincerely,

Arlene Kabei, Chief Compliance Monitoring and Enforcement Section

cc: Paula Rasmussen, Reg. 4 Hernan Gomez, Oakland Fire Services

bc: Elaine Schimmel Reading File H-4-1




Photo #1- Salt cake deposits on ground in material offloading area




Photo #2 - Cullet bin



Photo #3 - Hot glass quench water vat




Photo #4 - Oily wastewater skim pond




Photo #5 - Concrete used oil tank #1




Photo #6 - Concrete used oil tank #2




Photo #7 - Basement used oil tank, showing elevation above floor



Photo #8 - Basement used oil tank, close-up of elevation above floor




Photo #9 - Skim sump next to used oil tank




Photo #10 - Used oil drum (unmarked with the words "Used Oil") in satellite accumulation area in the Machine Repair Shop.




Photo #11 - Closeup of label of used oil drum in satellite accumulation area in the Machine Repair Shop.



Photo #12 - Used oil drum (unmarked with words "Used Oil") in Satellite Accumulation Area, Selecting Maintenance Shop



Photo #13 - Used oil drum (unmarked with words "Used Oil") in Satellite Accumulation Area, Forklift Maintenance Shop




Photo #14 - Closeup of label on used oil drum in Satellite Accumulation Area, Forklift Maintenance Shop







Photo #15 - Exterior 4000 Gallon Above-Ground Used Oil Tank, unmarked with the words "Used Oil".










.











.





Material Safety Data Sifett

anhydrous sodium sulfate

North American Chemical Company

13200 Main Street Trona, California 93562

For more detailed information on the hazards of this product, write to the address above. Technical Information Bulletin is also available. For emergency information, telephone (619) 372-2291 any time.

PRODUCT IDENT	IFICATIO	ON	PHYSICAL AND CHEMICAL PROPERTIES			
Brand Name		TRONA salt cake	StateGranular solid			
Signe (warner in it.)		TRONA anhydrous	Meiting Point C			
		sodium sulfate		Not applicable		
Chemical Name		Sodium sulfate				
Common Name		Salt cake		None		
Formula		.Na ₂ SO ₄		/cu. ft		
DOT Proper				onNot applicable		
Shipping Name DOT Hazard		. Not applicable		@ 20CNot applicable		
			•	, % By Wt. @ 20C 16.3		
Class				MethodNot applicable		
DOT I.D. Number			рн	Not applicable		
				•		
LAS Number		. / / 5 / - 6 2 - 0	.,,,,,,,	<u> </u>		
		HAZARDO	US INGREDIENTS	•		
Chemical Na	me	ne Common Name CAS Number Haza		Hazard		
Sodium sulfate Salt cake		Sait cake	7757-82-6	Mild irritant to eyes, nose, and skin and a strong cathartic.		
		PHYSICAL HA	ZARD INFORMATIO	DN		
Explosive: No		Upper Explosive Limit:	Not applicable	Lower Explosive Limit: Not applicable		
Pyrophoric: No				•		
Flammable: No		Flammability Class:	Not applicable			
Combustible: No		Organic Peroxide:	No			
Oxidizer: No		Compressed Gas:	No .			
Reactivity:	Stable at	ordinary and expected ter	mperatures and pres	sures.		
Incompatibilities:	Aluminu	m powder and molten sodi	um sulfate has explo	oded.		
	•					
Hazardous Decomposition:	Moiten s	odium sulfate decomposei	s, evolving toxic sulfi	ur oxides.		
Conditions To Avoid:	Tempera	tures at or above the melti	ng point.			

HEALTH INFORMATION

Precaution	nary Information:	CAUTION! May cause irritation. May be harmful if swallowed.
Symptom:	s Of Exposure:	Burning sensation in the eyes or nose, coughing or sneezing or rash on the skin.
Restrictive Condition	e Medical	Skin disorders may be aggravated by the dehydrating action of this product. Gastrointestinal and kidney disorders may be aggravated by the cathartic action of this product. A
Inhalation	n (breathing), eye	PRIMARY ROUTE(S) OF ENTRY and skin contact and ingestion (swallowing).
		TOXICITY INFORMATION
This prod LD ₅₀ 598	duct is of low toxic 9 mg/kg; lvn-mou	city to humans; no lethal doses for humans were reported in the literature; Oral-mouse see LDLo 1220 mg/kg.
********		EXPOSURE LIMITS
ACGIH:	Not established. Not established. ACGIH nuisance	dust TLV-TWA is 10 mg/m³ total dust or 5 mg/m³ respirable dust.

Reported As A Pote	ential Carcinogen	Not Applicable	□ National Toxicology Program		
Or Carcinogen		D OSHA	☐ International Agency For Research On Canc		
	PRECAU	TIONS FOR SAFE HAP	IDLING AND USE		
Avoid breathing dua Avoid contact with Use only with adeq Wash thoroughly at	eyes and skin. uate ventilation.				
		SPILL AND LEAK PRO	CEDURES		
Soil Release:		up into a container and recordance with federal, state	claim for salvage value or dispose of at an industrial le and local regulations.		
Water Spill:	Disperse and dilute	with water jets, propeller	s or other similar devices.		
Air Spill:	Let dust settle and	dispose of as in Soil Rele	ase above.		
Occupational Spill		up into a container, Recla an industrial sewer.	im for salvage value, or as permitted, small amounts		
RCRA Waste Number:	Not applicable.				
E	NGINEERING CO	NTROLS AND PERSON	IAL PROTECTIVE EQUIPMENT		
Ventilation:	Use general dilution	on ventilation techniques.			
Respirator:	Use NIOSH/MSH/ exposure limit.	A approved dust and mis	st respirator for exposure above the nuisance dust		
Eye Protection:	Safety glasses or v	rented safety goggles.			
Gloves:	No special require	ments. Ordinary work glo	ves.		
Clothing:	No special require	ments. Wear easily washab	le clothing. Change daily. Wash clothing before reuse.		

3 of 4

Mr. John Verber, esq. May 28, 1998 Page 2

If you have any questions or need clarifications on any of the items listed above, please contact Mr. David Bacharowski at (213) 266-7546, or Mr. Rick Vergets at (213) 266-7556. You may also contact USEPA's project managers, Mr. Steve Linder at (415) 744-2036 or Mr. Sean Condry at (415) 744-2112 regarding technical issues. Please contact Mr. Jorge Leon at (916) 657-2428 or Ms. Laurie Williams at (415) 744-1387 with respect to any legal issues. We look forward to working with you.

Sincerely,

DAVID A. BACHAROWSKI
Environmental Program Manager
Regional Water Quality Control Board
Los Angeles Region

SEAN T. CONDRY
Project Manager
Waste Management Division
U.S. EPA Region 9

cc: Jorge Leon, Office of Chief Counsel, SWRCB

David Spath, Division of Drinking Water and Environmental Management, State Department of Health Services

Gary Yamamoto, Drinking Water Field Operations, State Dept. of Health Services

Steve Linder, United States Environmental Protection Agency

Laurie Williams, United States Environmental Protection Agency

Carl Sjoberg, Environmental Programs Division, Los Angeles County Department of Public Works

Capt. Dennis Wilcox, Underground Storage Tank Program, City of Los Angeles Fire Dept.

Keith Pritsker, City Attorney's Office, City of Los Angeles

Walter Crone, Ninyo & Moore

Michael Schwennesen, Ecology and Environment, Inc.

Craig Perkins, Environmental & Public Works, City of Santa Monica

Joseph Lawrence, Assistant City Attorney, City of Santa Monica

Rey Rodriguez, Utilities Engineer, City of Santa Monica

Brian Johnson, Underground Storage Tank Program, City of Santa Monica

Barry Groveman, Special Environmental Counsel for City of Santa Monica

Denise Kruger, Southern California Water Company

Rob Saperstein, Counsel for Southern California Water Company

Toby Moore, Mission Geoscience

Angelo Bellomo, Environmental Strategies Corporation

Gino Bianchi-Mosquera, Geomatrix Consultants, Incorporated

Brad Boschetto, Shell Oil Company

Adam Leiter, Wayne Perry, Inc.

-	*	•			
			٤		
				•	
			,		
				•	
				•	
				-	

HAZARDOUS WASTE TRAINING

	_	_
DATE: <u>7/24/98</u> PLANT	r: Ozkland INSTRUCT	or: B. Nezl
SUBJECTS COVERED: Del. 2	ertons, Typuol Vados Catellitos, Spills, etc. Kon Age	Acum, Gon Worte Mit,
NAME (print)	SIGNATURE	JOB TITLE Enviro Administrator
1. Bob Neal	SIGNATURE Kobert C. Weal	
2. Tom MAHONEY	Tom Wahoney	Maint Week.
3. VIRGIL HENLEY	Mirgel Henley Sank	Ment Superior
4. DON CLARK	Den Back	MANT METT.
5. PHiL Hord		
6. Ray WIH/PAMS	Ray I. Willim	My (NT-
7. Nel Serafim	Mel Serafin	mant.
8. GARY PRINCE	Gan Pence	MOLO REP. SUPV.
9. LARRY BERTRAND	Pair Date Corlina Corlina Corlina Corlina Corlina Corlina Corlina Corrections	MAINT
10. Casey, CORCESS	Colliss Ray Case	Mariot
11. JOHN ALAMILLO	John D. alamile	a machine pepain
12. JAVIER MORALES	Jun 1. Merche	MAINT.
13.MicHael Flentrof	Michael Flation	Maint
14. Pedro KomirE2	Jehro Tamié	frewing.
14. Pedro Komirez 15. Romeo M. Binono	GCAL Sungel	SELECT, MAINT.

HAZARDOUS WASTE TRAINING

DATE: 8/11/98 PLANT:	: Oskland instruc	CTOR: B.Nea
SUBJECTS COVERED: Backy	would, Typisal Hollis, Plant. Attacked Hardout Used	Jole, Spills
NAME (print)	SIGNATURE	JOB TITLE
1. Bab Nezl	Lobert C. Weal	Enviro. Administrator
2. DAVID BUNNIGHT	Vani Duning	Munil Mac.
3. WILLIAM DELong	William J. Dus	WILD ATT.
4.	·	
5.		
6.		
7.		
8.		
9.		
10.		
11.		
12.		
13.		
14.		
15.		
16.		
17		

HAZARDOUS WASTE TRAINING

DATE: 7/23/98 PLANT: Oakland INSTRUCTOR: B. Neal
SUBJECTS COVERED: Background H.W., Sotelite Accum., Con. H.W Mgt. Requirements Inspections, Costs, Spill Resource, (See Attached Outline) NAME (print) SIGNATURE JOB TITLE
NAME (print) SIGNATURE JOB TITLE
1. Bob Neal Robert C. That Enviro. Administrator
2. BORDYER for Salmer MAINT MEC. 3. RON SALMER for Salmer MAINT C.L.
4. JIM HOAD JE HOUSE MUINT MECH
3. RON SALMER FOR SOUTH BATCH MAINT C.L. 4. JIM HOAD 5. LUIS GONZALEZ Jui HOTT MECH 5. LUIS GONZALEZ
o. Ore cursion
7. Michael S. Burns maint
7. Michael S. Burns michael S. Burns maint 8. HENRY V. RULL frumy Vallo KULL MAINT 1. DOSE T MORALES JOSE E MONDLE MAINT MECH.
9. JOSE T MORACES JOSE MATHITIES.
10. Jaime Morono 11. HANK WIELEL Wight Pet- Eng.
11. HANK WIELEL & Wiegel pet Eng.
12.
13.
14.
15.
16.
17.

MEETING TOPIC: Hazardous Waste Training

NAME: (PLEASE PRINT YOUR NAME)	DEPARTMENT
Bob Nezl	Environmental
² Steve Springer	Plant Engineering
+ Jan't Ding	MAINT
5 RICHARD TORRES	MAINT
Richard W. GRAY	SELMAINT
7 JoHN BASIEE	BATCH
8 Rosilyn MORRII	sel maint
9 Ohlip Cob	Storeroom
10	
11	
12	
13	
14	
15	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25 .	

. ę .

HAZARDOUS WASTE MANAGEMENT TRAINING

- 1. **DEFINITIONS** What is a waste? When? Hazardous waste? Generator? Facility?
- 2. HAZARDOUS WASTES GENERATED BY GLASS PLANTS

- Waste oil ("Used Oil")

- Oil contaminated solids

- Oil Filters and Antifreeze -

- Checker Dust (furnace repairs)

- Coder Inks and Solvent (MEK)

- Melter Bottom with Lead (furnace repairs)

- Parts washer solvents

- Asbestos

- Contaminated Cullet and Sludge - Caustic

3. SATELLITE ACCUMULATION (Tasks of the H.W. Satellite Accumulator)

(Coder wastes and mobile equipment maintenance wastes)

- Must be located in the immediate area where the waste is generated.
- Must be under the direct supervision of the area supervisor(s).
- The accumulation area must be appropriately marked and kept clean.
- Must use proper containers.
- CONTAINERS MUST BE LABELED PROPERLY.
 - Must be marked "Hazardous Waste".
 - Must indicate the content. i.e. "Used Oil", "Oil filters", "MEK Solvent".
 - Must indicate the "satellite" accumulation start date.
- Use protective equipment (rubber gloves and safety glasses) when handling.
- Ensure that only the designated waste is added to the container.
- CONTAINERS MUST BE CLOSED EXCEPT WHEN ADDING WASTE.
- 55 gal. is the maximum waste volume allowed at a satellite accumulation site.
- One (1) year is the limit for accumulation at a satellite accumulation site.
- Requires notification of a "haz. waste handler" when the container is full so a replacement container can be provided and the full container removed.

4. GENERAL HAZARDOUS WASTE MANAGEMENT (Tasks of the H.W. Handler)

- Maintain the 90-day accumulation area for hazardous wastes.
- Ensure that proper containers are used and that they are closed and leak free.
- Ensure that containers bear the proper labels and contain required information.
- Ensure that wastes are shipped for disposal within 90 days of generation.
- Maintain current waste profiles at the disposal facilities of choice.
- Prepare manifests for waste shipments including proper waste and DOT information, certification signatures and attachments as required.
- Ensure that the waste load is secure and that proper placards are displayed.
- Ensure proper distribution and filing of waste manifests.
- Ensure that the disposal facility copy is returned within 35 days of shipment.
- Prepare and submit reports and fees as required by the regulatory agencies.
- Maintain the required training records.

5. HAZARDOUS WASTE INSPECTIONS (Tasks of the H.W. Inspector)

- Conducted weekly to ensure waste is accumulated only in the designated areas.
- Containers are checked to ensure they are closed, properly labeled and spill free.
- Accumulation dates are checked to ensure they do not exceed specified limits.
- Loading/unloading areas are checked to ensure they are free of spilled materials.
- Containment areas are checked for leaked material.
- Used oil accumulation facilities are checked for proper maintenance.
- Spill response equipment is checked.
- Housekeeping in accumulation areas and throughout the plant is checked.
- Inspections are documented. Inspection records must be retained for 3 years.
- Observed deficiencies are reported to the plant engineer for corrective action.

6. **DISPOSAL COSTS**

- Transportation and disposal costs vary widely for hazardous waste depending on the characteristics of the waste, treatment requirements and the disposal facility used. In general, the transportation cost for a truck load of waste to the facility most often used (CWM) is about \$1,000.
- Treatment and disposal costs for hazardous waste solids typically range from \$100 300/ton. The cost for some problem wastes can be as high as \$800/ton.
- Disposal of waste oil costs about \$3,000 per truck load. More if high solids.
- In general, haz. waste transportation and disposal costs \$4000-8,000/truck load.
- A drum of waste solvent may cost \$500 for disposal.

7. SPILL RESPONSE

- Small incidental spills typical during normal operation are handled by the user.
- Spills involving larger quantities of material which can be handled internally by plant personnel are handled by the Emergency Response Team.
- A spill which could impact the public or the environment or is beyond the response capabilities of designated plant employees is considered an emergency response. Emergency spill responses are handled by trained environmental response contractors or the local fire department.

8. MOST COMMON MISTAKES IN HAZARDOUS WASTE MANAGEMENT (See attached sheet.)

9. REVIEW

OWENS-BROCKWAY

GLASS CONTAINERS a unit of Owens-Illinois

August 12, 1998



Mr.Clint Seiter WST-3-1 Waste Compliance Branch U.S. EPA, Region 9 75 Hawthorne Street San Francisco, CA 94105

RE: Owens-Brockway Glass Container Inc.

3600 Alameda Ave. Oakland, Calif. 94601 UST-3-1

051-3-1

Letter Dated June 17, 1998

Dear Mr. Seiter:

As a supplement to our previously submitted training records, we are adding this response.

We appreciate the additional time to conduct hazardous waste training during this heavy vacation season. With the plant's three shift operation, vacations and limited availability of our environmental administrator to conduct the training; achieving the desired training coverage has been difficult.

Since our discussion on July 7, 1998, we have completed four hazardous waste training sessions for the plant's operations personnel. A total of 35 workers attended the sessions which focused specifically on hazardous waste requirements as they relate to the individual's job. A copy of the attendee lists and the training session outline are attached. A training review (test) was completed by each attendee which demonstrated their comprehension of the necessary information. The individual training reviews will be retained as part of the training documentation.

Hazardous waste job descriptions for waste management tasks at the Oakland plant are attached along with the name of persons filling the hazardous waste management jobs. With the exception of "Handlers" Patti Nielsen and Kathy Allen who attend off-site refresher courses annually, all the listed individuals have received job related refresher training within the past month.

All areas related to training, identified in Arlene Kabei's letter of June 17, 1998, have been addressed and corrected. The plant will continue to comply with applicable hazardous waste regulations. If there are any questions related to this submittal, please give me a call at (510) 436-2058.

Sincerely,

Hank Wiegel Plant Engineer

Had Way

bcc: Dick Schieder Oakland
Bob Stutz Oakland
Patti Nielsen Oakland
Steve Springer Oakland
Walt Long 30 LDP
Bob Neal Pleasanton

OWENS-BROCKWAY

GLASS CONTAINERS a unit of Owens-Illinois



3600 Alameda Ave. Oakland, CA. 94604

April 16, 1998

U.S. Environmental Protection Agency Mr. Clinton Seiter 75 Hawthorne Street (WST-3-1) San Francisco, CA. 94105-3901

Mr. Seiter

Enclosed is the information that you requested from you visit on April 9, 1998. If I can be of any further help, please give me a call at 510-436-2183.

Sincerely,

Steve Springer

General Foreman

CLASSIFICATION LEVELS

FOR

GLASS CONTAINER DIVISION

MAINTENANCE WORKERS

UTILITY WORKER

The duties of this classification involve manual and laboring work requiring only a limited degree of skill, training, or plant experience. The individual performs simple duties in plant maintenance, using such simple equipment as bend and hand tools, brooms, shovels, cleaning equipment, etc. The utility worker may perform laboring duties associated with moving and installing heavy machinery and equipment, upkeep, demolition, and construction. The individual normally is closely supervised by a foreman or crew leader. Performs other related duties as assigned.

HELPERS

Individuals in this classification normally work under the direction of tradesmen, and assist tradesmen in such ways as delivering tools and supplies, performing simple tasks incident to the work of tradesmen, cleaning up work areas, etc. May oil, grease, clean and inspect equipment, and may salvage and store parts. Uses simple hand tools. May move and handle heavy equipment and supplies, and may operate tractors, Hi-lifts, or trucks in connection with maintenance and repair, furnace rebuilds, plant cleanup, etc. Performs other related duties as assigned.

HANDY WORKER

Work in this classification requires approximately the same level of ability as that of the Helper, but involves, in addition to some Helper duties, specialized experience in one or more unskilled or semi-skilled areas. Examples include, but are not limited to, tool or cutter grinding, maintenance and storage of tools, oiling and upkeep of special equipment, operation of special equipment such as cranes or hoists, etc. Performs other related duties as assigned.

APPRENTICE CLASSIFICATIONS

Duties and responsibilities of apprentices are included in the apprentice agreements in effect at each plant. Performs other related duties as assigned.

REPAIRMAN

An individual in this classification performs semi-skilled or skilled work in trades which are not apprenticeable under the apprentice program, such as painting, carpentry, bricklaying, tinsmithing, etc., or individual may perform tradesman work requiring moderate skill, but individual has not been enrolled in the apprentice program. Performs other related duties as assigned.

MAINTENANCE JOURNEYMAN

All maintenance tradesmen who have completed the Maintenance Apprenticeship Program fall in this category. Performs other related duties as assigned.

MACHINE REPAIRMAN JOURNEYMAN

All repairmen of bottle machines and related equipment who have completed the Machine Repair Apprentice Program fall in this category. Performs other related duties as assigned.

b Tit	le MAINTENANCE FORE	MAN T	Job No.	LNCØ3	
visio	n Plant Location	Department		Job Level	
GCD	Oakland, CA Function & Responsible	Maintenance	Points	Rate Group	Hourly Rate
elec plan	trical maintenance, ca t systems (air conditi	tradesmen engaged in one rpentry, pipe fitting, to oning, air, oils, water mechanical repair, elec	welding, brickla , etc.), iron an	ying, auto med	chanics, instru-
ties:					
:	schedule to insure wor	h assignment of personn k is completed on time.			
	Reviews operation and personnel, equipment a	makes recommendations r nd procedures.	elative to chang	es in organiz	ation,
	Assists with the follo employees, settling gr and administering pers	wing personnel function ievances, supervising s onnel policies.	s: disciplining afety and housek	and training eeping progra	of ms,
		ections of plant system			
	Assists with supervisi	ty for quality of work on of construction work	performed by ou	tside contrac	tors.
	Assists with inventory parts, supplies, mater areas.	control program for de ials and equipment. Al	partment and des so supervises ma	ignated plant intenance of	storage
7.	Attends department mee men from other departm	tings and conducts meet ents to discuss mutual	ings as required work problems.	. Meets with	fore-
8.	Responsible for proper	maintenance of product	ion and time rec	ords.	
9.	Performs other duties	as assigned.			
alifi Gener	.cations:	communication, and end	ineering skills		
Educa		High school graduate or			rience.
Exper	ience/prerequisite tra	aining <u>Several years e</u>	xperience in Mai	int. skilled t	rades work o
	al qualifications or	skills			
	ts to (job title):	Plant Engineer or A			
	onnel supervised or dis			Hourly	'nd weu
	Othe	XXOutside		VY MOTEN YX	————
Job h	nours: XX Days	tating shifts \(\sum Other \)	Assigned s		
rdarb	Machine	ines (typewriter, calcu tools	ing (XX)Other Teresary	esting/control	

JOB SPECIFICATION

Job Title				Job No.		
PLANT ENGINEER				LNCIØ		
Division Plant Location Department				Job Level		
GCD	Oakland, CA	Maintenance	Points	Rate Group	Hourly Rate	
General Function & Responsibility:			185		1	

Directs subordinate supervision and salary and hourly personnel engaged in all phases of plant engineering function, including installation, repair, and maintenance of all plant systems, equipment, grounds, and facilities, including pollution control systems. Responsible for all related design work.

Duties:

- Plans department work schedules and directs assignment of personnel and equipment. Insures work is completed on time, and revises work schedules to reflect changed plant or department priorities.
- Analyzes operations and makes recommendations to supervisor relative to changes in organization, personnel, equipment, department policies and procedures. Prepares department short and long range plans. Reviews and recommends appropriate action on maintenance requests, materials requisitions, forms 901, etc.
- Hires and disciplines employees; supervises training and development of personnel; participates in settling of grievances; directs safety and housekeeping programs; insures personnel policies are properly applied.
- 4. Conducts periodic inspections of all plant systems, equipment, facilities and grounds, and takes corrective action. Directs plant preventive maintenance programs; has a major responsibility for furnace rebuilds.
- Responsible for quality of all work performed by maintenance employees. Also coordinates and supervises all construction work performed by outside contractors.
- Responsible for all department and designated plant parts, supplies, materials and equipment. Submits requisitions to Purchasing, and meets with vendor representatives to discuss technical requirements.
- Conducts regular department meetings. Meets with supervisor and other supervisors and managers to discuss common problems and projects. Has working relationship with Toledo Engineering and outside contractors.
- 8. Develops and administers department budget. Responsible for accurate preparation and maintenance of all department records and reports.
- 9. Performs other duties as assigned.

Qualifications:					
General	Management	, communication	and diversifie	d engineering.	
Education or equi	valent BS de	gree in Mechani	cal or Electric	cal Engineering.	
Experience/prerec	misite traini	ng <u>Experience</u>	as Maint. forem	nan and/or in plant	t engineering services
Special qualifica	tions or skil	ls			services.
Job Parameters: Reports to (job t	itle):	Plant Manage	r		
Personnel supervi	sed or direct	ed: 3-5	Salary	77 Hourly	
Job conditions:	Inside XX	70utside 🗁 Ter	mperature extre	emes 🐼 Noisy 🐼	7Dirty
Job effort: Phys Job hours: 🐼 Da	ical strength			eavy	
			cessing 🖅 Oth	Laboratory ner Repair & mainte testing & control	
Analyzed by	Date	Checked by	Date	W&S Approval	Date
		1		DNL	FEB 2.2 198

SPILL RESPONSE TRAINING
(First Responder - Awareness Level)

DATE: 9/9/97 PLANT: Ozkland INSTRUCTOR: B. Wezl
SUBJECTS COVERED: Hzz. Substances, 1st. Responder Actions, Video
Emergency ve Traidental Spills, Reporting Spill Plan See Attached Agenda and Copy of Slides
NAME (print) SIGNATURE JOB TITLE
DATE: 9/9/97 PLANT: DZK/ZUD INSTRUCTOR: B. Nez/ (2 pm. sees row) SUBJECTS COVERED: HZZ. Substances, 1st. Responder Actions, Video Emergency vs Tocidental Spills, Reporting Spill Plan See Attached Agenda and Copy of slides NAME (print) SIGNATURE 1. Bob Nez/ Robert C. Weel Environmental Administrator
2. Steve Springer Steve Springer General toreman
3. ANTONIO LANDAVERDE Aufoninfandamente Selecting Maintenance
4. FRANK GOOCH June fool SELECTING MAINT.
5. Don Clark DorChark Selecting Want.
6. Kuh Washed Yh Washed Sel Mant. 7. FORREST MAXO Foront I My Marint. 8. Tom MAHONEY Tom Mahoney Sen Maint. 8. Tom MAHONEY Tom Mahoney Sen Maint.
7. FORREST MAXO format I My MISINT.
8. Tom MAHONEY Tom Mahoney Sen Maint. 9. FON SAKMER Lon Salmer Gen Maint
10 ELCHARD TORKES RUBBLE
11. LARRY BERTRAND Garry Bouth
12. DAVID BURNIGHT (Jame Burnight) MAINT.
13. MIKE NIETOGOMEZ Michael Jule Somes Maint
13. MIKE NIETOGOMEZ Michaelferte somer Maint 14. Jasus J Varrela Jesus Varela mount
15. Jose & Martine
.16.

17.

SPILL RESPONSE TRAINING
(First Responder - Awareness Level)

DATE: 9/9/97 PLANT: Oakland INSTRUCTOR: B. Neal
SUBJECTS COVERED: Hzz, Substances, 1st Responder Actions, Video Emergency Vs Incidental Spills, Reporting, Spill Plan See Attached Agenda and Copy of Stides NAME (print) SIGNATURE JOB TITLE Planing track
Emergency Vs Incidental Spills, Reporting Spill Phu
NAME (print) SIGNATURE JOB TITLE
1. Bob Nez
2. Nel Seration Will Seration Mainte
3. RAYMOND TORRES former Rouns SEL. MAINT.
4. JAVIER MORALES Jumn. Monder MAINT MECH. APP.
5. Charles Pugh Jr. Charles Frust MAINT ELECT.
6. ED CAHOTAL BODOLD ELECTRICAN
a sul chausen of Land CRad (
O IT TIDE WILLIAM PROL
9. JOSE T MORALES Jose & Morale SELECT MAINT.
9. JOSE T MORACES JOSE SELECTING MINT. 10. NERY D.FILDANA Selecting Mint. 10. NERY D.FILDANA Colon Colon Colon Colon Colon Colon MECHANIC, SCICETA
10. NERY D. ALDANA. Jack Calvin C. There MECHANIC, SECTION 11. CALVIN YADEN Calvin C. There MECHANIC, SECTION 11.
i 2.
13.
14.
15.
16.
17.

SPILL RESPONSE TRAINING

(First Responder - Awareness Level)

DATE: 9/10/97 PLANT: Oakland INSTRUCTOR: B. Neal	
(L'00 3.m. Session)	
SUBJECTS COVERED: Haz. Substances, 1st. Responder Actions, Video "Proporto Repord Emergency to Incidental Spille, Reporting Rold., Spill Plan See Attached Agenda and Handout	••
See Attached Agenda and Handout	
NAME (print) SIGNATURE JOB TITLE	
1. Bob Neal Robert C. Weal Environmental Administra.	Ł
2. DAVID Strayer David Strayer Select maint	
3. MICHEL LHEUREUX Wind depend	
4. HENRY CHEW his ches sel. maint.	
5. GREG BROWN Shey Brown	
6.	
7.	
8.	
9.	
10.	
11.	
12.	
13.	
14.	
15 .	
16.	
17.	
A F ,	

SPILL RESPONSE TRAINING

(First Responder - Awareness Level)

DATE: 9/0/97 PLANT: Osk/and INSTRUCTOR: Rob Nes/	
SUBJECTS COVERED: Haze Substances Let Rossen den Actions Video Presser de Poss	1
SUBJECTS COVERED: Haz. Substances 1st. Regnader Actions Video Prepare to Regnancy Je Tucidents/ Spills, Reporting Rgid., Spill Plan See Attached Agences and Handout NAME (print) SIGNATURE JOB TITLE	~~
See Attached Agenta and Handout	
NAME (print) SIGNATURE JOB TITLE	
1. Bob Neal Kobert C. The Eurironmental Haministrate	>
2. E. ZAMORA Eleutono moral M. Mechmic	
3. ERNEST WAIGHT Emat Chieft M. HACHANIE	
4. PEDRO KAMIREZ PENLO Jamis JAVISON HOT ENd	•
5. Richard W. Gray Ruland W. Bray C. E. Foreman	
6. JUANITO P. AGCANGO -	
6. JUANITO P. AGCANGE MONIT. 7. Delong, Wikking William Hely Monit.	
8. Kdrud Forg Roland Jose Sel-Maint	
9. Enrique Canho, Te	
10. Edgardo Valentin F. // Sel. Mant	
11. ROMEO M. BINONGCALSEL. MAINT.	
12. HENRY V. RULL SER. MAINT.	
13. Philip Cobb	
14 MIVE BATTU Wiche Salles SEL MAINT	
15. EMIL BERNARDO & PUDO SEL. MAINI	
16. J. Moruno Batch & Furnace Superiso	<u></u>
17. I Horr SATCH WAIL C.L.	
HWOLF HWOLF Though CLA CREWNEADER Though M. MEEH.	
Thomas M. MEEH.	

PHOTO PHILIPHOND 9/10/97
Noon Se
Vie Carlson ion Killer

Dave Allamon 9

SPILL RESPONSE TRAINING

(First Responder - Awareness Level)


DATE: 9/10/97 PLANT: Dakland (3 p.m. Session)	_ INSTRUCTOR: Bob Neal
SUBJECTS COVERED: Haz. Substances !	t. Responder Actions Video Prepare to Reso
SUBJECTS COVERED: Haz. Substances Is Emergency To Indide. See Attached Age.	Hal Spills Reporting Rad., Spill Plan
NAME (print) SIGNATURE	JOB TITLE
1. Bob New Robert C. Ke	al Environmental Haministrator
2. U, Ry; L HENLEY Virgil Heal 3, AL =X GUTIERREZ Alalix Lu	ley CE Maint Supervisor
3. I. ALEX GUTIERREZ Aller Su	tione Master Mechanic
A FOLL C LEE Donnell J.	mechanic
5. JESUS G. DONES Jesus	J. VONS LEAD MECHANIC
6. Bill Hom	How Mechan
7. Noel Lansangan Moul Re	Carry Marisana Lech
8. Hark Wiele / Hark 1 9.	way per ang.
9.	· ·
10.	
11.	
12.	
13.	•
14.	
15.	
16.	
17.	

SPILL RESPONSE TRAINING AGENDA (First Responder - Awareness Level)

- First Responder Awareness Level Defined
- General Principles of Hazardous Substances
- Hazardous Substances in a Glass Plant
- Spill Response Classifications
- "Prepare to Respond" (18 min. video)
- First Response Awareness Level Actions
- Plant Spill Contingency Plan
- Miscellaneous Information
- Review

SPILL RESPONSE

(FIRST RESPONDER - AWARENESS LEVEL)



SPILL RESPONSE TRAINING AGENDA (First Responder - Awareness Level)

- First Responder Awareness Level Defined
- General Principles of Hazardous Substances
- Hazardous Substances in a Glass Plant
- Spill Response Classifications
- "Prepare to Respond" (18 min. video)
- First Response Awareness Level Actions
- Plant Spill Contingency Plan
- Miscellaneous Information
- Review

■ FIRST RESPONDER - AWARENESS LEVEL

- First responders at the awareness level are individuals who are likely to witness or discover a hazardous substance release and who have been trained to initiate an emergency* response sequence by notifying the authorities of the release. First responders at the awareness level shall have sufficient training or have had sufficient experience to objectively demonstrate competency in the following areas:
 - understand what hazardous substances are and the risk associated with them in an incident
 - understand the potential outcomes associated with an emergency when hazardous materials are present

■ FIRST RESPONDER - AWARENESS LEVEL (Continued)

- the ability to recognize the presence of hazardous substances in an emergency
- the ability to identify the hazardous substance(s), if possible
- understanding of the role of the first responder awareness level individual in the employer's emergency response plan
- the ability to realize the need for additional resources, and to make appropriate notification

GENERAL PRINCIPLES OF HAZARDOUS SUBSTANCES

- Classes of Hazards
 - **Physical** Includes fires, explosions or other effects by mechanical means. Physical hazards may result from hazardous substances such as gasoline, compressed gases, cryogenic liquids, oxidizers and corrosive (acid or caustic) mixtures .
 - **Health** Contact your body directly and can cause biological reactions, destroy tissue or make you sick. These hazards may be immediate or delayed (**Acute** or **Chronic**). Health hazards may result from hazardous substances such as toxics (poisons, irritants, carcinogens, mutagens) or corrosives (acids and caustics).

HAZARDOUS SUBSTANCES

- Hazardous substances are materials to which exposure results in or may result in adverse affects on health, safety or the environment.
- Typical Hazardous Substances
 - Flammables (gasoline, propane, MEK)
 - Combustibles (diesel, oils, paints, solvents)
 - Corrosives (acids, caustics, salts)
 - Toxics (ammonia, chlorine, pesticides)
 - Reactives (explosives, oxidizers, a/b mixtures)
 - Hazardous Wastes (all RCRA wastes)
 - Compressed Gas (acetylene, propane, chlorine)
 - Physical Hazards (cryogenic liquids, molten s)

HAZARDOUS SUBSTANCES

COMMON IN A GLASS PLANT

HAZARDOUS SUBSTANCE	NAERG#
Safety Kleen Parts Washer Solvents	128
Methyl Ethyl Ketone (MEK)	127
Ammonia	125
Tin Tetrachloride	137
Sulfuric Acid	137
Muriatic Acid	157
Oakite (Caustic Cleaner) / Caustic Soda	154
Lube Oils / Diesel / Used Oil / Gasoline	128
Propane	115
Water Treatment Chemicals	154
Chlorine	124
SFL (contains xylene)	130
Checker Dust	171
Tin Reclaimable Material	154

SPILL RESPONSE CLASSIFICATIONS

- An Emergency Response is defined as a response effort by persons from outside the immediate release area or by other designated responders (i.e. fire department) to an occurrence which results or is likely to result, in an uncontrolled release of a hazardous substance.
 - Responses to <u>incidental releases</u> of hazardous substances where the substance can be absorbed, neutralized, or otherwise controlled at the time of release by employees in the immediate area, or by maintenance personnel are not considered to be emergency responses. Responses to release of hazardous substances where there is no potential safety or health hazard (i.e. fire, explosion or chemical exposure) are not emergency responses.

EMERGENCY RESPONSE VS INCIDENTAL SPILL

Any of the following would be considered an "emergency".

- The release / spill is forcing workers out of the area! The immediate area needs to be evacuated.
- The required level of personal protective equipment excees the level provided the employee for handling.
- There is a potential risk to health, safety, or environment.

If one or more of the above conditions is present - an emergency response situation exists.

Assessment of hazardous conditions and substances is a case-by-case issue when determining incidental vs emergency situations.

"Prepare To Respond"

Video on First Responder - Awareness Level

FIRST RESPONSE AWARENESS LEVEL ACTIONS

- Fundamentals of a First Response
 - Approach cautiously from upwind. Do not rush in; others cannot be helped until the situation has been fully assessed.
 - **Secure the scene.** Without entering the immediate area, isolate the area and assure the safety of people and the environment, keep people away from the spill area.
 - Identify the hazard. Placards, container labels, shipping documents, or knowledgeable persons on the scene are valuable sources of information.

- Fundamentals of a First Response (Cont'd)
 - **Assess the situation.** Does the amount of the spill / release constitute a "hazard"? What about the location of the spilled substance?
 - Obtain Help! Obtain internal help and <u>if needed</u> advise management to notify responsible agencies and call for assistance from qualified personnel.
 - Decide on site entry. Any efforts to rescue persons, protect property or the environment must be weighed against the possibility that you could become part of the problem. Enter the spill area only if you are wearing appropriate protective gear and you have the appropriate level of training.

- Fundamentals of a First Response (Cont'd)
- TRAINED AND PROPERLY EQUIPPED

 PERSONNEL. Respond in an appropriate manner.

 Establish a command post. Rescue any casualties only where possible without personal risk. Evacuate if necessary. Maintain control of the area.

 Continually assess the situation and modify the response accordingly. The first duty is to consider the safety of people.

- Fundamentals of a First Response (Cont'd)

• General Rules of Thumb

Do not walk into or handle spilled material.

Avoid inhalation of fumes, smoke, and vapors, even if no haz. material is known to be involved.

Do not assume that gasses or vapors are harmless due to a lack of odor. They could be harmful!

REPORTING REQUIREMENTS

- Reporting Requirements. EPCRA, CERCLA, RCRA and CWA. Any of the following fall under the reporting requirements.
 - The released material exceeds the Reportable Quantity (RQ) in any 24-hour period.
 - A release, fire, explosion that could threaten human health or the environment outside the facility.
 - An oil spill into the "navigable waterways" of the US or onto land from which it might flow or drain into said waters.
- Such spills must be immediately reported to the National Response Center, local authorities and State authorities. Not all spills require notification.

REPORTABLE QUANTITIES FOR COMMON GLASS PLANT SUBSTANCES

HAZARDOUS SUBSTANCE	REPORTABLE QUANTITY
Ammonia	100 lbs
Checker Dust	100 lbs
Sulfuric Acid	1,000 lbs
Potassium Hydroxide	2,000 lbs
Methyl Ethyl Ketone (MEK)	5,000 lbs
Hydrochloric Acid	5,000 lbs
Tin Tetrachloride	8,910 lbs
Tin Reclaimable Material	15,150 lbs
Oil on Navigable Waters	Quantity that produces sheen

REVIEW SPILL RESPONSE

(First Responder - Awareness Level)

- First Responder Awareness Level Defined
 - General Principles of Hazardous Substances
 - Hazardous Substances in a Glass Plant
 - Spill Response Classifications
 - --(Incidental vs Emergency)--
 - "Prepare to Respond" (video)
 - First Response Awareness Level Actions
 - Plant Spill Contingency Plan
 - Miscellaneous Information

COMPANY OWENS-ILLINOIS, INC. Job Description and Classification

X0901

ant Job Title STORES RECEIVER & DISPENSER - 1st CLASS	Plant Job Code0-90
Plant 20, 21, 23, 22	Standard Title
Department Purchasing & Stores	Std. Job Code
Operation GC - West	Effective Date 6-22-73

PRIMARY FUNCTION:

To perform general plant storekeeping duties involving receiving, storing and issuing storeroom materials and supplies.

TOOLS AND EQUIPMENT:

Hammer, nail puller, pliers, power hacksaw, hi-lift, calculator, etc.

MATERIALS AND PRODUCTS:

Storeroom materials and supplies, refractories, stationery, etc.

SUPERVISED BY:

Storeroom Supervisor or Storekeeper-Buyer

DIRECTION EXERCISED:

May relay instruction to the Stores Receiver & Dispenser-2nd Class.

TYPICAL DUTIES:

- 1. Receives, counts, inspects and verifies incoming materials and supplies and stores systematically on shelves or bins. May use hi-lift to unload or move heavy material Performs some unloading manually.
- 2. Packs materials or supplies not meeting specifications for return to suppliers, and prepares materials or supplies for shipment to other plants. Weighs material to be sent out such as molds or machine parts and will move boxes or crates to proper pickup point.
- 3. Processes necessary paper work to reflect such transfers.
- 4. Dispenses storeroom materials and supplies to plant personnel against approved requisitions. Refers certain requisitions to salvage center when substitute material possible.
- 5. Receives, checks, stores and dispenses stationery stores and supplies to Pacific Region Plants, Sales Branches and General Offices. (Oakland)
- 6. Inventories a portion of stock daily, checks against stock cards and requests replacement of "non-value" items to maintain normal inventory. Participates in regular physical inventoring.
- 7. Places orders with vendors to replenish stock when we have a blanket order with the vendor. Otherwise will pull and process a Traveling Requisition when the re-order point is reached on an item.
- 3. Posts activity to stock record cards.
- 9. Keeps work area neat and orderly.
- 10. Is responsible for notifying the department involved whenever an item comes in for which they are waiting.
- 11. Measures gas and oil in storage tanks, counts frit inventory and some batch colorant material.

Company	Owens-Illinois, Inc.	Plant 20, 21, 23, 22
Plant Job Title_	Stores Receiver & Dispenser-lst Class	Std. Job Title
Plant Job Code	0-90	Std. Job Code

Factor Degree		Points	Reason for Classification			
Knowledge B		.5	Requires some specialized knowledge involving accepted storekeeping and dispensing procedures.			
ls	2 Experience	С	1.0	Requires up to 12 months of continuous experience to become familiar with a wide variety of materials handled and storeroom procedures.		
Skills	3 Judgment	С	1.0	Uses judgment to perform semi-routine storeroom duties and handle responsibilities where actions to be taken and decisions to be made are somewhat limited.		
	Manual Skill	В	.4	Operates a hi-lift from time to time in unloading or moving materials, supplies or refractories.		
Responsibility	Materials and Products	СЪ	1.7	Duties are standardized subject to clearly defined practices and procedures and general supervision. Errors made in receiving or dispensing material or supplies would not normally exceed \$1000.		
Respon	Tools and Equipment	Ca	.5	Required to use care when operating hi-lift to prevent damage. Probability of damage is low.		
ort	7 Mental	В	.5	Light mental and visual application required in receiving incoming materials and supplies, in dispensing items, and in maintaining storeroom.		
Effe	8 Physical	Ca	.6	Moderate physical exertion required. Materials vary from light to heavy with handling of medium to heavy weight items intermittently.		
tions	9 Surroundings	В	.5	Is exposed to inside and outside conditions due to location of storeroom, however, not required to remain out in extreme conditions.		
Conditions	10 Hazards	В	.5	Accident hazards moderate with some exposure to cuts, bruises or crushed fingers when handling medium to heavy weight items.		
Tot	tal Points		7.2	Described By DNL Date 6-22-73 Supercedes:		
Job Group 7		7	Classified By DNL Date 6-22-73 Same Approved By RLS Date Same Plant Job Title Same Plant Job Code			

COMPANY OWENS-ILLINOIS, INC.

Job Description and Classification

60304

Plant Job Title UTILITY WORKER	Plant Job Code <u>G-31</u>
Plant#20, #21, #23	Standard Title
Department SELECTING	Std. Job Code
Operation GC - West	Effective Date 9-1-69

PRIMARY FUNCTION:

To perform general cleanup and utility work in the Resort area.

TOOLS and EQUIPMENT:

Broom, shovel, dust pan, trash cans, hand truck, etc.

MATERIALS and PRODUCTS:

Cullet, cartons, pallets, etc.

SUPERVISED BY:

Shift Foreman

DIRECTION EXERCISED:

None

TYPICAL DUTIES:

- 1. Sweeps, cleans up and disposes of broken glass, damaged cartons and other debris in the Resort area.
- 2. Dumps ware resulting from cullet authorization.
- 3. Salvages corrugated cases.
- 4. Transfers cases of ware from pallets to resort tables.
- 5. Moves empty pallets by hydraulic hand truck to pickup area.
- 6. Moves or assists in moving resort equipment such as tables, conveyors, etc.

Company CHENS-ILLINOIS, INC.	Plant#20, #21, #23
Plant Job Title UTILITY WORKER	Std. Job Title
f_t Job Code_G-31	Std. Job Code

	Factor	Degree	Points	Reason for Classification
-	1 · Knowladge	A	Base	Performs work of a semi-repetitive nature to carry out simple verbal or written instructions handling routine manual tasks.
Skills	Experience	A	Base	Requires 2 to 4 weeks of continuous progress to gain sufficient experience to perform duties proficiently.
	3 Judgment	A	Base	Performs simple, repetitive, routine and closely directed tasks.
	Manual Skill	A	Base	Handles ordinary material manually where manual dexterity and accuracy are not of particular importance.
Responsit	Materials and Products	A	Base	Performs manual cleanup and routine material handling duties where damage or loss to materials is unlikely.
	Tools and Equipment	Ba	.2	Required to prevent damage in using a hand lift truck, but probability of damage is low.
ırt	7 Mental	A	Base	Minimum mental or visual application required for performing routine, simple cleanup and material handling duties.
Effort	8 Physical	Da	1.4	Handles medium to heavy weight materials when transferring ware or assisting in the moving of equipment, but extent of such work is less than 50% of working time.
itions	Surroundings	A	Base	Works inside average factory type building with some exposure to dirt, noise and not necessarily uniformly heated.
	10 Hazards	В	.5	Hazards exists with some exposure to cuts, bruises or crushed fingers when handling medium to heavy weight products.

Total Points	2.1	Described By ACM Date	Supercedes:
		Classified By ACM Date	Same
Job Group	2	Approved By RLS Date	Plant Job Title -
		<i>, ~</i> .	Plant Job Code

JOB DESCRIPTION & CLASSIFICATION

OWENS-ILLINOIS

B1100

"Int Job Title	Furnace Tender	Plant Job Code <u>B-110</u>
Plant :	#20, 21	Standard Title
Department	Batch & Furnace	Std. Job Code
Operation	GC - West	Effective Date 9/1/69

PRIMARY FUNCTION:

To charge and operate furnaces and to observe and adjust controls in the production of molten glass.

TOOLS AND EQUIPMENT:

Gas, oil or electric furnaces and related feeding, recording and controlling equipment, hand tools, etc.

MATERIALS AND PRODUCTS:

Batch material, fuel, air, molten glass, etc.

SUPERVISED BY:

Combustion Engineer

DIRECTION EXERCISED:

None

YPICAL DUTIES:

- 1. Charges furnaces with batch material at required rate.
- 2. Observes various indicating and recording instruments to ensure specified material and fuel temperatures, levels, pressures, etc., as applicable and makes necessary adjustments or changes to maintain prescribed procedures.
- 3. Operates small frit furnace as necessary.
- 4. Periodically examines furnaces and related feeding and control equipment, notifying Foreman of malfunctions.
- 5. Maintains record of furnace operation, material use, output, fuel consumption, etc., as required.

Plant.		F20, 21	
Plant	Job Title _	Furnace Tender	Std. Job Title
Plant	Job Code	B-110	Std. Job Code

		1			
Factor	Degree	Points	Reason for Classification		
Knowled	g• B	.5	Requires knowledge of furnace operation to make necessar decisions and adjustments.		
Experien	D D	2.0	Requires more than 12 months but less than 24 months to become proficient.		
Judgme	nt C	1.0	Uses judgment where actions to be taken and decisions made to operate furnace are limited.		
Manua Skill	I A	Base	Operates simple controls. Dexterity and pace are not of particular importance.		
Products Cc 2.5 Has		2.5	Follows standardized procedures in operation of furnace. Has some latitude in operation of furnace which can result in material or product losses exceeding \$1,000.		
Tools and Equipme		1.0	Intermittent care and attention required to prevent damage in operation of glass furnace. Large measure of control placed on automatic devices.		
7 Menta	C	1.0	Moderate mental or visual application required to detect and adjust for variance from proper furnace operation.		
8 Physica	Ba	.2	Low physical exertion required. Considerable walking and climbing involved, and some clean up and handling of light tools, but for less than 50% of the work period.		
Surround i	ngs C	1.0	Considerable heat when in proximity of furnace but not for extended periods.		
Conditions Date of the Conditions of the Conditi	Hazards		Exposure to burns and falls such as may occur when working on and around furnaces.		
Total Points 10.2 Described By JHF Date 4/22/77 Supercedes:		Described By JHF Date 4/22/77 Supercedes:			
Job Group	Group 10 Classified By JHF Date 4/22/77 SAME Approved By HMW Date Plant Job Title		Classified By JHF Dore 4/22/77 SAME		
			Plant Job Code		

T		-		
	•	•		
	•			
-				
			¥	
i				
!				
1				
				•
ļ				•
				•
1				
I				
I				
I				
I				
I				
			,	
1				
				•
1				
Date of the state				
1				
1				
İ				
!			-	
•			-	
i				•
-				
i				
1				
!				

BOB BARBER -> CONTACT NAME

Facsimile Transmission Face Sheet



City of Oakland

FIRE DEPARTMENT OFFICE OF EMERGENCY SERVICES



P. 1

-			510 -
ROM:_	Lensy Griffin		PHONE: 238-3938
TES:_	pages 1-3	juspecta neports	Hazandaus Wask.
	page 4-10	1.9	Нивр
			AIR AIR AIR AIR AIR AIR AIR AIR AIR AIR
			-

CITY OF OAKLAND FIRE DEPARTMENT OFFICE OF EMERGENCY SERVICES DIVISION 505 14th Street, 7th Floor Oakland, CA 94612

> PHONE (510) 238-3938 FAX (510) 238-7761

HAZARI	OOUS WA	ST	Έ	GEN	ER	ATOR INSPECTION REPORT				
ADDRESS: 3600 Alum	ockne	~ <u>~</u>	-			EPA 1.0.#:	00061	89	8	
ADDRESS: 3600 Alum	order A	D	e_			,	DATE: 11-4			
		CC	MC	PLIANC	E					NCE
	CODE SECTION	YE	s	NO N	/A		SECTION	YES	NO	N/A
I. IDENTIFICATION NUMBER	SECTION	L		1_	-	6. CONTINENCY/BUSINESS PLAN				
(a) Obtained EPA I.D. Number	66262.12(a)		7		_	(a) Contingency Plan Complete	66265.52(4-1)	L		7
(b) Transporter and TSDF Have EPA L.D.#	66265.12(c)	5	\mathcal{H}	_	-	(b) Copy of Plan on Site	66265.53			1
2. PRE-TRANSPORT REQUIREMENTS			_			(c) Contingency/Business Plun Submitted	66265.53(b)		 	†
(a) HW Containers Labeled	66262.31	1	7			(d) Plan Amended as Necessary	66265.54	\Box	-	
(b) HW Label Properly Filled Out	66262.32(14)	Н	H		\neg	(e) ER Coordinator Familiar w/Plan	66265,55			
(c) HW Accumulation of Time Not Exceeded	66262.34 (c)	H	1		_	7. PREPAREDNESS AND PREVENTION				
(d) Accumulation Date Indicated	66262.34(f)	H	H			(a) Internal Commun./Alarm Provided	66265.32(a)	}		
(c) Description of HW Contents	66262.34(f)	Н	H	-	\dashv	(b) A Device to Call Outside Provided	66265.32(Ь)			1
(f) HW Containers in Good Condition	66265.171		H			(c) Spill Control Systems Available	66265.32(c)		 	1
(g) HW Compatible with Containers	66265.172		H			(d) Maintain ER Equipment	66265,33	\vdash	 	
(h) HW Containers Closed/Sealed	66265.173	-	H			(c) Security Measure	66265.14	H	┢	
(i) HW Storage Area Inspected Weekly	66265.174		Н			(f) Maintain Adequate Aisle Space	66265.35	\vdash	<u> </u>	t
(j) Tank & Tank Equip, Inspected Daily	66265,195		H			(g) Arrangements W/Local Agencies	66235.37	H		
(k) Incompatible HW in Separate Containers	66265.199		H			8. EMERGENCY PROCEDURES				
(i) Proper Management of Used Oil Filters	66266.130	H	┪		×	(a) Character/Source/Extent of ER Determined	66265.56	1		X
3. RECORDKEEPING AND REPORTING					_	(b) Proper Agencies Notified of Health Hazard	66265.56		1	1×
(a) HW Analysis Kept 5 Yrs./Land Disposal	66262.11		٦		,	(c) ER Data Submitted to DTSC & LIA	66265.56		\vdash	
(b) Biennial Report Submitted to State	66262.41	(d) Uncontrol. Release HW Property Handled		66235.56		 	 			
4. MANIFEST/RECEIPTS		Щ.			Ť	9. WASTE STREAMS				1,
(a) HW Shipped with Proper Manifest	66262.20	ı	ì			(a) Waste Oil		X		T
(b) Manifests Kept for Last 3 Years	66262,40(a)	Н				(b) Non-Halogenated Solvents/Parts Cleaner		×	 	1
(c) HW Analysis Kept for 3 Years	66262.40(c)	Н	Ħ		X	(c) Ethylene Glycol/Antifreeze		-	<u> </u>	
(d) Manifests Received from TSDF	66262.42	7	7		-	(d) Oily Sludges				
5. TRAINING						(e) Other:			-	
(a) Training Program Provided	66265.16					(f) Other:	_			1
(b) Personnel Trained & Supervised	66265.16(b)				_	(g) Other:		 		
(c) HW Personnel Trained within 6 Months	66265.16(b)		7			(h) Other:			 	+-
(d) Training Records Kept on Site	66265.16(d)	Н				1.00				t
(e) Training Records Maintained for 3 Years	66265,16(e)	Н						1	<u> </u>	
(f) Training Records Complete	66265.16(1,2)					All above code sections refer to the Ca	ılifornia Code o	Reg	Title	22
Source Reduction Plan Completed	25244.19				X	Pollution Prevention	Health & Safety Code			
REMARKS:								·	1	<u></u>
							······································			

	· · · · · · · · · · · · · · · · · · ·			******			***	••••		

Page	of	ļ	
	~.	6	

white -env.health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

Oakland, CA 94621 (415) 271-4320

80 Swan Way, #200

Hazardous Materials Inspection Form

	ste M./. ste
LA BUSINESS PLANS (Title 19)	ID # 866 Ste Name DWENS BAILAWAY Date 4/11 197
	Site Address 3600 MAMEDA
	City 01/2 Zip 94 60 Phone 734 - 2057
	MAX AMT stored > 500 lbs. 55 gal 200 cft.?
B ACUTELY HAZ MATIS	inspection Categories: Haz. Mat/Waste GENERATOR/TRANSPORTER
10, Registration Form Filed 25533(c 11. Form Complete 25533(t 12. RMPP Contents 25534(c	iii. Underground lanks
13. Implement Sch. Regid? (Y/N) 14. OriSite Coreeq, Assess. 25524(c) 15. Probable Risk Assessment 25534(c) 16. Persone Responsible 25534(c)	n Calif. Administration Code (CAC) or the Health & Safety Code (HS&C)
III. UNDERGROUND TANKS (Title 23)	- plurial proper monitorint Book for
1. Permit Application 25284	
	- SOMPLEKE AND SENDIN PARTI
Senti-curuci grick-citer One time soit: 3) Daily Vacione	SUM COLE THE SELECTION OF THE SELECTION
One first sols Annual tank list 6 4) Monthly Gnoblester	HARP AS DISCUSED.
Annual trans test 4) Martiffly Godhecter Creatiffre sols 5) Dolly theentiary Annual trans testing Contribute sols 6) Dolly inventory Annual trans transcript Contribute sols Contribute sols Contribute sols Annual transcript Annual	- 2ABEL ZGILIN LABRE BAR. WASTE
Vocidate/gindwater mon. 6) Daily Inventory Annual fault testing Cont pipe lack defi	
8) Arrual Tank Testing	Constainers
Odly inventory 9) Other	- SEND IN AIRICIFIAM RAJET.
Date:	
10. Ground Worker, 2647 11.Monitor Plan 2622 12.Access. Secure	- Confly 41712 300 475!
13.Plane Submit 2711 2711	
2 Dd1e: 2635	
Contact:	II, III
Title:	Inspector:
\$ignature:	Signature:

while -env.health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF **ENVIRONMENTAL HEALTH**

K- G-HOLAMI

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

	yellow -facility	EN	NVIRONMENTAL HEALTH (415) 271-4320
	pink -files	На	zardous Materials Inspection Form
	BUSINESS PLANS (Title 19) 1. Immediate Reporting 2. Bus. Plan Sids. 3. RR Cars > 30 days 4. Inventory Information 5. Inventory Compilate 6. Emergency Response 7. Training 8. Deficiency 9. Modification ACUTELY HAZ MATLS 10. Registration Form filed 11. Form Complete 12. RMPP Contents 13. Implement Sch. Regid? (Y/N) 14. Offsite Conseq. Assess. 15. Probable Risk Assessment 16. Persons Responsible 17. Certification 18. Exemption Request? (Y/N)	2703 25503(b) 25503,7 25504(c) 2750 25504(c) 25504(c) 25504(c) 25503(c) 25503(c) 25503(c) 25503(c) 25533(c) 25533(c) 25534(c) 25534(d) 25534(d) 25534(d) 25534(d) 25534(d) 25534(d)	Site Address 3600 MAMERIA AVE City OMMAND Zip 9460) Phone 736-2058 MAX AMT stored > 500 lbs. 55 gal 200 cft.? Inspection Categories: Haz. Mat/Waste GENERATOR/TRANSPORTER III. Business Plans, Acute Hazardous Materials Till. Underground Tanks Calif. Administration Code (CAC) or the Health & Safety Code (HS&C) Comments: 5 VN Nemalo (MSC)
III.		25538 23) 25284 (H&S) 25292 (H&S) 2712	101ESEL / INLENDED
Eukithg Tonke	4. Release Report 5. Closure Plans 6. Method 1) Marity Test 2) Daily Vodase Serri-arrival gnowater One little sale Arrival tank feel 4) Mority Gnowater One little sale Arrival tank feel 4) Mority Gnowater One little sale Arrival tank feel 5) Daily Inventory Arrival tank testing Contribute look det	2051 26570	- typica moste (HAZ MAD) GREATED ARE DOUBLE WARED FREE CHAS WENTED
Monitoring for t	Variable/grah-value mon. 6) Doily Inventory Avertal traft testing Conti pile lack det 7) Weekly York Gauge Arrual traft testing Doily Inventory 9) Other 7. Precis York Yest Date: 8. Inventory Rec. 9. Soil Testing 10, Ground Water.	 2643 2644 2646 2647	- Luguicominia de ail vos pi - Luguicominia de ail vos pi - Luguicominia de ail vos pi - Britanos le -
Hew Tanke	11.Monitor Plan 12.Access, Secure 13.Plans Submit Date: 14. As Bull' Date:	2632 2634 2711 2635	of Arme of he.
6 ¥	6/88		HIMMP PAND WAS DISCUSIED WILL SENDIN PANTIL

Contact:

BOB BARBER

Title:

Signature:

Inspector:

Signature:

OAKLAND FIRE SERVICES AGENCY/OFFICE OF EMERGENCY SERVICES

HAZARDOUS MATERIALS UNIT

505 - 14th Street, Oakland, CA 94612 (510) 238-3938

HAZARDOUS MATERIALS INSPECTION REPORT

Site Number	Facility Name	Facility Address	Zip Gode
G8	Owens - Brockway	3600 Alameda Are.	01
	Inspect		
Perm	vision to mercet gran oling Tower H-O	ned - Searly men. P1	
Co	oling lover 4-0	treatment room	
-	Signaj	n CORR. rign	
2	UST for degel of	gas, are going to be hem w/ AGT	
removes	1 in 98 - Replace 1	hem w/ AGT	
	·		
- Nu	mber of personnel h	andling H.M. need to	2
upelales	L -		
Z	0		-10
	nergency Ropunsi is	under review - A copy 2	mel
be sent	dr me		
	ARP I. I T		
[T]	MBP already submit	is Time	
NA	- not observed at in	is time	
	W W W W W W W W W W W W W W W W W W W		

Facility Contact/ Print Name:	Inspected By:	☐ Insp. Griffin	238-7759
Steve Springer		☐ Insp. Johnson	238-3804
Facility Contact Signature:	HEG	☐ Insp. Craford	238-7758
,		🔀 Insp. Gomez	238-7253
Ster Springer	Date:	11-4-97	

OAKLAND FIRE SERVICES AGENCY/OFFICE OF EMERGENCY SERVICES HAZARDOUS MATERIALS UNIT

505 - 14th Street, Oakland, CA 94612 (510) 238-3938 Hazardous Materials Inspection Report

	Owens Brockway									
		UNAUTHORIZED OPERATION	v	C	N	OBSERVATIONS				
400	Hazardous	Materials Release Response Plans and Inver	atory (1	IMRR	P/Busi	ness Plan)				
401	25507	Failure to report a release/threatened release.	·		×					
402	25504	Emergency Response Plan inadequate		X						
403	25509	Emergency contacts not provided/current		X						
404	25504	Personnel training program is inadequate		*						
405	25504	Hazardous Materials Chemical Inventory is not attached, is not accurate, or is incomplete		X						
406	25509	Site map is not attached or is not sufficient		X						
408	255339(a)	Acutely Hazardous Materials Registration not filed		×		abul update it				
408		Material Safety Data Sheets are not located where the Business Emergency plan (BEP) indicates they should be		×						
409		The BEP indicates the facility maintains hazardous materials response equipment, and the equipment listed is not in place and in operable condition		X						
410		Hazardous materials are not located in the designated areas as indicated on the site map		X						
411		Containers are not clearly labeled with the chemical name and hazard class		入						
412		Containers are in poor condition or are leaking		`						
413		Secondary containment is inadequate		X						
414		Emergency procedures are not adequately posted		X						
415		Monitoring records are not complete or are not current	,	X						

V=Violation C=Compliance N=Not applicable/addressed/Unknown

OAKLAND FIRE DEPARTMENT/OFFICE OF EMERGENCY SERVICES Hazardous Materials Management Program 475-14th Street, 9th Floor, Oakland, CA 94612, (510) 238-3938

HAZARDOUS MATERIALS INSPECTION REPORT

STID#:	FACILITY NAME			PG.	OF .
	O.	WENS - B	ROCKWAY		
ADDRESS: 3	600 Alamed	a Ave	(oi		
1) Compre	550	7	secured	a copped	at
all	times				
2) chech	Gire	exting.	annvall	4	ntour?
J		7			
3) Place	de facina	entry	ways w	/ NFOA	
	de facing	iafa)	<u> </u>	<u> </u>	
4) Label	Amnoni	<u>Sto</u>	Page	dealy	
,	"ANH"	(DROUS	Amnor	VIAUI	
	•				
					·
HMBP-	+ I + A		_30	days	
MSNS	e to date				
	434.2058				
FACILITY CO	ONTACTS/	,	INSPECTED	BY:	
SIGNATURE:	1000 100			=01P	
PRINT NAME	· BOBBB	RHER	DATE: 7-3	1.96	

	. 7	Dr.	OAKI	AND HAZARDOUS MATERIALS INSPECTION REPORT
Facility	Name:	2/44	IKAD:	BROCKURY Date: 22 Aug 25 MEDA AVE Inspector: LERGY GROFFIN
Phone:	- 2	36 - 2	OST	Inspection Time:
Contact	84	BB	ARBE	Administrative Time
ID No.:	86	6		SIC:
Compla	int/Invest	igation	Request	W/A Phone:
Compla	nant Nam of Comp	ie: Jaint		Findings:
	int:	_		t manuages.
				the appropriate boxes relating to chemical storage.
STORE	D (Vori	ginal (container	s ()smaller ()larger ()safety cans (Yexisting underground ()other
()flatt	/nitrous comable cr	omprese yogen li	sed gas quid (abustible liquid ()chlorinated solvents ()water soluble oil ()non-soluble oil ()waste oil ()Clammable compressed gas ()chlorinated solvents ()toxic/poison ()corrosive ()oxidizer ()non-flammable cryogen liquid ()oxygen-cryogen liquid ()other ()floor/shelf(surface tension) ()raised/lipped(berm/tray) ()lowered/dike(sump/grate)
(Ngou	ble walled	i tank	()liner	underground ()other
MONT	ORING	(V)vis	nal (A)	mechanical ()dip stock (v)vapor monitor ()other
EMER ()disp	GENCY I	EQUIP (~)p	MENT osted em	(Sfire extinguisher(s) (Mosorbents (Scollection containers (Sresponse team (Sgloves ergency procedures ()other
()disc ()rec Health	charge to ; ycle (ground)other _ Code (()disc	aterials and/or wastes handled and disposed of? () no waste () empty containers into trash harge to sewer () discharge to pretreatment-sewer () vaporise/vent to air (/) ship to haz-mat facility 6.95 Violations:
		-		Needs H.M.S. Permit
	<u></u>			
_	•		_	Business Plan/HMMP Inadequacies, check inadequate areas Facility Information Emergency Response Plan Record Keeping MSDS MSDS MSDS Other Emergency Plan Other Control of the control
	a		Q	Leaky/damaged containers
O .	ū			Secondary containment needed
				Evidence of spillage/release
				Incompatible materials need to be separated
			\Box	Unlabeled containers
				Unlabeled storage area
				Unsecured area
			O.	Container/vessel needs earthquake bracing/securing
				Storage too close to property line
				Storage too high
3				Empty containers need to be labeled/segregated
				Excessive storage of hazardous materials A special room or enclosure will be required. Contact Fire Prevention at 510 238-3851 for permit requirements.
				Inadequate aisle width
0				Combustible materials stored too close to hazardous materials
				Inadequate ventilation
	ū			Inadequate/faulty secondary containment
O.	ū		Ō	Containers left open - should be closed
				Other

OAKLAND FIRE DEPARTMENT/OFFICE OF EMERGENCY SERVICES Hazardous Materials Management Program 475-14th Street, 9th Floor, Oakland, CA 94612, (510) 238-3938

HAZARDOUS MATERIALS INSPECTION REPORT

STID#:	FACILITY NAME: OULUS- BROCKWA	+4	PG.	OF _/
ADDRESS:	3600 HAMEDA	AYE	94601	
1.) TERM	15510N to INSPECT	GRANT		
	·			
z.) HME	of part I complet	ed par	+II due in	30 Days
3.) Gla	essted	Tipe 1 1	racandous wa	ste
91	unsted	<i>y</i> •		
4.) Aug	id. Amnounce type	on Sit	z.	
			•	
-,,-,-	<i>T</i> .			
Ulala-	fimi	<u> </u>		·····
1/201	e noted during 1	1150-1		
HOM	E NOTED WURING I	NSPECI		
		,		
			•	
			·	
FACILITY CO SIGNATURE:	•	INSPECTE		
PRINT NAME	BOB BARBER	DATE:	Y GRIFFIN 22 AUG 95	
14/3141	· BOB BAKBER	DAIE:	ce Aug 13	

white -env.health yellow -facility pink -files

ALAMEDA COUNTY, DEPARTMENT OF **ENVIRONMENTAL HEALTH**

Hazardous Materials Inspection Form

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320 (510) -

11 111

		,					11,111
	sı	te ID #	Site Nan	ne	NEWS-BA	LUCKWAY	Today's ate[0]/4/9
LA BUSINESS PLANS (Title 19)				0			
2, Bus. Plan Stas,	2703 25503(b) 25503,7	Site	Address _	3600 A	LAMERK !	NE	
4, inventory information 5. Inventory Complete	25574(41)	City .	OALLA	~0	ZIp 946 0 1	Phone	436-2058
7, Training 8, Deficiency	25504(c) 25505(d) 25505(b)		MAX A	MT stored	> 500 lbs, 55 gal.	., 200 cff.7	
_ :			<u>inspectio</u> I. Haz. i	n Categor Mat/Waste	<u>:les:</u> GENERATOR/TRA	NSPORTER	
	25533(p) 25533(b)			es Plans, Ac	ute Hazardous N		
12. RMPP Carrients 13. Implement Sch. Regid? (Y/N)	25534(c)						
15. Probable Risk Assessment 16. Persons Responsible	25524(c) 25534(d) 25534(g)	° Co	illf. Administrati	on Code (C	AC) or the Healt		
16. Exemption Request? (Y/N)	25534(D) 25534(D) 25538	Com	ments:		, En	B NEAL 7	mwish(8ha 348276
III. UNDERGROUND TANKS (TITLE	23)	7 2	457 5	Dore	slk -gil	ED RUT	BAOMITORING
	25294 (H&S) 25292 (H&S) 2712	60	10 3-12	Is Not	ADEQVA	<u> </u>	
5, Clasure Plans	2651 2670	Pao	PMEIR		ADECADA		
				F QU	ioner		
Settlement graduater Graphtres sale 3) Daily Vadose			monitox	116-			
Che litre sols 2 Arruck fork feet 5 Ø Monthly Gnowater	<u> </u>		100				<i>[</i>
Armuel funit lest 6) Mantify Gnatwater One time sals 9) Daily inventory Armuel kan't testing Cont pipes leak det Vadase/gratwater mon. 6) Daily inventory Armuel funit lesting Cont pipe leak det 7) Weekly Tan't Gouge Armuel funk testing Armuel funk testing Cont pipe leak det	-	,			/		
Controlomies (and controlomies value) Southern Controlomies (and controlomies) Southern Controlomies (and controlomies)	<u> </u>						
E Armud funk heiting S Cont pipe leak det 5 7) Weeldy Tank Gauge		7	0		The state of the s		,
5) Annual Tank Testing Oddy Inventory			000				
7) Other	2043	<u> </u>	ANIDEN	MNIFE	wind int	<u> </u>	savibación.
5. Inventory Rec.	3044 2046		- Stewn				
11.Monitor Plan	2647	- 0	ا سان مع	t m P P	(BUSINELL	ala ()	DUTT).
313.Pigra Submit Date:	2034 2711					1	
Date:	2035	- 1	illing b	1AZ-~	BS 13 Land	LS Pref	OFA Ly
	L			, <u>!! </u>			
Contact:	BOB		3BRB	ER			II, III
Title:	1luns	ريع	٠	Ins	pector:	AMIR	K- CHO MANI
Signature:	1200		reul	Sig	nature:	<i>N.</i> /	1/1

white -env.health yellow -facility plnk -สิโอร

Title:

Signature:

ALAMEDA COUNTY, DEPARTMENT OF **ENVIRONMENTAL HEALTH**

K. GHOLAM 80 Swan Way, #200 Oakland, CA 9462 (415) 271-4320

(0/2)

Site Name owins 1900 and 190 a			На	zardous Materials Inspection Form	11,111
Invended to Reporting 2700 2	_			' (-
1. Designation from Fland 2553000 255300 255300 255300 255300 255300 255300 2553000 255300 255300 255300 255300 255300 255300 2553000 255300 255300 255300 255300 255300 255300 2553000 255300 255300 25530000 25530000 25530000 25530000 2553000 25530000 25530000 25530000 25530000 25530000	I.A	1, immediate Reporting 2, 8ts. Plan Sids, 3, RR Cars > 30 days 4, inventory information 5, inventory Camplete 6, Emergency Response 7, Training 8, Deficiency	25503(b) 25503.7 25504(c) 2730 25504(b) 25504(c) 25505(d)	Site Address 3600 ALAMEDA AVE City OMMAND Zip 9450 Phone 73 MAX AMT stored > 500 lbs, 55 gal., 200 cft.? Inspection Categories:	
1. Person Responsible 2504(g)	В.	i0. Registration Form Filed 11. Form Complete 12. RMPP Contents 13. Implement Sch. Regid? (Y/N) 14. OriSite Gorsed, Assess,	25533(b) 25534(c)) 25524(c)	II. Business Plans, Acute Hazardous Materials III. Underground Tanks	
I. Parmit Application 2. Pipeline Look Detection 2. Resides Deport 3. Resides Deport 4. Resides Deport 2. Color Person 2. Deport Deport 2. Deport Deport 2. Deport Deport 2. Depor	16. Persons Responsible 17. Certification 18. Exemption Request? (Y/N)	25534(p) 25534(p) 25534(p) 25534	5 458 12 mo 20 1098/0	,	
1) Monthly last 2) Day Vadane Santianual production Che fire sale 3) Day Vadane Che fire sale 4) Monthly Goldene Che fire sale 4) Monthly Goldene Che fire sale 5) Day Frenchay Annual fair there Con fire sale 7) Soly Frenchay Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Annual fair there Che fire sale 7) Che fire sale 7) Che fire sale 7) Che fire sale 7) Che fire sale 7) Sol Tentha 7) Che fire sale 7) Sol Tentha 7) Che fire sale 7) Sol Tentha 7) Che fire sale 7) Sol Tentha 7) Che fire sale 7) Sol Tentha 7) Che fire sale 7) Che fir			25284 (H&S) 25292 (H&S) 2712 2651	BOTH ARE POURLE WORLED FIBELCIES -	int.
Date: 2044 2045 2046 2046 2046 2046 2047 2047 2046 2047 2047 2047 2047 2047 2047 2047 2047 2047 2047 2048		1) Morathy feet 2) Dolly Vodose Sent-curving gnotwater Cine fame sale 3) Dolly Vodose Gine fame sale 4) Morathy Gnotwater Cine fame sale 4) Morathy Gnotwater Cine fame sale 5) Dolly inventory Annual tank testing Contribute lack det Vodose/gnotwater mon, 6) Dolly inventory Annual famic feeting Contribute lack det 7) Weekly York Gouge Annual famic feeting 8) Annual famic feeting Contribute lack det 7) Weekly Tank Gouge Annual famic feeting 8) Annual famic feeting Colly inventory		- Lugaricanial de la vos pe	<i>p</i>
12.Access. Secure 2024 2		Date:	2644 2646 2647	- BRITH WOS IE	
- HAMME PANTE WAS DISCUSIED WIN SEND IN PANTE	New Tanks	12.Access. Secure 13.Picre Submit Date; 14. As Bullt	2 034 2711	and ABOVE AND HAZ. ~ BY HE HONLES TO HAM	Land
	•	6/88			

Inspector;

Signature:

•	,			
		ŧ		
			•	
		,		
			•	
			,	
		•		

RCRA COMPLIANCE INSPECTION REPORT

U.S. ENVIRONMENTAL PROTECTION AGENCY, REGION 9

HAZARDOUS WASTE MANAGEMENT DIVISION

WASTE COMPLIANCE EVALUATION

Purpose:

RCRA Compliance Evaluation

Facility:

Owens-Brockway Glass Containers

3600 Alameda Ave. Oakland, CA 94601

EPA ID Number:

CAT000618918

Date of Inspection:

April 9, 1998

EPA Representative:

Clint Seiter

Environmental Protection Specialist

(415) 744-2141

City of Oakland

Hernan Gomez

Fire Services Agency

Hazardous Materials Inspector

Representative:

(510) 238-7253

Facility Representative:

Hank Wiegel

Plant Engineer (510) 436-2181

Report Prepared By:

Clint Seiter

Report Date:

June 16, 1998

BACKGROUND

Owens-Brockway Glass Containers, a unit of Owens-Illinois, is a glass manufacturing facility located at 3600 Alameda Avenue, Oakland, CA 94601. It has been in operation for approximately sixty years and employs approximately 500 people. 70% of the facility's product line consists of wine bottles, with the remainder being food and beverage bottles. The facility has three furnaces, each furnace devoted exclusively to a particular color of glass (green, amber and clear (or flint)). Most of the bottles manufactured come from recycled glass (cullet), which is ground down and remelted, with the remainder glass made on site from silica sand mixed with salt cake, soda ash, limestone, and colorizers or de-colorizers. Approximately 875 tons of glass containers are manufactured every working day. Each furnace has an approximate 450 ton holding capacity for molten glass. Furnaces attain a temperature of 2750 degrees to achieve proper melting of the raw materials.

The facility operates forty forklifts, three trucks, one bobcat and two payloaders, which are maintained on the site.

MANUFACTURING PROCESS

Raw materials are blended together in batches in the proper proportions for the desired quality of glass. The batches are transported via closed conveyor belts to the facility furnaces, where the batch material is melted down to molten glass. The molten glass is drawn from the bottom of the furnace, via the throat to feeders. Orifices in the feeders control the amount of molten glass let through, and shears cut off the bottoms of the gobs (discreet units of molten glass) to the desired length (the weight of the gob is determined to an accuracy of one hundreth place). The gobs are first formed into blanks, called "parisons", which are then transferred into molds (two at a time) in machines called shops (there is a total of eight shops in the facility). The molds in each shop can be configured to whatever specifications are required for the particular bottle. Bottles are formed when compressed air is blown into the molds containing the gobs. The bottles then go through an annealing process where they are reheated in lehrs to temperatures up to 1030 degrees and then gradually cooled down. After the bottles are sufficiently cooled, they are sprayed with a poly-coat mixture that increases the bottles' lubricity (scratch resistance).

The bottles are then checked by means of optical equipment for various potential defects (irregular wall thickness, blisters, cracks, specks, etc.) and defective bottles are removed from the assembly line (to be recycled as cullet). The bottles that pass inspections are eventually packaged and transported off to the customers.

WASTES GENERATED

The following wastes are generated at the facility

1. Used Oil: The hot glass is quenched by water as it is ejected out of the shop. This water picks

up lubricating oil from the shop machinery, and before the water is recycled, it is directed to a skim pond. Used oil is skimmed off the pond and diverted to an above-ground tank. Used oil is also generated through routine vehicular maintenance at the vehicle maintenance center.

- 2. Checker Dust: Dust contaminated with chromium and lead (from crushed cullet) accumulates on the bottom of the exhaust chambers that flank the furnaces. Approximately once every three years this dust is vaccuumed out and shipped off to be disposed of as D007 and D008 waste.
- 3. Methyl Ethyl Ketone (MEK): MEK used as a solvent for bottle coders eventually gets contaminated to the point where it has to be disposed of periodically as a D035 waste.
- 4. EP dust: Dust from the furnace exhaust is collected on electrostatic plates in the exhaust ducts. It generally is recycled into the batches used to make glass, but occasionally, due to recycling system breakdowns, it must be transported off-site for disposal as a D002 waste.

INVESTIGATION

On April 9, 1998, Clint Seiter, representing the Environmental Protection Agency (EPA), and Hernan Gomez, representing the City of Oakland Fire Services Agency, conducted an unannounced site investigation at the Owens-Brockway facility (EPA ID# CAT000618918), located at 3600 Alameda Ave., Oakland, CA 94601. Upon providing introductions and credentials, the inspectors contacted Mr. Hank Wiegel, the Plant Engineer of the facility. Also in attendance was Mr. Steve Springer, the facility general foreman. The inspectors explained that this was a routine inspection to determine whether or not the facility was in compliance with federal and state regulations concerning the proper management of RCRA and non-RCRA hazardous wastes. The inspection would consist of a walk-through of those areas of the facility where hazardous wastes were handled, with photos taken, followed by a record review.

Pre-Walk-Through Briefing

The facility representatives described the manufacturing process (as described above) to the inspectors. Per these representatives, enough waste is generated to qualify the facility as a Large Quantity Generator (LQG).

Walk-Through Inspection

- Raw Material Delivery

The walk-through inspection began where raw materials that make up the glass are received. Trucks delivering these materials deposit their loads through grates onto conveyor belts. The inspectors noted deposits of salt cake (anhydrous sodium sulfate) packed on the pavement surrounding the grate where this substance is off-loaded (photo 1). (The facility reps have since provided documentation that this has been cleaned up (see Attachment 2).) A post-inspection

review of the MSDS for salt cake has indicated that this substance is not a hazardous material (see Attachment 3). Cullet is kept in bins, segregated by color, until ready for use (photo #2). The conveyor belts, which transport the materials to the furnaces, are enclosed and vacuumed daily (the dust vacuumed up is re-entered into the manufacturing process).

- Used Oil Tanks #1 and #2

As mentioned above, water used to quench hot glass becomes contaminated with lubricating oil from the machinery (photo #3). The water from the quench water bins is routed to two skim sumps (photo #4), where the used oil is skimmed and pumped to two interior above-ground used oil tanks adjacent to the sumps. After the oil has been skimmed off the water in the sumps, the water is pumped to an exterior skim pond. These two used-oil tanks (Tank #1 and Tank #2) are located in the facility basement. Whereas Tank #1 (see photo #5) was correctly identified as containing non-RCRA hazardous waste, it was not marked with the words "Used Oil", as is required by Title 22 §66279.21 (this was subsequently corrected by the facility (see Attachment 2)). All other labeling requirements were in order. Similarly, while Tank #2 was also correctly identified as containing non-RCRA hazardous waste, it was not labeled with the words "Used Oil" (see photo #6). As with Tank #1, this has subsequently been corrected (see Attachment 2). Fire extinguishers were mounted close by and their tags indicated that they had been inspected within an acceptable time frame. Eye washes nearby were in working order.

Per Mr. Wiegel, the tanks have been in operation since the construction of the facility. The two tanks are located on a concrete floor which appears to be in good condition (i.e., showed no signs of cracks). The tanks are elevated approximately three inches above the concrete floor on one end (photos #7 and 8). The floor gradually slopes up until, in both instances, it touches the tank bottoms on the other end. There appears to be adequate containment of the tanks in the event of a leak. Should a leak occur, the oil could be directed to the skim sumps next to the tanks (photo #9).

- Satellite Accumulation Area, Machine Repair Shop

Used oil drum was not marked with the words "Used Oil" (see photos #10 and 11)(this has subsequently been corrected (see Attachment #2)). No other violations were noted.

- Satellite Accumulation Area, Selecting Maintenance Shop

Used oil drum was not marked with the words "Used Oil" (see photo #12) (this has subsequently been corrected (see Attachment #2)).

- Satellite Accumulation Area, Forklift Maintenance Shop

Used oil drum was not marked with the words "Used Oil" (see photos #13 and 14) (this has subsequently been corrected (see Attachment #2)).

- Exterior 4000 Gallon Above-Ground Used Oil Tank

As mentioned above, the water from the skim sumps in the basement is pumped to a skim pond after the used oil is pumped into one of two concrete above-ground tanks located in the basement. Residues of used oil can still be found in the water in the skim pond, and these residues are skimmed off the surface of the pond and pumped into an exterior 4000 gallon above-ground used oil tank. As with the other used oil containers, the tank was not marked with the words "Used Oil" (see photo #15)(this has subsequently been corrected (see Attachment #2)).

Document Review

There were no training records on file, as required by Title 22 §66265.16(d). No discrepancies were found in the manifest review. No other violations noted in facility documentation.

Post Inspection Briefing

The inspectors met with the facility representatives and emphasized the following concerns noted during the inspection:

- 1. Improper labeling of used oil tanks and containers (since corrected).
- 2. The salt cake spill in the unloading area (since corrected).
- 3. Incomplete training records.
- 4. Potential violations concerning the concrete used oil tanks in the basement.

POTENTIAL VIOLATIONS

Personnel Training

Title 22 §66262.34(a)(4)

A generator may accumulate hazardous waste on-site for 90 days or less without a permit provided that the generator complies with the requirements for owners or operators in Article 4 of chapter 15 and with section 66265.16.

Title 22 §66265.16(d)

The owner or operator shall maintain (training) documents and records at the facility.

There were no training documents at the facility conforming to the requirments of section 66265.16(d)(1)-(4).

Used Oil Labeling

Title 22 §66279.21(b)

Containers and aboveground tanks used to store used oil shall be marked or clearly labeled with the words "USED OIL".

The following facility used oil containers and tanks were not marked with the words "USED OIL" (this has since been corrected by the facility).

- Basement Tanks #1 and #2
- Drum in Machine Repair Shop
- Drum in Selecting Maintenance Shop
- Drum in Forklift Maintenance Shop
- Exterior 4000-gallon Used Oil Tank



Photo #1- Salt cake deposits on ground in material offloading area




Photo #2 - Cullet bin



Photo #3 - Hot glass quench water vat



Photo #4 - Oily wastewater skim pond



Photo #5 - Concrete used oil tank #1



Photo #6 - Concrete used oil tank #2



Photo #7 - Basement used oil tank, showing elevation above floor



Photo #8 - Basement used oil tank, close-up of elevation above floor



Photo #9 - Skim sump next to used oil tank



Photo #10 - Used oil drum (unmarked with the words "Used Oil") in satellite accumulation area in the Machine Repair Shop.



Photo #11 - Closeup of label of used oil drum in satellite accumulation area in the Machine Repair Shop.



Photo #12 - Used oil drum (unmarked with words "Used Oil") in Satellite Accumulation Area, Selecting Maintenance Shop



Photo #13 - Used oil drum (unmarked with words "Used Oil") in Satellite Accumulation Area, Forklift Maintenance Shop



Photo #14 - Closeup of label on used oil drum in Satellite Accumulation Area, Forklift Maintenance Shop



Photo #15 - Exterior 4000 Gallon Above-Ground Used Oil Tank, unmarked with the words "Used Oil".





Area were green round was found in Green liquid on basement floorwas gooling lower water with dye in it to find leak).




Cylinder Storage Basement Area Between A & B Furnace



D-Furnace Feet Hitle




Selecting Maintenance Satellite Storage Area




Oil Filter Container




Skim Pond Oil




Used Oil A-Sump Tank



Used Oil D-Sump Tank





Material Safety Data Sheet

anhydrous sodium sulfate

North American Chemical Company

13200 Main Street Trona, California 93562

To Avoid:

For more detailed information on the hazards of this product, write to the address above. Technical Information Bulletin is also available. For emergency information, telephone (619) 372-2291 any time.

PRODUCT IDE	NTIFICATI	ON	PHYSICAL AND CHEMICAL PROPERTIES				
Brand Name			State Granular solid Melting Point C 884 Boiling Point C Not applicable Color White Odor None Bulk Density, lb/cu. ft 80 to 90 Weight Per Gallon Not applicable Specific Gravity @ 20C Not applicable Water Solubility, % By Wt. @ 20C 16.3 Flash Point And Method Not applicable pH Not applicable				
			US INGREDIENTS	······································			
Chemical I	Name	Common Name	CAS Number	Hazard			
Sodium sulfate		Sait cake	7757-82-6	Mild irritant to eyes, nose, and skin and a strong cathartic.			
		PHYSICAL HA	ZARD INFORMATION	ON			
	lo lo	Upper Explosive Limit:	Not applicable	Lower Explosive Limit: Not applicable			
Flammable: N	lo	Flammability Class:	Not applicable				
Combustible: N	lo	Organic Peroxide:	No				
Oxidizer: N	lo	Compressed Gas:	No .				
Reactivity:	Stable a	t ordinary and expected ter	nperatures and pres	sures.			
Incompatibilitie	es: Aluminu	um powder and molten sodi	um sulfate has explo	oded.			
Hazardous Decomposition		sodium sulfate decomposes	s, evolving toxic sulf	ur oxides.			
Conditions	Temper	atures at or above the melti	ng point,				

HEAL	TH	INE	TAN	ON
		1136	-	-

recautionary Information:	CAUTION! May cause irritation. May be harmful if swallowed.							
Symptoms Of Exposure:	Burning sensation in the eyes or nose, coughing or sneezing or rash on the skin.							
Restrictive Medical Conditions:	Skin disorders may be aggravated by the dehydrating action of this product. Gastrointestinal and kidney disorders may be aggravated by the cathartic action of this product.							
	PRIMARY ROUTE(S) OF ENTRY							
inhaiation (breathing), eye	and skin contact and ingestion (swallowing).							
	TOXICITY INFORMATION							
This product is of low toxicity to humans; no lethal doses for humans were reported in the literature; Oral-mouse D ₅₀ 5989 mg/kg; lvn-mouse LDLo 1220 mg/kg.								
	EXPOSURE LIMITS							
OSHA: Not established. ACGIH: Not established. Other: ACGIH nuisance	dust TLV-TWA is 10 mg/m ³ total dust or 5 mg/m ³ respirable dust.							

2 of 4

B-5023

Reported As A Pote	ntial Carcinogen	Not Applicable	□ National Toxicology Program
Or Carcinogen		OSHA	☐ International Agency For Research On Cance
	PRECAU	TIONS FOR SAFE HAN	NDLING AND USE
Avoid breathing dus Avoid contact with a Use only with adequ Wash thoroughly aff	eyes and skin. late ventilation.		
	s	SPILL AND LEAK PRO	
Soil Release:		ip into a container and rec ordance with federal, state	claim for salvage value or dispose of at an industrial e and local regulations.
Water Spill:	Disperse and dilute	with water jets, propellers	s or other similar devices.
Air Spill:	Let dust settle and d	dispose of as in Soil Relea	se above.
Occupational Spill:	Shovel and sweep using be washed to a		m for salvage value, or as permitted, small amounts
RCRA Waste Number:	Not applicable.		
E	NGINEERING CON	TROLS AND PERSON	AL PROTECTIVE EQUIPMENT
Ventilation:	Use general dilution	n ventilation techniques.	
Respirator:	Use NIOSH/MSHA exposure limit.	approved dust and mis-	t respirator for exposure above the nuisance dust
Eye Protection:	Safety glasses or ve	ented safety goggles.	
Gloves:	No special requirem	nents. Ordinary work glov	es.
Clothing:	No special requirem	ents. Wear easily washahl	e clothing. Change daily. Wash clothing before reuse.

Mr. John Verber, esq. May 28, 1998 Page 2

If you have any questions or need clarifications on any of the items listed above, please contact Mr. David Bacharowski at (213) 266-7546, or Mr. Rick Vergets at (213) 266-7556. You may also contact USEPA's project managers, Mr. Steve Linder at (415) 744-2036 or Mr. Sean Condry at (415) 744-2112 regarding technical issues. Please contact Mr. Jorge Leon at (916) 657-2428 or Ms. Laurie Williams at (415) 744-1387 with respect to any legal issues. We look forward to working with you.

Sincerely,

DAVID A. BACHAROWSKI Environmental Program Manager Regional Water Quality Control Board Los Angeles Region

SEAN T. CONDRY Project Manager Waste Management Division U.S. EPA Region 9

cc:

Jorge Leon, Office of Chief Counsel, SWRCB

David Spath, Division of Drinking Water and Environmental Management, State Department of Health Services

Gary Yamamoto, Drinking Water Field Operations, State Dept. of Health Services

Steve Linder, United States Environmental Protection Agency

Laurie Williams. United States Environmental Protection Agency

Carl Sjoberg, Environmental Programs Division, Los Angeles County Department of Public Works

Capt. Dennis Wilcox, Underground Storage Tank Program, City of Los Angeles Fire

Keith Pritsker, City Attorney's Office, City of Los Angeles

Walter Crone, Ninyo & Moore

Michael Schwennesen, Ecology and Environment, Inc.

Craig Perkins, Environmental & Public Works, City of Santa Monica

Joseph Lawrence, Assistant City Attorney, City of Santa Monica

Rey Rodriguez, Utilities Engineer, City of Santa Monica

Brian Johnson, Underground Storage Tank Program, City of Santa Monica

Barry Groveman, Special Environmental Counsel for City of Santa Monica

Denise Kruger, Southern California Water Company

Rob Saperstein, Counsel for Southern California Water Company


Toby Moore, Mission Geoscience

Angelo Bellomo, Environmental Strategies Corporation

Gino Bianchi-Mosquera, Geomatrix Consultants, Incorporated

Brad Boschetto, Shell Oil Company

Adam Leiter, Wayne Perry, Inc.





BOB BARBER -> CONTACT NAME

Facsimile Transmission Face Sheet



City of Oakland

FIRE DEPARTMENT OFFICE OF EMERGENCY SERVICES



- -:ROM	Leng Griffin		510 - PHONE: 238-3938
- _:ЭТ Е S	page 5 1-3	juspecto neport	ts Hazandaus Wask.
	page 4-10	B 0	Нивр
· · · · · <u>·</u>			
		4.4.4	

CITY OF OAKLAND
FIRE DEPARTMENT
OFFICE OF EMERGENCY SERVICES DIVISION
505 14th Street, 7th Floor
Oakland, CA 94612

PHONE (510) 238-3938 FAX (510) 238-7761

HAZARDOUS WASTE GENERATOR INSPECTION REPORT

FACILITY NAME:	05 lea -	_				EPA I.D.#:	00061	80	178	
ADDRESS: 3600 Alum	1 0	ð					DATE:			
3600 Alum	edo H	אר	<u>.</u>				11-4	_		
		CO	MPLIA	NCE			CODE	CC	MPLIA	INCE
•	CODE	YES	NO	N/A			SECTION	YE	NO	N/A
1. IDENTIFICATION NUMBER				_	6. CONTINENCY/BUSIN	ESS PLAN			-	
(a) Obtained EPA I.D. Number	66262.12(a)	×	T		(a) Contingency Plan Compl	icte	66265.52(a-f)	1	T	
(b) Transporter and TSDF Have EPA [.D.#	66265.12(c)	メ			(b) Copy of Plan on Site		66265.53	П		\Box
2. PRE-TRANSPORT REQUIREMENTS					(c) Contingency/Business Pla	n Submitted	66265.53(b)	П		
(a) HW Containers Labeled	66262.31	1	T		(d) Plan Amended as Necess	ery .	66265.54	П	7	
(b) HW Label Property Filled Out	66262.32(14)	1			(e) ER Coordinator Familiar	w/Pian	66265.55	П		
(c) HW Accumulation of Time Not Exceeded	66262.34 (c)	\sqcap			7. PREPAREDNESS AND	PREVENTION				
(d) Accumulation Date Indicated	66262.34(f)	\Box			(a) Internal Commun./Alam	Provided	66265.32(a)			
(c) Description of HW Contents	66262.34(I)	\sqcap			(b) A Device to Call Outside	: Provided	66265.32(b)	П		
(f) HW Containers in Good Condition	66265.171	\Box		1	(c) Spill Control Systems A	vailable	66265.32(c)	П		
(g) HW Compatible with Containers	66265,172	\sqcap		T	(d) Maintain ER Equipment		66265.33	П		
(h) HW Containers Closed/Sealed	66265.173				(c) Security Measure		66265.14	П		
(I) HW Storage Area Inspected Weekly	66265.174	П			(f) Maintain Adequate Aisle	: Space	66265.35	П		
(j) Tank & Tank Equip. Inspected Daily	66265.195	П			(g) Arrangements w/Local A	Agencies	66235.37	П		
(k) Incompatible HW in Separate Containers	66265.199	7			8. EMERGENCY PROCE	DURES				
;i) Proper Management of Used Oil Filters	66266.130		1	1×	(a) Character/Source/Extent	of ER Determined	66265.56			X
3. RECORDKEEPING AND REPORTING					(b) Proper Agencies Notified	of Health Hazard	66265.56	1		×
(a) HW Analysis Kept S Yrs./Land Disposal	66262.11		T	1	(c) ER Data Submitted to D1	TSC & LIA	66265.56			×
(b) Biennial Report Submitted to State	66262.41			11	(d) Uncontrol. Release HW	Property Handled	66235.56			7
4. MANIFEST/RECEIPTS					9. WASTE STREAMS					
(a) HW Shipped with Proper Manifest	66262.20	l			(a) Waste Oil			D	II.	
(b) Manifests Kept for Last 3 Years	66262.40(a)	П			(b) Non-Halogenated Solve	nts/Parts Cleaner		>	<	
(c) HW Analysis Kept for 3 Years	66262.40(c)			X	(c) Ethylene Glycol/Antifree	sze .				
(d) Manifests Received from TSDF	66262.42	1	T_{-}	•	(d) Oily Sludges					
5. TRAINING					(e) Other:					
(a) Training Program Provided	66265.16	П			(f) Other:					
(b) Personnel Trained & Supervised	66265.16(b)	П			(g) Other:			T		T
(c) HW Personnel Trained within 6 Months	66265.16(b)	\prod			(h) Other:					
(d) Training Records Kept on Site	66265.16(d)							and the		
(c) Training Records Maintained for 3 Years	66265,16(e)	\prod							T :41	
(1) Training Records Complete	66265.16(1,2)				All above code section	ons refer to the Ca	litornia Code (OI K	9g. 110	B 22
Source Reduction Plan Completed	25244.19		1	X	Pollution Prevention		Health & Safety Code			
REMARKS:										
								_		

	1		1	
Page	.!	of	Į	

white -env.health yellow -facility pink -files

ALAMEDA COUNTY, BÉPARTMENT OF ENVIRONMENTAL HEALTH

Hazardous Materials Inspection Form

80 Swan Way, #200 Oakland, CA 94621 (415) 271-4320

11,111

_			ID # Name DWENS BRICK WAY Date	4/11/27
	BUSINESS PLANS (Title 19)			
		2703 25503(b) 25503.7	Site Address 3606 MAMEDA	
	4. Inventory information 5. Inventory Complete 6. Emergency Response	25804(a) 2730 25504(b)	City Ohl Zip 9460 Phone 43	36-2057
	7. Training 5. Deficiency 9. Modification	25504(c) 25505(a) 25505(b)	MAX AMT stored > 500 lbs. 55 gal 200 cft.?	
8	ACUTELY HAZ MATLS		Inspection Catedories: 1. Haz. Mat/Waste GENERATOR/TRANSPORTER 1. Business Plans, Acute Hazardous Materials	
	10, Registration Form Filed 11. Form Complete 12. RMPP Contents 13. Implement Sch. Regist? (Y/N)	25523(a) 25533(b) 25534(c)	III. Underground Tanks	
	14. OffSile Coreeq, Assess. 15. Probable Pisk Assessment 16. Persons Responsible	25524(c) 25534(d) 25534(g)	* Calif. Administration Code (CAC) or the Health & Safety Code (F	S&C)
	17. Certification 18. Exemption Request? (Y/N) 19. Trade Secret Requested?	25534(1) 25536(b) 25838	Comments:	
u.	UNDERGROUND TANKS (Title	23)	- plusion proper monitorint Bo	~ hor
Ceneral Ceneral	1. Permit Application 2. Pipeline Leak Detection 3. Records Maintenance 4. Release Report	25284 (H&S) 25292 (H&S) 2712 2651	ME V.S.T. AS DICCULED	
_	5. Closure Plans 6. Method	2679	8	
	Monthly Yest Dolly Vactors Stimicanuscal graphicater One time sols		- somplete AND SENDIN PART	<u></u>
5	Dotly Vazione Ores firms sols Annual fank feet		HORD AS DISCUSED.	
<u> </u>	4) Morifity Gradwater One time sale 5) Dolly inventory			
	Annual tank hading Contiples lack dat Voctore/gnowater mon. 6) Dolly inventory		- LABEL EGILIN LARRE BAR. L	VAS PE
	Arrust funk heltig Cont pipe leck det 7) Weeldy Tork Gouse		(O deal p.4)	
Ē	Arvicel forth fetting 8) Arvicel forth Testing Colly Inventory		Conspirers	
	9) Other	2643	- SEND IN AIR, C, FIRM PULL	(/ ·
	Date:	2644 2646	- Comply within BODAICI	
2	1).Morritor Pion 12.Access. Secure	2647 2632	COAGY WITH A SOUNTS!	
¥	13.Plans Submit Date: 14. As Buft	2634 2711		
_	Date:	2035		
•				
	Contact: _		~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	A, M
	Title:		Inspector:	

Signature:

for Barla

white -env.health yellow -facility pink -files

Title:

Signature:

ALAMEDA COUNTY, DEPARTMENT OF ENVIRONMENTAL HEALTH

Hazardous Materials Inspection Form

AMIR K- G-Holami 80 Swan Way, #200 Oakland, CA 94621

Oakland, CA 94621 (415) 271-4320 (510)

11,111

_		***	site of ste
	BUSINESS PLANS (Title 19) 1. Immediate Reporting 2. Bus. Plan Sids. 3. RR Cars > 30 days 4. Inventory Information 5. Inventory Information 6. Emergency Response 7. Training 8. Deficiency 9. Modification ACUTELY HAZ. MATLS 10. Registration Form filed 11. Form Complete 12. BMPP Contents 13. Implement Sch. Regiat? (Y/N) 14. Onsite Conseq. Assess. 15. Probable Risk Assessment 16. Persons Responsible 17. Certification 18. Exemption Request? (Y/N) 19. Inade Secret Requested?	2703 25503(b) 25803.7 25504(c) 2750 25504(c) 25504(c) 25505(c) 25505(c) 25503(c) 25503(c) 25533(c) 25533(c) 25533(c)	Site Address 3600 MAM FOR AVR City OMUND Zip 9460 Phone 73 6-2058 MAX AMT stored > 500 lbs. 55 gal 200 cft.? Inspection Categories: Haz. Mat/Waste GENERATOR/TRANSPORTER III. Business Plans, Acute Hazardous Materials Till. Underground Tanks Calif. Administration Code (CAC) or the Health & Safety Code (HS&C) Comments: Survivo AD 1986
IJ.	UNDERGROUND TANKS (Title	e 23)	This facility that only 2 vist and 18
General		25284 (H&S) 25292 (H&S) 2712 2681 2670	BOTH ARE DOUBLE WINED FIBELLIAGE WITH
Monitoring for Existing Tranks	6. Meithod 1) Morithy Test 2) Daily Vadase Sent-crinual grawater Che little sale 3) Daily Vadase Che little sale Annual tank lest 4) Morithy Grawater Che little sale Annual tank lest 5) Daily Inventory Annual tank testing Cart pipe leck dat Vadase/grawater mon. 6) Daily Inventory Annual tank testing Cont pipe leck dat 7) Weekly Tank Galupe Annual tank testing Daily Inventory 9) Other		- typica maste (HAZ - MSTE) GENERATED ARE: - Luguication of ail was the - Luguication of ail was the - Luguication of the maste (Penery master)
_	7. Precis fank Test Date:	2644 2646 2647	-BATHWOSIE -
New Tanke	11.Monitor Plan 12.Access, Secure 13.Plans Submit Date: 14. As Bull Date:	2632 2634 2711 2635	and ABOVE apr 12.
Rev	Centact:	13 0	HIMMP PHUB WAS DISCUSSED WILL SEMPINIANTE

Inspector:

Signature:

OAKLAND FIRE SERVICES AGENCY/OFFICE OF EMERGENCY SERVICES HAZARDOUS MATERIALS UNIT

505 - 14th Street, Oakland, CA 94612 (510) 238-3938

HAZARDOUS MATERIALS INSPECTION REPORT

Site Number	Faculty Name	Facility Address	Zip Code					
G8	Owens - Brockway		01					
	inspect	ion Report						
Porm	Permission to mercat granted - Jounny inep. P1 Cooling tower H-O treatment room Signagin CORR righ							
G	oling Tower H-O	treatment room						
the state of the s	Signa	in CORR. righ						
	,							
2	UST for desel of	gas, are going to	a .					
remove	I in 98 - Replace]	hem w/ AGT						
Nu	mber of personnel h	andling H.M. need to	ke					
undates	1-	andling H.M. need to	A					
1								
E	neighborg Aspense is	under review - A copy	will					
be sent	to me	under review - A copy						
HC	MSF dready submit	led						
No	MBP already submit	is Time						
		·						

Facility Contact/ Print Name:	Inspected By:	☐ Insp. Griffin	238-7759
Steve Springer		☐ Insp. Johnson	238-3804
Facility Contact Signature:	HEG	☐ Insp. Craford	238-7758
		🗷 Insp. Gomez	238-7253
Steve Springer	Date:	11-4-97	·

OAKLAND FIRE SERVICES AGENCY/OFFICE OF EMERGENCY SERVICES HAZARDOUS MATERIALS UNIT

505 - 14th Street, Oakland, CA 94612 (510) 238-3938 Hazardous Materials Inspection Report

	Owens	Brockway	out do linear to our			
		UNAUTHORIZED OPERATION	V	C	N	OBSERVATIONS
400	Hazardous	Materials Release Response Plans and Inver	tory (I	IMRR	P/Busi	ness Plan)
401	25507	Failure to report a release/threatened release.			×	
402	25504	Emergency Response Plan inadequate		X		
403	25509	Emergency contacts not provided/current		X		
404	25504	Personnel training program is inadequate		メ		
405	25504	Hazardous Materials Chemical Inventory is not attached, is not accurate, or is incomplete		X		
406	25509	Site map is not attached or is not sufficient		X		
408	255339(a)	Acutely Hazardous Materials Registration not filed		×		about update it
408	·	Material Safety Data Sheets are not located where the Business Emergency plan (BEP) indicates they should be		×		
409		The BEP indicates the facility maintains hazardous materials response equipment, and the equipment listed is not in place and in operable condition		X		
410		Hazardous materials are not located in the designated areas as indicated on the site map		X		
411		Containers are not clearly labeled with the chemical name and hazard class		入		
412		Containers are in poor condition or are leaking		X	A Company of the Comp	
413		Secondary containment is inadequate		X		
414		Emergency procedures are not adequately posted		X		
415		Monitoring records are not complete or are not current		X		

V=Violation C=Compliance N=Not applicable/addressed/Unknown

OAKLAND FIRE DEPARTMENT/OFFICE OF EMERGENCY SERVICES Hazardous Materials Management Program 475-14th Street, 9th Floor, Oakland, CA 94612, (510) 238-3938

HAZARDOUS MATERIALS INSPECTION REPORT

STID#:	FACILITY N	AME:				PG.	OF,
		OMEN	S-BRO	CKWAY			
ADDRESS: 3	600 Alan	neda F	1ve	(10)			
,							
D Games	550		-	Ecured	٠ - د	cognet a	
all	times		<u> </u>		-		
2.1	71112						
2) chech	GI	• 2.	dia.	maril			
J 0.000	<u> </u>		373	annually			
3) 11.	<u>د</u>		ONAT. AL	8	/ NF	5A	
y para	4 41		()	ays w,		1/	
		78-7	10)				
4) Label	A. 140.40	1000	Stor		losh		
1	il An	VHYDR	8(15	Amnon	TAU		
		VI) I DIS		7 17 0-00.0			
		•					
		M*************************************					
					,		
HMBP-	2 1	A	Ín.	30	1		
1111	7	7			Mys		
-MSDS	40-00-00						
FACILITY C	<u>434.105</u> ONTACTS/	3	i in the second	INSPECTED I	RV.		
SIGNATURE		- Ban	ノ	CRAF			
PRINT NAMI	E: Bob	BARB	en	DATE: 7-31			
			Annual Property of the Control of th				